

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 25 Jan 2023

Preliminary Advice

Vehicle No	: GBK606X	Accident Date	: 14/01/2023
Make	: TOYOTA HIACE	Policy No.	: SP2004006721
Assignment Date	: 18/01/2023	Excess	: S\$1,500.00
Date of Inspection	: 19/01/2023	Est. Duration of Repair	: 7
Inspection At	: FULCO AUTOCARE PTE LTD (HQ) 176 SIN MING DRIVE #03-02 SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,979.40
Revised Amount	:S\$	8,127.20
Check Items (Estimated)	:S\$	7,808.50
Total	:S\$	15,935.70

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	16,864.00
Salvage Value	:S\$	
Margin for Repair	:S\$	53,136.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The vehicle repair on Lump Sum basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.