

Fulco Autocare Pte Ltd

176 Sin Ming Drive #03-02 Sin Ming Autocare Singapore 575721

Tel: (65) 6552 0302 Fax: (65) 6552 0780 Email: fulco0302@gmail.com

Make/Model: TOYOTA HIACE

Date: 17/01/2023


Engine/Chassis No.:

Claim Type: OD

Date of accident:

VRN: GBK606X

Damaged area: Front



Supplementary List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Intercooler <i>Per</i>	1	\$ 1,558.20	\$ 1,558.20
2	Radiator fan assy <i>1281.10 CM</i>	1	\$ 2,078.90	\$ 2,078.90
3	Coolant expansion tank <i>DU</i>	1	\$ 259.90	\$ 259.90
4	Chassis frame bracket upper <i>@ 212.00 R₁</i>	2	\$ 345.50	\$ 691.00
5	Chassis frame bracket lower <i>@ 144.60 R₁</i>	2	\$ 422.80	\$ 845.60
6	Dashboard inner member <i>R</i>	1	\$ 659.80	\$ 659.80
Subtotal				\$ 6,093.40
List discount				25.00%
Total				\$ 4,570.05

✓
✓
✓
✓
✓
X

Supplementary Estimate Grand Total	\$ 4,570.05
---	--------------------