



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER:

ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCG22005300	Date of Loss:	13/01/2023
Vehicle Reg. No.:	XE2928A	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CA TRANSPORTATION & WAREHOUSING PTE LTD		
Make/Model:	UD TRUCKS GKB85ELDHNT, 10.8 D (M)	Vehicle Reg. Date:	08/05/2017
Vehicle Colour:	WHITE	Chassis No:	JNCM1F1AXHU019629
Engine No:	GH11742602		
Odometer:	312092 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	14,188.90
Miscellaneous Items	220.00
Labour	2,840.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	17,248.90
+ GST 8.00% (S\$)	1,379.91
Nett Amount (S\$)	18,628.81

This claim is handled by: BRIAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 18 Jan 2023)**Parts:** N/A UD TRUCKS GKB85ELDHNT 10.8 D (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for XE2928A)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*GRILLE ASSY TOP <i>repair</i>	0.00	0.00	*485.00 F
2	1		*GRILLE ASSY LOWER <i>cm</i>	0.00	0.00	*450.00 F
3	1		*FRONT BUMPER STEP CENTER <i>cm</i>	0.00	0.00	*25.00 F
4	1		*FRONT BUMPER STEP LH <i>cm</i>	0.00	0.00	*51.00 F
5	1		*CORNER PANEL LOWER COVER LH <i>cm</i>	0.00	0.00	*20.00 F
6	1		*FRONT BUMPER BASE <i>bt</i>	0.00	0.00	*950.00 F
7	1		*FRONT BUMPER CENTER <i>bt</i>	0.00	0.00	*500.00 F
8	1		*FRONT BUMPER CORNER <i>bt</i>	0.00	0.00	*450.00 F
9	1		*FRONT BUMPER CORNER, END PIECES <i>cm</i>	0.00	0.00	*65.00 F
10	1		*FRONT BUMPER GRILLE, CTR <i>ml</i>	0.00	0.00	*137.50 F
11	1		*FRONT BUMPER GRILLE LH <i>ml</i>	0.00	0.00	*65.00 F
12	1		*SIDE STEP <i>cm</i>	0.00	0.00	*120.00 F
13	1		*SIDE STEP REFLECTOR <i>ml</i>	0.00	0.00	*15.00 F
14	1		*SIDE STEP BACK COVER <i>cm</i>	0.00	0.00	*85.00 F
15	1		*SIDE STEP BRKT <i>bt-lpl</i>	0.00	0.00	*500.00 F <i>280</i>
16	1		*HEADLAMP ?	0.00	0.00	*600.00 F
17	1		*FRONT LAMP <i>cm</i>	0.00	0.00	*85.00 F
18	1		*FOG LAMP <i>cm</i>	0.00	0.00	*90.00 F
19	1		*UNDERNEATH COVER, FRONT <i>cm</i>	0.00	0.00	*258.00 F
20	1		*FAN SHROUD	0.00	0.00	*300.00 F
21	1		*AIR COOLER <i>bt</i>	0.00	0.00	*2,089.00 F
22	1		*COOLANT HOSE, TOP	0.00	0.00	*95.00 F
23	1		*RADIATOR <i>bt</i>	0.00	0.00	*1,400.00 F
24	1		*NET RADIATOR <i>repair</i>	0.00	0.00	*850.00 F
25	1		*FAN ASSY <i>cm</i>	0.00	0.00	*1,700.00 F
26	1		*RADIATOR SUPPORT BRKT <i>bt</i>	0.00	0.00	*45.00 F
27	1		*FAN SHROUD SUPPORT ?	0.00	0.00	*350.00 F
28	1		*FAN SHROUD, INNER ?	0.00	0.00	*1,058.50 F

F=Franchise part.

11 264

Sub Total (\$\$)	12,899.00
+ Margin on L,N Items 10.00% (\$\$)	1,289.90
Total Parts (\$\$)	14,188.90

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	3	COOLANT <i>new</i>	180.00
2	1	FRONT NUMBER PLATE <i>51</i>	40.00
Sub Total (S\$)			220.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK FRONT BUMPER BRACKET & REPLACE ACCIDENT DAMAGED PARTS RELATED TO ACCIDENT	New	<i>500</i> 600.00
2	TO SPRAY PAINT ON FRONT GRILLE, BUMPER CENTER, BUMPER CORNER, SIDE STEP BACK COVER	New	<i>1000</i> 1700.00
3	TO CRANE OUT THE RADIATOR ASSY, TURBO INTERCOOLER <i>photo</i>	New	<i>300</i> 500.00
4	TO ADJUST FOCUS HEADLAMP AND CHECK ALL LIGHTING FUNCTIONING	New	40.00
Gross Labour Cost (S\$)			2,840.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Parts: 12390.40

S/N: 220

L: 1840

Total: 14450.40

Ys: 11550 #

Repair

#p 90010068

5 days

4/5

19/01/23 @ 1540

EXCESS: 1500

Repair

Repay after repair