



Section A - Accident Details

Registration Number	SHB5384D
Case Reference Number	TAX/01/23/2040
Registration Date	13/May/2016
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	LEE KIM HUA
Type of Accident	Head to Rear
Accident Date and Time	18/Jan/2023 7:25 AM
Accident Reported Date and Time	18/Jan/2023 11:00 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24117467
Special Instruction to ARC,if any	TP/REAR LEFT PORTION
Prepared Date and Time	18/Jan/2023 1:12 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$1,296.00	\$200.00
Total Spare Part Cost	\$3,658.94	\$1,191.48
Total Other Cost	\$500.00	(\$291.48)
TOTAL COST	\$6,130.94	\$1,300.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Boon Chew Tay	Taufikh (LKK) / INCOME
ARC / Surveyor Sign Off Date	18/01/2023 3:25 PM	18/01/2023 3:13 PM
Signature		
Remarks	LUMPSUM REPAIR / AFTER REPAIR PHOTOS, FOR CHECK ITEM and REPLACE ITEM. PLEASE CALL SURVEYOR TAUFIKH , HP 9749 5749/ EMAIL: taufikh@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2302-0142	Invoice Number	
Quotation Date	15.02.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION LH	\$676.00	\$200.00
Total Labour	\$676.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FUEL LID COVER	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$1,296.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$351.48)
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$500.00	(\$291.48)

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$478.90	25.00	\$359.18	Replace	Replace
		90467-07211	BUMPER CLIPS (10 PCS)	10.00	\$2.40	25.00	\$18.00	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$234.70	25.00	\$176.03	Replace	Replace
		52015-47050	ARM SUB-ASSY. RR BUMPER RH	0.00	\$157.90	0.00	\$0.00	Replace	Not Given
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$157.90	0.00	\$0.00	Replace	Check
		89997-30070	ANTENNA,ELECTRICAL LOWER REAR	0.00	\$208.10	0.00	\$0.00	Replace	Not Given
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check
		52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$108.70	25.00	\$81.53	Replace	Replace
		52592-47021	BUMPER SEAL, RR LH	0.00	\$101.80	0.00	\$0.00	Replace	Not Given
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$93.90	0.00	\$0.00	Replace	Not Given

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 26/02/2023

User ID : PohSuan

		76891-47020	BUMPER LIP REAR	0.00	\$301.90	0.00	\$0.00	Replace	Not Given	X
		58307-47060	END PANEL	0.00	\$755.10	0.00	\$0.00	Replace	Check	X
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
		61602-47091	FENDER RR/LH	0.00	\$980.80	0.00	\$0.00	Replace	Not Given	X
			STRIDES LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
			STICKER DECAL 65558888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
		52563-47010	TAIL LAMP BRACKET, LH	0.00	\$35.20	0.00	\$0.00	Replace	Check	X
		81561-47170	TAIL LAMP LH	1.00	\$618.60	10.00	\$556.74	Replace	Replace	√
		77350-47030	LID ASSY, FUEL	0.00	\$116.80	0.00	\$0.00	Replace	Not Given	X
			STICKER PETROL ONLY	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
Total					\$4,606.90		\$1,191.48			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	1,191.48	
+	200.00	L/S \$1,300/-
+	260.00	
	<u>1,651.48</u>	
	-20%	
	<u>1,321.18</u>	