

KV

Trust Autoworks

Mailing address Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/p 91082728

Li Zhenyao
Blk 273A Bishan St 24
#22-102
Singapore 571273

Vehicle No : SNC 5640 M
Make/Model : Skoda Octavia
Year : 2021

Not Withain
1/1 Day @ 2400/-
Paying After Repair
3 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear boot lid	Repair	
1 pc	Rear boot lid emblem " SKODA "	new	
1 pc	Rear boot lid emblem " OCTAVIA "	new	
1 pc	Rear boot lid batch	new	
1 pc	Rear bumper		
1 pc	Rear bumper reinforcement	?	
1 pc	Rear bumper inner top beam	?	
1 pc	Rear n/s bumper side retainer	?	
1 pc	Rear n/s bumper reflector	59.81	
1 pc	Rear bumper lower garnish		
2 pcs	Rear bumper reverse sensor		

R	\$950.00	X
na	\$55.00	
na	\$75.00	
na	\$25.00	
halant	\$1,050.00	
R	\$480.00	X
CM	\$185.00	
na	\$115.00	X
CM	\$195.00	
na	\$355.00	X
Short	\$275.00	
	\$550.00	LP
	\$4,035.00	
Less 10 %	\$403.50	
	\$3,631.50	

S Nett

1 pc	Rear bumper lower skirt	?	photo
------	-------------------------	---	-------

CM \$600.00 ✓

Labour Charges

Remove/renew the above accident parts including knocking, welding etc.

\$700.00 400/-

To putty and spray paint

\$700.00 400/-

Check & reconnect wiring.

\$30.00 15/-

To respray anti-rust proofing treatment

na \$100.00 X

Remove/renew rear bumper sensor and to reset to factory specification

\$180.00 60/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To survey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Total

\$5,941.50

Authorised by Repairer

Signature

Date