



Boxfresh Pte Ltd

7030 Ang Mo Kio Ave 5 #06-49

Northstar @AMK Singapore 569880

Tel : 64585441 Fax : 64553470

Vehicle No : SG1840Z

Accident date : 31/12/2022

Model No : MAN

Registered owner : Go Ahead Singapore Pte Ltd

A22

Date of Estimate : 27/01/23

My Ref : BF-IC-1114

Total Charge

Parts Replaced

1) OS REARVIEW MIRROR (A22) P/N: MSVE-R692243135	S\$ 1308 ✓ BR	1308
2) Remove and installation of mirror (Labour)	S\$ 100 50	-10%
		1177.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total charges S\$1409

GST 8% S\$112.72

Total Bill S\$ 1521.72

P/P - 1227.20

1 day

BOXFRESH PTE LTD

WORKSHOP: 154 GUL CIRCLE SINGAPORE 629611

OFFICE: 7030 ANG MO KIO AVE 5 #06-49 NORTHSTAR SINGAPORE 569880

T: +65 64585441 • F: +65 64553470 • E: business@boxfresh.com.sg • W: www.boxfresh.com.sg