

Vehicle Registration No: SMG 2681 E

Our Ref No: ATECM/10/0001/JM

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

Under normal circumstances, the repair period would be about 7 (Seven) working days.

Qty	Description	Condition	Repairer's Estimate	Revised Amount
-----	-------------	-----------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Rear bumper assy <i>X Repair</i>	Repair	\$ 650.00	\$ - <i>X</i>
1	Rear sliding door RH <i>X Repair</i>	Warped	\$ 1,350.00	\$ 1,350.00 <i>XR</i>
1	Rear fender assy RH	Warped	\$ 1,200.00	\$ 1,200.00 <i>981</i>
1	Rear fender liner RH <i>X^{^^}</i>	Cracked	\$ 250.00	\$ 250.00 <i>X</i>
1	Rear wheel hub bearing RH	Bent	\$ 320.00	\$ 320.00 <i>280-</i>
1	Rear wheel shock absorber RH	Bent	\$ 380.00	\$ 380.00 <i>238</i>
Total			\$ 4,150.00	\$ 3,500.00
Less 20%			\$ 830.00	\$ 700.00
			\$ 3,320.00	\$ 2,800.00

1499
20%
1199.20

SPECIAL NETT ITEMS

1	Rear bumper clip (1 set) <i>X^{^^}</i>	Necessary	\$ 100.00	\$ 100.00 <i>X</i>
1	Rear wheel tyre RH <i>X^{sv}</i>	Torn	\$ 180.00	\$ 180.00 <i>X</i>
1	Rear wheel sports rim RH	Cut	\$ 550.00	\$ 550.00 <i>300</i>
1	Rear fender sealant	Necessary	\$ 100.00	\$ 100.00 <i>40</i>
			\$ 930.00	\$ 930.00
Total parts			\$ 4,250.00	\$ 3,730.00

340

