ASS. REC. BY: REF: A16-1	
Kenneth	SSIGNMENT
Pale:	
Estimated Cost:	Veh No: SIFD 378U Yr Regn: 51 6 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi? Prime Mover /
OD VP WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
10 Inspect Vehicle No:	Make: Renault Controle c.c 1985
at Workshop m/s Trans Cab	Colour M.P. White / Per AC: Insured / Std / NI / NA
Insured:	Sp.Reading 6775 T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No:
Claims No.	C/No: VFIABLISAUC 282309
Comple	Gen. Cond: Good'/ Fair / Poor / Burnt
(Cfient's Record)	Steering: Inorger Jammed / Leaked / Burnt or
Make of Ven:	Brake: Inorder / Jammed / Leaked / Burnt or
	Modi: MI S/Rim / STD A/Rim or
(Policy Condition)	Tyre Size: F: 215/60R16
Remark: The veh had commenced its N/S O/S	R:
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or FIR / 2 P
Bal. or Market Value:	F
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. Rear
GIA / PR Seen: Consistent?: Yes or No	mm Noa: 6 mm
Est. Repairs: 04 days Res.: Yes or No	The Date of the Inch
Lum Sum: 20 % 3 Val.: Yes or No	D.O.A. 70/1/23 D.O.I. 12/1/2023 Survey held at
CA / REV / REP. / 24 HRS	
Vahio IN COLT	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date:Person Contacted:	The U/C / Chasals frame / Body Structure affected due to collision.
Date / Time Action / Instruction	Tallie / Body Structure affected due to collision.
2)	
RC.	
10.	
Cate/Time, File Pass to? Prell. Report Day	to Of Paris
1)	ys Of Repair:
Duta/Time, File Return to?	Survey No. of Trip: Survey Fee:
Add Fee:	Transportation
Add Fee:	: Site Insp (\$)_s - RSSI
Report Format:	: Interview (\$
Lump Sum / I.B.I: (S	Tech Invs (\$). Others
,	Weekend (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD378U

Not Northern AAD2301-

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

SHD378U

VF1ABL15AUC282309

200303878K

RENAULT

LATITUDE

10/01/2023

SKQ6794H/ ALG

31/05/2016

bate of Registration.		31/05/2016		
PÄRT		LIST		
1 DOOR PANEL FRT LH	\$	1 2,844.66		
1 DOOR MOULDING FRT LH	\$	ام 100.50 گ		
1 DOOR HANDLE OUTER FRT LH	\$	√ 169.50 ⊀		
1 DOOR HANDLE MODULE FRT LH	\$	<i>f</i> 133.40 ₹		
1 DOOR REGULATOR FRT LH	\$	501.40 7		
1 DOOR REGUALTOR MOTOR FRT LH	\$	758.10 7		
1 DOOR HINGE UPPER FRT LH	\$	√ 274.50 ✓		
1 DOOR HINGE LOWER FRT LH	\$	1 300.55 X		
1 DOOR PANEL REAR LH	\$	Ry 2,844.66		
1 DOOR HANDLE OUTER REAR RH	\$	5≥ 42.10 ×		
1 DOOR HANDLE MODULE REAR RH	\$	133.40 €		
1 DOOR REGULATOR REAR LH	\$	450.60 X		
DOOR REGULATOR MOTOR REAR LH	\$	758.10 X		
DOOR HINGE UPPER REAR LH	\$	241.60 X		
DOOR HINGE LOWER REAR LH	\$	↑ 169.90 ★		
BUMPER COVER REAR	\$	rin 1561.70 X.		
BUMPER BRACKET SIDE LH REAR	\$	80.80 X		
BUMPER RETAINER LH REAR	\$	54.20 X		
FENDER PANEL FRT LH	¢			
WHEELARCH FRT LH	4	A 437.10		
FENDER PANEL REAR LH	\$	191.40 —		
WHEELARCH REAR LH	\$	1 ,933.20 ★		
	\$	275.40 X		
DOOR MIRROR LH	\$	1,483.40 X		
HEADLAMP LH	\$	743.60 🖈		
BUMPER BRACKET FRT LH (Headlamp Lower)	\$	116.47 X		
WHEEL HUB CAP	\$	nes 30.50		
	~	30.30		

12 JAN 2023

Trans-cab Auto Services Pte Ltd No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330 CO./GST Reg. No. 201019626G SHD378U		AAD2301-
1 WHEEL HUB CAP		
1 ROCKER PANEL OUTER LH	\$	30.50 X
	\$	1,184.99 X
TOTAL		15,600.24
10%		1,560.02
	<u>\$</u>	14,040.21
Special Nett		
1 DOOR TRIM CLIP		NA 7000 /
1 DOOR MOULDING CLIP	\$	70.00 X
1 DOOR STICKER TRANSCAB	\$	
1 DOOR STICKER 65553333	\$	Ma 100.00 601a
1 DOOR STICKER CLASSIC	\$	Ma 100.00 Gosac
1 RIM	\$	m 100.00 15/a
	\$	350.00 T
	\$	ام 300.00 /
1 RIM	\$	√ _{2 350.00} } X
1 TYRE	\$	300.00
1 FRT BUMPER CLIP	•	65.00
1 FENDER CLIP	ď	
1 FENDER LINER CLIP	4	70.00
	3	1~ 65.00)
TOTAL	\$	1,940.00
TOTAL PARTS	\$	15,980.21
LABOUR		A CONTRACTOR OF THE CONTRACTOR
To rust-proofing and apply undercoat of the affected areas.	\$	230.00 901
To transfer of door fittings, attachment and perform water		
seepage test.		
seepage test.	\$	170.00 1201
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.		(
ocopage rest.	\$	ルヘ 170.00 X
Putty and spray pointing of the		
Putty and spray painting of the affected portion.	\$	1,400.00 1329
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same		
Juine	\$	2,000.00 Fox

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666

Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD378U

(LUMPSUM) Repair Days	12 Days
Over All Total	20,510.21
TOTAL	4,530.00
To check steering geometry and computer wheel alignment	\$ 220.00 601
To Check Electrical Lighting Concerned.	\$ 170.00 201
To transfer of tire, rim and on wheel balancing.	\$ √∼ 170.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

AAD2301-

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

C SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
2. This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>
3. Information provided must be as truthful and accurate as possible. Any wilful misr 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation of the insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid. epresentation or witholding of material facts may allow insurance companies to repudiate

ACCIDENT STATEMENT

Date of Submission

Reported by

Date of Accident

Exact Location of Accident

Additional Location Information

Country/State of Loss

11/01/2023 10:41 (SGT)

Driver

10/01/2023 20:10 (SGT)

58 Toh Tuck Rd, Singapore 596747

SIGNATURE PARK CONDO

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SHD378U

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No

Email Address

Mobile Phone No

Alternative Phone No.

Yes

TRANS-CAB SERVICES PTE LTD

2XXXXX878K

claims@transcab.com.sg

(Phone) +65-62876666

VEHICLE PARTICULARS

Manufacturer

Model

Renault Latitude

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle?

. Vehicle Category

Transmission

CC

Private hire

No - Claiming third party

Taxi

Auto

1998

INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

AXA Insurance Pte Ltd

VFX/P2413997

DRIVER

Name of Driver NRIC No

Date Of Birth

Occupation

TAN BIN HUAT SXXXX202F 29/08/1957 Outdoor



Date Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?

26/03/1979 43 YEARS AND 10 MONTHS Male (Phone) +65-97958564

claims@transcab.com.sg 220 ANG MO KIO AVE 1

#12-799 560220 No

Hirer No

Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver

-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

Side Swipe Clear Drv

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Was notice of intended Prosecution given?
If yes, against whom?

No No

CIRCUMSTANCES OF ACCIDENT


ON 10/1/2023 AT ABOUT 2010HOURS , I WAS DRIVING MY VEHICLE AT SIGNATURE PARK CONDO TOWARDS MAIN ROAD . WHEN I DRIVING STRAIGHT , SUDDENLY VEHICLE B TURNING OUT FROM BASEMENT CAR PARK AND COLLIDED ONTO LEFT SIDE OF MY VEHICLE ${\sf E}$

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Yes No

DETAILS OF OTHER VEHICLE PROPERTY 1



Policyholder's Signature / Date &

300

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed By Reporting Officer
Wong Jun Keet
Witnessed by Reporting Centre
Personnel

We declare the foregoing particulars are true in every respect.