

ASS. REC. BY:

REF:

AIG/230006521kp

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/HO 378U

Yr Regn:

05, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

C.C

1995

Colour

M.P. White/Red

A/C:

Insured / Std / NI / NA

Sp. Reading

6775

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC 282309

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/80R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

FIREAR

Front

Rear

R/Bal.

7

mm

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

10/1/23

D.O.I.

12/1/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/11 11:00 @ 85506 Cahu

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

) S + RS. SI

) P. 105

) Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD378U*Not Authorised*
*L1 Reg 86550/r***AAD2301-**

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

12 JAN 2023**SHD378U**

VF1ABL15AUC282309

200303878K

RENAULT

LATITUDE

10/01/2023

SKQ6794H/ ALG

31/05/2016

PART**LIST**

1	DOOR PANEL FRT LH	\$	<i>Pr</i>	2,844.66	✓
1	DOOR MOULDING FRT LH	\$	<i>Pr</i>	100.50	X
1	DOOR HANDLE OUTER FRT LH	\$	<i>Pr</i>	169.50	X
1	DOOR HANDLE MODULE FRT LH	\$	<i>Pr</i>	133.40	X
1	DOOR REGULATOR FRT LH	\$	<i>Pr</i>	501.40	X
1	DOOR REGULATOR MOTOR FRT LH	\$	<i>Pr</i>	758.10	X
1	DOOR HINGE UPPER FRT LH	\$	<i>Pr</i>	274.50	X
1	DOOR HINGE LOWER FRT LH	\$	<i>Pr</i>	300.55	X
1	DOOR PANEL REAR LH	\$	<i>Pr</i>	2,844.66	✓
1	DOOR HANDLE OUTER REAR RH	\$	<i>Pr</i>	42.10	X
1	DOOR HANDLE MODULE REAR RH	\$	<i>Pr</i>	133.40	X
1	DOOR REGULATOR REAR LH	\$	<i>Pr</i>	450.60	X
1	DOOR REGULATOR MOTOR REAR LH	\$	<i>Pr</i>	758.10	X
1	DOOR HINGE UPPER REAR LH	\$	<i>Pr</i>	241.60	X
1	DOOR HINGE LOWER REAR LH	\$	<i>Pr</i>	169.90	X
1	BUMPER COVER REAR	\$	<i>Pr</i>	561.70	X
1	BUMPER BRACKET SIDE LH REAR	\$	<i>Pr</i>	80.80	X
1	BUMPER RETAINER LH REAR	\$	<i>Pr</i>	54.20	X
1	FENDER PANEL FRT LH	\$	<i>Pr</i>	437.10	✓
1	WHEELARCH FRT LH	\$	<i>Pr</i>	191.40	✓
1	FENDER PANEL REAR LH	\$	<i>Pr</i>	1,933.20	X
1	WHEELARCH REAR LH	\$	<i>Pr</i>	275.40	X
1	DOOR MIRROR LH	\$	<i>Pr</i>	1,483.40	X
1	HEADLAMP LH	\$	<i>Pr</i>	743.60	X
1	BUMPER BRACKET FRT LH (Headlamp Lower)	\$	<i>Pr</i>	116.47	X
1	WHEEL HUB CAP	\$	<i>Pr</i>	30.50	✓

Trans-cab Auto Services Pte Ltd**AAD2301-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD378U

1 WHEEL HUB CAP	\$	<i>Pr</i> 30.50	X
1 ROCKER PANEL OUTER LH	\$	<i>n</i> 1,184.99	X
TOTAL	\$	15,600.24	
10%	\$	1,560.02	
	\$	14,040.21	

Special Nett

1 DOOR TRIM CLIP	\$	<i>nn</i> 70.00	X
1 DOOR MOULDING CLIP	\$	<i>nn</i> 70.00	X
1 DOOR STICKER TRANSCAB	\$	<i>nn</i> 100.00	<i>60sn</i>
1 DOOR STICKER 65553333	\$	<i>nn</i> 100.00	<i>60sn</i>
1 DOOR STICKER CLASSIC	\$	<i>nn</i> 100.00	<i>15sn</i>
1 RIM	\$	<i>Pr</i> 350.00	} X
1 TYRE	\$	<i>Pr</i> 300.00	
1 RIM	\$	<i>Pr</i> 350.00	
1 TYRE	\$	<i>Pr</i> 300.00	
1 FRT BUMPER CLIP	\$	<i>nn</i> 65.00	
1 FENDER CLIP	\$	<i>nn</i> 70.00	
1 FENDER LINER CLIP	\$	<i>nn</i> 65.00	
TOTAL	\$	1,940.00	
TOTAL PARTS	\$	15,980.21	

LABOUR

To rust-proofing and apply undercoat of the affected areas.	\$	230.00	<i>901</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	<i>1201</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00	X
Putty and spray painting of the affected portion.	\$	1,400.00	<i>13201</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,000.00	<i>7001</i>