

ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C

bizSAFE₃

FROM : Jaclyn Lai
TEL. NO. : 6265-0026 / 9236-8218
EMAIL : jaclynlai@asmauto.com.sg

TO : Allianz Insurance Singapore Pte. Ltd.
ATTN : Motor Claim Department
TEL. NO. : 6714 3369
EMAIL : claims@allianz.com.sg

CC : UBTS PTE LTD

DATE : 17.01.2023


VEHICLE NO. : XE 3860 D
MODEL NO. : SCANIA P440LA4X2HSZ
CHASSIS NO. : YS2P4X20005480009
ENGINE NO. : DC13112L017033663
LTA REG DATE : 22.12.2017 - 21.12.2027

CLAIM TYPE : Own Damaged
D.O.A : 11.01.2023
CLAIM REF NO. : asm/AC23006/JL

QUOTATION FOR ACCIDENT REPAIR

S/N	SPARE PARTS	QTY	UOM	UNIT PRICE	AMOUNT
1	Front view mirror	1	pc	\$ 275.04	\$ 275.04 <i>un</i>
2	Front windscreen	1	pc	\$ 1,080.00	\$ 1,080.00 <i>cur</i>
3	Wiper arm, LH	1	pc	\$ 382.20	\$ 382.20 <i>bt</i>
4	Wiper blade, LH	1	pc	\$ 70.56	\$ 70.56 <i>ent</i>
5	Member panel, LH	1	pc	\$ 154.08	\$ 154.08 <i>cur</i>
6	Member panel, center	1	pc	\$ 131.64	\$ bt 131.64 <i>TV</i>
7	Member panel, RH	1	pc	\$ 154.20	\$ 154.20 <i>de</i>
8	Space frame	1	pc	\$ 2,431.80	\$ 2,431.80 <i>bt</i>
9	Space frame hinge, LH & RH	2	pcs	\$ 391.56	\$ nn 783.12 <i>TX</i>
10	Front upper panel	1	pc	\$ 1,696.92	\$ 1,696.92 <i>bt</i>
11	Logotype "SCAN"	1	pc	\$ 89.64	\$ 89.64 <i>cur</i>
12	Logotype "IA"	1	pc	\$ 74.16	\$ 74.16 <i>cur</i>
13	Front upper panel rail	1	pc	\$ 868.68	\$ 868.68 <i>bt</i>
14	Front upper panel top mesh, LH	1	pc	\$ 133.68	\$ 133.68 <i>bt</i>
15	Front upper panel center mesh, top	1	pc	\$ 272.64	\$ 272.64 <i>bt</i>
16	Front upper panel center mesh, bottom	1	pc	\$ 285.96	\$ 285.96 <i>bt</i>
17	Mesh clamp	15	pcs	\$ 4.08	\$ 61.20 <i>cur</i>
18	Cab corner - outer, LH & RH	2	pcs	\$ 979.44	\$ 1,958.88 <i>cur</i>
19	Cab corner - inner, LH & RH	2	pcs	\$ 101.40	\$ 202.80 <i>de</i>
20	Wiper link	1	pc	\$ 722.88	\$ nn 722.88 <i>TX</i>
21	Wiper link bracket	1	pc	\$ 1,590.00	\$ bt 1,590.00 <i>TV</i>
22	Wiper motor	1	pc	\$ 831.12	\$ nn 831.12 <i>TX</i>
23	Expansion tank	1	pc	\$ 922.08	\$ nn 922.08 <i>TX</i>
24	Expansion tank square casing	1	pc	\$ 90.36	\$ 90.36 <i>de</i>
25	Air duct assy	1	unit	\$ 793.68	\$ 793.68 <i>cur</i>
26	Fan motor assy	1	unit	\$ 1,551.12	\$ cra 1,551.12 <i>TV</i>
27	Heat exchange core	1	pc	\$ 932.04	\$ nn 932.04 <i>TX</i>
28	Evaporator coil	1	pc	\$ 1,274.52	\$ nn 1,274.52 <i>TX</i>
29	HVAC assy	1	unit	\$ 711.36	\$ nn 711.36 <i>TX</i>
30	Aircon receiver drier	1	pc	\$ 218.40	\$ 218.40 <i>bt</i>
31	Aircon condenser	1	pc	\$ 2,204.64	\$ 2,204.64 <i>bt</i>
32	Charge air cooler	1	unit	\$ 3,510.12	\$ 3,510.12 <i>bt</i>
33	Radiator	1	unit	\$ 2,933.16	\$ bt 2,933.16 <i>TV</i>
34	Radiator fastener/mounting, LH & RH	2	pcs	\$ 292.56	\$ bt 585.12 <i>TV</i>
35	Front cabin bracket, LH & RH	2	pcs	\$ 1,811.40	\$ bt 3,622.80 <i>TV RH</i>
36	Front cabin air spring (shock absorber), LH & RH	2	pcs	\$ 703.32	\$ 1,406.64 <i>bt</i>
37	Air spring link yoke, LH & RH	2	pcs	\$ 257.88	\$ 515.76 <i>bt</i>
38	Turret, LH & RH	2	pcs	\$ 945.24	\$ 1,890.48 <i>RH</i>

LH-TX RH *nn*



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424

Main Line: 6265 0980 Fax: 6265 6068

Email: enquiry@asmauto.com.sg

Co. / GST Reg. No.: 201203813C


bigSAFE
LH-X RH-bro

39	Turret cap, LH & RH	2	pcs	\$ 336.84	\$ nn 673.68 RH
40	Anti-roll bar assy with bushing & washer	1	unit	\$ 3,954.72	\$ 3,954.72 bt-
41	Air piping (left)	1	pc	\$ 143.00	\$ 143.00 d/d
42	Cabin lock, LH & RH	2	pcs	\$ 382.08	\$ 764.16 bt-
43	Cabin lock wire rope	1	pc	\$ 367.20	\$ 367.20 ?X n
44	Air intake, center	1	pc	\$ 657.00	\$ 657.00 d/d
45	Air cleaner assy	1	pc	\$ 3,334.32	\$ 3,334.32 ?nn-
46	Headlamp seal, LH & RH	2	pcs	\$ 231.60	\$ 463.20 d/d
47	Headlamp inner bracket, RH	1	pc	\$ 999.60	\$ 999.60 bt-
48	Headlamp side bracket, RH	1	pc	\$ 228.96	\$ nn ?nn 228.96 ?X
49	Headlamp inner housing, RH	1	pc	\$ 544.32	\$ 544.32 d/d
50	Headlamp assy, RH	1	pc	\$ 478.44	\$ 478.44 ?nn-
51	Front signal lamp, RH	1	pc	\$ 138.00	\$ 138.00 ?nn-
52	Headlamp cover strip, RH	1	pc	\$ 34.32	\$ 34.32 d/d
53	Headlamp protection mesh, RH	1	pc	\$ 272.88	\$ 272.88 m/s
54	Protection mesh bracket (inner), RH	1	pc	\$ 129.12	\$ 129.12 bt-
55	Protection mesh bush, RH	1	pc	\$ 336.84	\$ 336.84 m/s
56	Protection mesh bracket (outer), RH	1	pc	\$ 129.12	\$ 129.12 d/d
57	Front lower panel, RH	1	pc	\$ 165.48	\$ 165.48 bt-
58	Front lower panel bracket, RH	1	pc	\$ 3,194.52	\$ 3,194.52 b/c
59	Front lower panel, center	1	pc	\$ 1,118.40	\$ 1,118.40 bt-
60	Front bumper step plate, center	1	pc	\$ 561.60	\$ 561.60 ?nn-
61	Front bumper cover, LH & RH	2	pcs	\$ 2,239.44	\$ 4,478.88 R/X
62	Front number plate holder	1	pc	\$ 179.52	\$ 179.52 m/s
63	Step cover - upper, LH & RH	2	pcs	\$ 132.00	\$ nn 264.00 ?X ni
64	Front wheel mudguard seal (front long), LH & RH	2	pcs	\$ 182.50	\$ 365.00 m/s
65	Rear cabin bracket - bottom, LH & RH	2	pcs	\$ 874.44	\$ 1,748.88 ?V
66	Rear cab tilt lock, LH & RH	2	pcs	\$ 1,518.72	\$ 3,037.44 RH
67	Lock key, LH & RH	2	pcs	\$ 338.40	\$?nn 676.80 ?X
68	Rear cabin spring (shock absorber), LH & RH	2	pcs	\$ 682.32	\$ bt 1,364.64 ?V
69	Rear crosslink bracket, LH & RH	2	pcs	\$ 108.24	\$ 216.48 RH
70	Link, LH & RH	2	pcs	\$ 136.32	\$ 272.64 RH
71	Link washer, LH & RH	6	pcs	\$ 16.56	\$ 99.36 RH

SUB-TOTAL : \$ 68,806.00
COST PLUS 10% : \$ 6,880.60
TOTAL : \$ 75,686.60

S/N	SPARE PARTS (SPECIAL NETT ITEMS)	QTY	UOM	UNIT PRICE	AMOUNT
1	Sealant	3	bot	\$ 30.00	\$ 90.00
2	IU bracket sticker	1	set	\$ 5.00	\$ 5.00
3	Front number plate	1	pc	\$ 30.00	\$ 30.00
4	Radiator coolant	25	Lit	\$ 15.00	\$ 375.00
S/N ITEMS TOTAL :					\$ 500.00

TOTAL PARTS : \$ 76,186.60



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424

Main Line: 6265 0980 Fax: 6265 6068

Email: enquiry@asmauto.com.sg

Co. / GST Reg. No.: 201203813C

bizSAFE₃


S/N	LABOUR CHARGES	AMOUNT
1	Dismantle and replace front windscreen, including apply sealant.	\$ 350.00 ³⁰⁰
2	To dismantle front and interior attached parts, such as instrument panels, seat cushions, all piping/hoses, wiring harness etc. To jack, knock and straighten dash panel & floor panel. Remove and replace damaged parts, reinstall necessary parts. Realign front cabin etc.	\$ 4,200.00 ²⁸⁰⁰
3	Remove and replace charge air cooler & radiator etc.	\$ 700.00 ⁵²⁵
4	Remove and replace aircon condenser. Vacuum and replenish aircon gas.	\$ 300.00 ²⁰⁰
5	Spray painting (interior & exterior)	\$ 1,000.00 ⁸⁰⁰
TOTAL LABOUR :		\$ 6,550.00
GRAND TOTAL :		\$ 82,736.60

Taufik 97495747
 Not Authorise
 Ex \$1500 22/1/23 @ 440pm
 L/S Resurvey after repair
 Taufik @ lkh auto. com
 14 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424

Main Line: 6265 0980 Fax: 6265 6068

Email: enquiry@asmauto.com.sg

Co. / GST Reg. No.: 201203813C

bizSAFE₃

FROM : Jaclyn Lai
 TEL. NO. : 6265-0026 / 9236-8218
 EMAIL : jaclynlai@asmauto.com.sg

TO : Allianz Insurance Singapore Pte. Ltd.
 ATTN : Motor Claim Department
 TEL. NO. : 6714 3369
 EMAIL : claims@allianz.com.sg

CC : UBTS PTE LTD

DATE : 21.02.2023

VEHICLE NO. : XE 3860 D
 MODEL NO. : SCANIA P440LA4X2HSZ
 CHASSIS NO. : YS2P4X20005480009
 ENGINE NO. : DC13112L017033663
 LTA REG DATE : 22.12.2017 - 21.12.2027

CLAIM TYPE : Own Damaged
 D.O.A : 11.01.2023
 CLAIM REF NO. : asm/AC23006/JL

QUOTATION FOR ACCIDENT REPAIR - SUPPLEMENTARY

S/N	SPARE PARTS	QTY	UOM	UNIT PRICE	AMOUNT
1	Sun visor, bottom	1	pc	\$ 540.15	\$ de 540.15
2	Recirculation shield, front upper panel	1	pc	\$ 143.91	\$ bt 143.91
3	Cabin lock bracket, LH & RH	2	pcs	\$ 105.17	\$ bt 210.34
4	Contact housing outer casing	1	pc	\$ 105.00	\$ dis 105.00
5	Front cabin stopper (missing)	2	pcs	\$ 18.00	\$ mis 36.00
6	Cab tilt stop	1	pc	\$ 982.28	\$ bt 982.28
7	Bleed pipe	1	pc	\$ 212.00	\$ cut 212.00
8	Water hose assy	1	set	\$ 225.00	\$ cut 225.00
9	Water hose	1	pc	\$ 30.00	\$ cut 30.00
10	Charge air cooler hose	2	pcs	\$ 135.00	\$ dis 270.00
11	Hose clamp	4	pcs	\$ 45.00	\$ bt 180.00
12	Radiator side link, LH & RH	2	pcs	\$ 238.16	\$ bt 476.32
13	Radiator side bracket, RH	1	pc	\$ 53.30	\$ bt 53.30
14	Recirculation shield, radiator	1	pc	\$ 573.95	\$ cra 573.95
15	Radiator fan cover	1	pc	\$ 708.24	\$ cra 708.24
16	Fan ring	1	pc	\$ 929.37	\$ dis 929.37
17	Fan ring rubber	1	pc	\$ 360.62	\$ cut 360.62
18	Fan c/w fan clutch	1	set	\$ 1,660.00	\$ cra 1,660.00
19	Front lower panel, LH	1	pc	\$ 179.27	\$ bt 179.27
20	Headlamp protection mesh bracket (inner), LH	1	pc	\$ 139.88	\$ bt 139.88
21	Power steering shaft	1	pc	\$ 870.00	\$ bt 870.00

SUB-TOTAL : \$ 8,885.63
 COST PLUS 10% : \$ 888.56
 TOTAL PARTS : \$ 9,774.19

S/N	LABOUR CHARGES	AMOUNT
1	To remove and replace water bleed pipe (on top of engine), fan ring & rubber, fan assy.	\$ 350.00
TOTAL LABOUR :		\$ 350.00
GRAND TOTAL :		\$ 10,124.19