

REC BY: T. J. J. J.

REF: CS / AB23000653 / TVY3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect/Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 91500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value: 984K.

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Salun

Date / Time _____ Action / Instruction _____

Veh No: XE 386 OD Yr Regn: 2017, Dec.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Scania P440LA4X2MSE 12742

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 528157 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: US2P4X2000 548 0009

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 315 / 80R22.5

R: ~ ~ (D)

BS / DUN / EXNOVA / GY / FS / LZA / MIC / DHTSU / PIR / SUMI /

TOYO / YOKO, or Double Coin

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 8/8 mm

L/Bal. 8 mm L/Bal. 8/8 mm

D.O.A. _____ D.O.L. 27/1/23

Survey held at ASM Auto

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to? _____

2) _____

Repair Format: _____

Lump Sum / I.B.R. (%) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)


☐ : Tech. Invs (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS SI _____

Photos _____



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C

bizSAFE₃

FROM : Jaclyn Lai
TEL. NO. : 6265-0026 / 9236-8218
EMAIL : jaclynlai@asmauto.com.sg

DATE : 17.01.2023

TO : Allianz Insurance Singapore Pte. Ltd.
ATTN : Motor Claim Department
TEL. NO. : 6714 3369
EMAIL : claims@allianz.com.sg

VEHICLE NO. : XE 3860 D
MODEL NO. : SCANIA P440LA4X2HSZ
CHASSIS NO. : YS2P4X20005480009
ENGINE NO. : DC13112L017033663
LTA REG DATE : 22.12.2017 - 21.12.2027


CC : UBTS PTE LTD

CLAIM TYPE : Own Damaged
D.O.A : 11.01.2023
CLAIM REF NO. : asm/AC23006/JL

QUOTATION FOR ACCIDENT REPAIR

S/N	SPARE PARTS	QTY	UOM	UNIT PRICE	AMOUNT
1	Front view mirror	1	pc	\$ 275.04	\$ 275.04 <i>cur</i>
2	Front windscreen	1	pc	\$ 1,080.00	\$ 1,080.00 <i>cur</i>
3	Wiper arm, LH	1	pc	\$ 382.20	\$ 382.20 <i>bt</i>
4	Wiper blade, LH	1	pc	\$ 70.56	\$ 70.56 <i>ent</i>
5	Member panel, LH	1	pc	\$ 154.08	\$ 154.08 <i>cur</i>
6	Member panel, center	1	pc	\$ 131.64	\$ 131.64 ?
7	Member panel, RH	1	pc	\$ 154.20	\$ 154.20 <i>de</i>
8	Space frame	1	pc	\$ 2,431.80	\$ 2,431.80 <i>bt</i>
9	Space frame hinge, LH & RH	2	pcs	\$ 391.56	\$ 783.12 ?
10	Front upper panel	1	pc	\$ 1,696.92	\$ 1,696.92 <i>bt</i>
11	Logotype "SCAN"	1	pc	\$ 89.64	\$ 89.64 <i>re</i>
12	Logotype "IA"	1	pc	\$ 74.16	\$ 74.16 <i>re</i>
13	Front upper panel rail	1	pc	\$ 868.68	\$ 868.68 <i>bt</i>
14	Front upper panel top mesh, LH	1	pc	\$ 133.68	\$ 133.68 <i>bt</i>
15	Front upper panel center mesh, top	1	pc	\$ 272.64	\$ 272.64 <i>bt</i>
16	Front upper panel center mesh, bottom	1	pc	\$ 285.96	\$ 285.96 <i>bt</i>
17	Mesh clamp	15	pcs	\$ 4.08	\$ 61.20 <i>re</i>
18	Cab corner - outer, LH & RH	2	pcs	\$ 979.44	\$ 1,958.88 <i>cur</i>
19	Cab corner - inner, LH & RH	2	pcs	\$ 101.40	\$ 202.80 <i>de</i>
20	Wiper link	1	pc	\$ 722.88	\$ 722.88 ?
21	Wiper link bracket	1	pc	\$ 1,590.00	\$ 1,590.00 ?
22	Wiper motor	1	pc	\$ 831.12	\$ 831.12 ?
23	Expansion tank	1	pc	\$ 922.08	\$ 922.08 ?
24	Expansion tank square casing	1	pc	\$ 90.36	\$ 90.36 <i>de</i>
25	Air duct assy	1	unit	\$ 793.68	\$ 793.68 <i>cur</i>
26	Fan motor assy	1	unit	\$ 1,551.12	\$ 1,551.12 ?
27	Heat exchange core	1	pc	\$ 932.04	\$ 932.04 ?
28	Evaporator coil	1	pc	\$ 1,274.52	\$ 1,274.52 ?
29	HVAC assy	1	unit	\$ 711.36	\$ 711.36 ?
30	Aircon receiver drier	1	pc	\$ 218.40	\$ 218.40 <i>de</i>
31	Aircon condenser	1	pc	\$ 2,204.64	\$ 2,204.64 <i>bt</i>
32	Charge air cooler	1	unit	\$ 3,510.12	\$ 3,510.12 <i>bt</i>
33	Radiator <i>photo</i>	1	unit	\$ 2,933.16	\$ 2,933.16 ?
34	Radiator fastener/mounting, LH & RH	2	pcs	\$ 292.56	\$ 585.12 ?
35	Front cabin bracket, LH & RH	2	pcs	\$ 1,811.40	\$ 3,622.80 ?
36	Front cabin air spring (shock absorber), LH & RH	2	pcs	\$ 703.32	\$ 1,406.64 <i>bt</i>
37	Air spring link yoke, LH & RH	2	pcs	\$ 257.88	\$ 515.76 <i>bt</i>
38	Turret, LH & RH	2	pcs	\$ 945.24	\$ 1,890.48

LH-?, RH *bt*



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424

Main Line: 6265 0980 Fax: 6265 6068

Email: enquiry@asmauto.com.sg

Co. / GST Reg. No.: 201203813C


bizSAFE₃
LH-? RH-? PH-?

39	Turret cap, LH & RH	2	pcs	\$ 336.84	\$ 673.68	
40	Anti-roll bar assy with bushing & washer	1	unit	\$ 3,954.72	\$ 3,954.72	<i>bt</i>
41	Air piping (left)	1	pc	\$ 143.00	\$ 143.00	<i>ddl</i>
42	Cabin lock, LH & RH	2	pcs	\$ 382.08	\$ 764.16	<i>bt</i>
43	Cabin lock wire rope	1	pc	\$ 367.20	\$ 367.20	<i>?</i>
44	Air intake, center	1	pc	\$ 657.00	\$ 657.00	<i>all</i>
45	Air cleaner assy	1	pc	\$ 3,334.32	\$ 3,334.32	<i>cur</i>
46	Headlamp seal, LH & RH	2	pcs	\$ 231.60	\$ 463.20	<i>bt</i>
47	Headlamp inner bracket, RH	1	pc	\$ 999.60	\$ 999.60	<i>bt</i>
48	Headlamp side bracket, RH	1	pc	\$ 228.96	\$ 228.96	<i>?</i>
49	Headlamp inner housing, RH	1	pc	\$ 544.32	\$ 544.32	<i>ddl</i>
50	Headlamp assy, RH	1	pc	\$ 478.44	\$ 478.44	<i>cur</i>
51	Front signal lamp, RH	1	pc	\$ 138.00	\$ 138.00	<i>cur</i>
52	Headlamp cover strip, RH	1	pc	\$ 34.32	\$ 34.32	<i>all</i>
53	Headlamp protection mesh, RH	1	pc	\$ 272.88	\$ 272.88	<i>mis</i>
54	Protection mesh bracket (inner), RH	1	pc	\$ 129.12	\$ 129.12	<i>bt</i>
55	Protection mesh bush, RH	1	pc	\$ 336.84	\$ 336.84	<i>mis</i>
56	Protection mesh bracket (outer), RH	1	pc	\$ 129.12	\$ 129.12	<i>ddl</i>
57	Front lower panel, RH	1	pc	\$ 165.48	\$ 165.48	<i>bt</i>
58	Front lower panel bracket, RH <i>Co</i>	1	pc	\$ 3,194.52	\$ 3,194.52	<i>bb</i>
59	Front lower panel, center	1	pc	\$ 1,118.40	\$ 1,118.40	<i>bt</i>
60	Front bumper step plate, center	1	pc	\$ 561.60	\$ 561.60	<i>cur</i>
61	Front bumper cover, LH & RH	2	pcs	\$ 2,239.44	\$ 4,478.88	<i>Rx</i>
62	Front number plate holder	1	pc	\$ 179.52	\$ 179.52	<i>mis</i>
63	Step cover - upper, LH & RH	2	pcs	\$ 132.00	\$ 264.00	<i>?</i>
64	Front wheel mudguard seal (front long), LH & RH	2	pcs	\$ 182.50	\$ 365.00	<i>mis</i>
65	Rear cabin bracket - bottom, LH & RH <i>LH-? RH-? RH-? RH-?</i>	2	pcs	\$ 874.44	\$ 1,748.88	<i>?</i>
66	Rear cab tilt lock, LH & RH <i>LH-? RH-? RH-?</i>	2	pcs	\$ 1,518.72	\$ 3,037.44	
67	Lock key, LH & RH	2	pcs	\$ 338.40	\$ 676.80	<i>?</i>
68	Rear cabin spring (shock absorber), LH & RH	2	pcs	\$ 682.32	\$ 1,364.64	<i>?</i>
69	Rear crosslink bracket, LH & RH <i>LH-? RM-? RM-?</i>	2	pcs	\$ 108.24	\$ 216.48	
70	Link, LH & RH <i>LH-? RM-? RM-?</i>	2	pcs	\$ 136.32	\$ 272.64	
71	Link washer, LH & RH <i>LH-? RM-? RM-?</i>	6	pcs	\$ 16.56	\$ 99.36	

SUB-TOTAL :	\$ 68,806.00
COST PLUS 10% :	\$ 6,880.60
TOTAL :	\$ 75,686.60

S/N	SPARE PARTS (SPECIAL NETT ITEMS)	QTY	UOM	UNIT PRICE	AMOUNT
1	Sealant	3	bot	\$ 30.00	\$ <i>net</i> 90.00
2	IU bracket sticker	1	set	\$ 5.00	\$ <i>net</i> 5.00
3	Front number plate	1	pc	\$ 30.00	\$ <i>mis</i> 30.00
4	Radiator coolant	25	Lit	\$ 15.00	\$ <i>net</i> 375.00
S/N ITEMS TOTAL :					\$ 500.00

TOTAL PARTS :	\$ 76,186.60
---------------	--------------



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C

bizSAFE₃

<u>S/N</u>	<u>LABOUR CHARGES</u>	<u>AMOUNT</u>
1	Dismantle and replace front windscreen, including apply sealant. <i>350.</i>	\$ 350.00 <i>300</i>
2	To dismantle front and interior attached parts, such as instrument panels, seat cushions, all piping/hoses, wiring harness etc. To jack, knock and straighten dash panel & floor panel. Remove and replace damaged parts, reinstall necessary parts. Realign front cabin etc.	\$ 4,200.00 <i>2800</i>
3	Remove and replace charge air cooler & radiator etc.	\$ 700.00 <i>525</i>
4	Remove and replace aircon condenser. Vacuum and replenish aircon gas.	\$ 300.00 <i>200</i>
5	Spray painting (interior & exterior)	\$ 1,000.00 <i>800</i>
TOTAL LABOUR :		\$ 6,550.00
GRAND TOTAL :		\$ 82,736.60

Taufik 97495749
Not Authorise
Ex \$1500 27/1/23 @ 440pm
L/S Resurvey after repair
Taufik @ lkk auto.com
14 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: