

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0055/2023/EQ
DATE : 17-Jan-23
WIP : 59237

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 17/1/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS TAN SIEW FOONG
ADDRESS : BLK 432 BUKIT PANJANG RING ROAD
#10-605
SINGAPORE 670432
TELEPHONE : HP +65 91265289
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220007934
VEHICLE NO : **SGQ 1219 H**
MODEL CODE : AUDI A3 SEDAN 1.5 TFSI
MODEL YEAR : 24/1/2022
ENGINE NO : DFY 293516
CHASSIS NO : WAUZZZGY2NA005888
MILEAGE : 27,430
DATE IN : 16-Jan-23
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Jan-23
PLACE OF ACCIDENT : CROSS ROAD OF ADAM ROAD AND DUNEARN ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGQ 1219 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	/
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	S O J
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,400.00	/
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	?
5	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILTIAE RESPRAY OF BOTH FRONT DOOR.	S/N \$ 560.00	X.
6	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT DOOR TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,300.00	3250.
TOTAL LABOUR CHARGES		: \$ 10,640.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGQ 1219 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDER, BOTH UPPER A-PILLAR AND BOTH FRONT DOOR. ✓✓✓	\$ 7,000.00 2400	4 x 550 = 2200 Hing x 2 = 200 <u>2400</u>
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 17,832.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGQ 1219 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1 \$	1,778.00	✓
2	FRONT BUMPER FIXING PARTS <i>photo</i>	1 \$	307.00	X
3	FRONT BUMPER CLOSING ELEMENT - LH / RH	2 \$	274.00	
4	FRONT BUMPER GRILLE - LOWER CENTRE <i>could</i>	1 \$	458.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>photo</i>	1 \$	281.00	✓
6	FRONT BUMPER AIR GUIDE - LH / RH <i>photo?</i>	2 \$	142.00	<i>photo?</i>
7	FRONT BUMPER SPOILER <i>photo</i>	1 \$	345.00	✓
8	FRONT BUMPER TRIM COVER - LH / RH <i>LH ut</i>	2 \$	220.00	<i>110</i>
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>LH ut</i>	2 \$	362.00	<i>181</i>
10	FRONT PARKING AID SENSOR SUPPORT - LH / RH <i>?</i>	2 \$	92.00	<i>?</i>
11	RADIATOR GRILLE <i>photo</i>	1 \$	1,167.00	✓
12	RADIATOR GRILLE CLOSING ELEMENT - CENTER <i>could</i>	1 \$	223.00	✓
13	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	1 \$	127.00	<i>?</i>
14	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1 \$	793.00	<i>?</i>
15	FRONT BUMPER SUPPORT - LH / RH <i>?</i>	2 \$	22.00	<i>?</i>
16	FRONT BUMPER GUIDE SECTION - LH / RH <i>?</i>	2 \$	114.00	<i>?</i>
17	FRONT BUMPER TOP COVER <i>could</i>	1 \$	94.00	✓
18	CAUTION SIGN STICKER <i>photo</i>	1 \$	17.00	✓
19	AIR CONDITIONER STICKER <i>photo</i>	1 \$	9.00	✓
20	HORN LOW TONE - LH <i>?</i>	1 \$	157.00	<i>?</i>
SUB TOTAL SPARE PARTS		:	\$ 6,982.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGQ 1219 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HORN HIGH TONE - RH	1	\$ 165.00	X
22	HORN BRACKET	4	\$ 108.00	X
23	HORN BRACKET - LH	2	\$ 75.00	X
24	HORN BRACKET - RH	2	\$ 75.00	X
25	FRONT PARKING AID SENSOR - INNER	2	\$ 571.00	+
26	FRONT PARKING AID SENSOR - OUTER	2	\$ 571.00	+
27	FRONT PARKING AID SENSOR	2	\$ 543.00	+
28	FRONT PARKING AID SEAL RING	4	\$ 54.00	+
29	FRONT BUMPER WIRING SET	1	\$ 254.00	X
30	FRONT FENDER - LH / RH	2	\$ 2,626.00	1313.
31	FRONT FENDER CLOSING ELEMENT - LH / RH	2	\$ 68.00	+
32	FRONT FENDER RIVET	6	\$ 24.00	?
33	FRONT FENDER BRACKET - LH / RH	2	\$ 97.00	?
34	FRONT FENDER BRACKET - LH / RH	2	\$ 75.00	?
35	FRONT FENDER BRACKET - LH / RH	2	\$ 68.00	?
36	FRONT FENDER BRACE - LH / RH	2	\$ 208.00	?
37	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 396.00	+
38	FRONT WHEEL HOUSING LINER CLOSING ELEMENT - LH / RH	2	\$ 48.00	+
39	FRONT WHEEL HOUSING LINER ATTACHEMENT PARTS	1	\$ 131.00	+
40	BONNET	1	\$ 3,330.00	✓
SUB TOTAL SPARE PARTS			\$ 9,487.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGQ 1219 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET HINGE - LH / RH <i>Bent</i>	2	\$ 146.00	✓
42	BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 269.00	+
43	BONNET GAS FILLED STRUT <i>new</i>	1	\$ 117.00	+
44	BONNET IMPACT PROTECTION <i>new</i>	1	\$ 32.00	✓
45	BONNET SOUND ABSORBER <i>new</i>	1	\$ 223.00	+
46	FRONT SIDE PANEL COVER - LH / RH <i>new</i>	2	\$ 102.00	+
47	BONNET STRIKER - LH / RH <i>new</i>	2	\$ 260.00	+
48	BONNET RELEASE ELEMENT <i>?</i>	1	\$ 69.00	+
49	BONNET RELEASE LEVER <i>new</i>	1	\$ 16.00	+
50	BONNET LOCK - LH / RH	2	\$ 481.00	+
51	BONNET BOWDEN CABLE - CENTER <i>new</i>	1	\$ 66.00	+
52	BONNET RELEASE CABLE COVER <i>new</i>	1	\$ 12.00	+
53	BONNET LOCK CABLE <i>new</i>	1	\$ 87.00	+
54	FRONT PLENUM CHAMBER COVER <i>Not New</i>	1	\$ 187.00	+
55	HEADLIGHT - LH / RH <i>Cracked</i>	2	\$ 8,646.00	✓
56	HEADLIGHT HOSE - LH / RH <i>new</i>	2	\$ 58.00	+
57	LIFT CYLINDER - LH / RH <i>LH ?</i>	2	\$ 446.00	?
58	LIFT CYLINDER HOSE <i>new</i>	1	\$ 112.00	+
59	LIFT CYLINDER PUMP <i>?</i>	1	\$ 175.00	?
60	LIFT CYLINDER WINDSCREEN WASHER SYSTEM PUMP <i>new</i>	1	\$ 140.00	+
SUB TOTAL SPARE PARTS			\$ 11,644.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGQ 1219 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	LIFT CYLINDER WASH WATER RESERVOIR WITH WATER GAUGE <i>new</i>	1	\$ 190.00	+
62	LIFT CYLINDER STRAINER <i>new</i>	1	\$ 24.00	+
63	LIFT CYLINDER END CAP <i>new</i>	1	\$ 24.00	+
64	LOCK CARRIER <i>cracked</i>	1	\$ 1,030.00	✓
65	A/C CONDENSER <i>Not new</i>	1	\$ 586.00	+
66	A/C CONDENSER REFRIGERANT LINE	1	\$ 627.00	+
67	A/C CONDENSER REFRIGERANT LINE	1	\$ 503.00	+
68	A/C CONDENSER REFRIGERANT LINE <i>Not new</i>	1	\$ 609.00	+
69	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$ 22.00	?
70	ADDITIONER RADIATOR	1	\$ 967.00	+
71	RADIATOR BUSH - LH / RH LOWER	2	\$ 22.00	+
72	RADIATOR BRACKET - LH / RH	2	\$ 92.00	+
73	RADIATOR	1	\$ 1,099.00	+
74	READY-MIX COOLANT <i>new</i>	6	\$ 326.00	✓
75	RADIATOR FAN WITH FAN RING <i>Not new</i>	1	\$ 1,368.00	+
76	RADIATOR AIR GUIDE - LH / RH ?	2	\$ 90.00	?
77	RADIATOR AIR GUIDE - LOWER CENTRE ?	1	\$ 61.00	?
78	RADIATOR AIR GUIDE SEAL - RH ?	1	\$ 15.00	?
79	FRONT NOISE INSULATION <i>Not new</i>	1	\$ 408.00	+
80	INTAKE AIR DUCT COVER ?	1	\$ 31.00	?
SUB TOTAL SPARE PARTS		:	\$ 8,094.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGQ 1219 H

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
81	RADIATOR AIR DUCT	1	\$ 60.00	X	
82	RADIATOR AIR DUCT	1	\$ 36.00	+	
83	INTAKE AIR GUIDE FLAP	1	\$ 28.00	+	
84	RADIATOR AIR DUCT	1	\$ 37.00	+	
85	FRONT WATER DEFLECTOR STRIP - LH / RH	2	\$ 110.00	SS	
86	FRONT WINDOW SLOT SEAL TRIM STRIP - LH / RH OUTER	2	\$ 548.00	+	
87	FRONT WINDOW GUIDE TRIM STRIP - LH / RH	2	\$ 628.00	+	
88	FRONT NO PLATE	S/N	\$ 60.00	✓	
89	SUNDRIES		\$ 500.00	?	
TOTAL SPARE PARTS		:	\$ 38,214.00		
TOTAL LABOUR CHARGES		:	\$ 17,832.00		
GRAND TOTAL		:	\$ 56,046.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *17/01/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 09 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT