



Case Details

Case Reference Number : TAX/01/23/2043
Type of Repair : Accident Repair
Vehicle Registration Number : SHB261H

Company Type : Strides Taxi Pte Ltd
Estimation ID : EST-20336-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd
Accident Date and Time : 18/01/2023 11:40 PM
Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			FENDER ASM-FRT - L	1	379.81	379.81	10.00	341.83	Replace	1	341.83	Replace	✓
Standard	Main			BRACKET-F/FDR FRT LWR - LH	1	15.81	15.81	10.00	14.23	Replace	0	0	Check	?
Standard	Main			MODULE-FRT END	1	295.26	295.26	10.00	265.73	Replace	0	0	Check	?
Standard	Main			BRACKET ASM-HDLP UPP - LH	1	22.57	22.57	10.00	20.31	Replace	0	0	Check	?
Standard	Main			LINER ASM-FRT W/H - LH	1	125.22	125.22	10.00	112.70	Replace	0	0	Check	?
Standard	Main			DEFLECTOR-U/B FRT	1	169.72	169.72	10.00	152.75	Replace	0	0	Check	?
Standard	Main			FASCIA-FRT BPR	1	721.66	721.66	10.00	649.49	Replace	1	649.49	Replace	de ✓
Standard	Main			GRILLE-FRT BPR FASCIA LOWER	1	149.03	149.03	10.00	134.13	Replace	1	134.13	Replace	de ✓
Standard	Main			FINISHER-FRT BPR LOWER - LH	1	20.38	20.38	10.00	18.34	Replace	1	18.34	Replace	de ✓
Standard	Main			COVER-FRT FOG LP - LH	1	40.25	40.25	10.00	36.23	Replace	1	36.23	Replace	de ✓
Standard	Main			FINISHER-FRT FOG LP CVR - LH	1	47.32	47.32	10.00	42.59	Replace	1	42.59	Replace	de ✓
Standard	Main			BRACKET-FRT BPR FASCIA - LH	1	23.09	23.09	10.00	20.78	Replace	0	0	Check	?
Standard	Main			FINISHER-FRT BPR - LH	1	98.80	98.80	10.00	88.92	Replace	1	88.92	Replace	ana ✓
Standard	Main			SUPPORT-FRT BPR FASCIA UPR	1	172.33	172.33	10.00	155.10	Replace	0	0	Check	?
Total Spare Part Cost									4,887.62	Surveyor Total				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)				
Final Spare Part Cost									4,887.62	Final Sur Total				

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			PANEL ASM-LEG CTHR	1	131.04	131.04	10.00	117.94	Replace	0	0	Check	?
Standard	Main			BAR ASM-FRT BPR IMP	1	624.00	624.00	10.00	561.60	Replace	0	0	Check	?
Standard	Main			GRILLE ASM-RAD	1	978.02	978.02	10.00	880.22	Replace	0	0	Check	?
Standard	Main			HEADLAMP ASM -LH	1	1,098.86	1,098.86	10.00	988.97	Replace	1	988.97	Replace	one ✓
Standard	Main			BRACKET-F/CMPT TR PLT	1	44.51	44.51	10.00	40.06	Replace	0	0	Check	?
Standard	Main			COVER-F/CMPT ORNA	1	217.67	217.67	10.00	195.90	Replace	0	0	Not Give	Xun
Standard	Main			BRACKET-F/CMPT TR PLT	1	55.33	55.33	10.00	49.80	Replace	0	0	Not Give	Xun
Total Spare Part Cost									4,887.62	Surveyor Total 2,300.50				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)				
Final Spare Part Cost									4,887.62	Final Sur Total 2,300.50				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	1,200.00	600	
Total:			1,200.00	600.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	428.00	220	
2	Main	TO RESPRAY FRONT FENDER LH	428.00	220	
Total:			856.00	440.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	50	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			880.00	380.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
5	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	150	
6	Main	ISOLATED OF (EV) (NET)	150.00	150.00	
Total:			880.00	380.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,887.62	2,300.50
Total Labour Cost	1,200.00	600.00
Total Spray Painting	856.00	440.00
Other	880.00	380.00
Overall Total	7,823.62	3,720.50
Lump Sum Repair Option		☐
Lump Sum Total	0.00	3,720.50
Surveyor Approved Amount		3,720.50
No of Repair Days*	6	4
Remarks	-	PART BY PART / Before paint photo ,FOR CHECK ITEM and REPLACE ITEM.PLEASE CALL SURVEYOR TAUFIKH , HP 0746 57401 EMAIL : taufigh@lkkauto.com
Surveyor Name		Taufikh
Signature		
		Save Clear

Survey Date

19/01/2023

Taufikh 97495249
 'up' 19/1/23 0330pm
 4 days
 i/p resurvey before paint
 Taufikh lkkauto.com

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: