



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD  
C/O SEAH ONG & PARTNERS LLP  
36 ROBINSON ROAD #12-03 CITY HOUSE  
SINGAPORE 068877

Ref: CS3/ASM22001687/Rnp3e2-1

Date: 24/04/2023

Code: HSB

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 8851S	Veh. Inspected	SFS 292C
Policy No.	VFX/P2419140	Coverage (\$)	0.00
Claim No.	23.30375	Excess (\$)	0.00
Assign From	HENG XINYI (SEAH ONG)	Assign Date	11/01/2023

### 2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WVWZZZ3CZGE106389	Colour	BROWN
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/30Z R20	FALKEN	6 mm
L/H Front Tyre	245/30Z R20	FALKEN	6 mm
R/H Rear Tyre	245/30Z R20	FALKEN	6 mm
L/H Rear Tyre	245/30Z R20	FALKEN	6 mm

### 4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.

REPAIR CONDITION SEE DETAILS.

### 5. General Information

Accident Date	07/02/2022	Inspection Date	15/03/2023
Survey held at	70 TUAS SOUTH AVENUE 1 SINGAPORE 637285		
Repairer	V8 MOTOR WERKZ PTE LTD		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------