

Success United Pte Ltd (Co.Reg.No:200402570G)2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
Singapore 417921

Tel: 6746 1515 Fax: 6748 5015 Email: sirina@successunited.com.sg

TP INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)**Tan Yew Meng Augustine**

Singapore

TP Allianz
Xiao Teng**PARTICULARS OF CLAIM**

Claim Type:	Third Party	Ref. No:	TP23-009
Policy No:	SP22003026618	Date of Loss:	16/01/2023
Vehicle Reg. No.:	GBF2632H	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	Kalimuthu Paulpandian		
Make/Model:	TOYOTA DYNA, 3.0 D (M)	Vehicle Reg. Date:	15/08/2016
Vehicle Colour:	Blue		
Engine No:	1KD2613576	Chassis No:	KDY2318024775
Odometer:	306823 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) 2

Description of Accident/Loss REFER TO SKETCH PLAN.

Present Location: SUCCESS UNITED PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	693.00
Miscellaneous Items	0.00
Labour	450.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,143.00
+ GST 8.00% (S\$)	91.44
Nett Amount (S\$)	1,234.44

This claim is handled by: LAW YI TING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 17 Jan 2023)
Parts: N/A TOYOTA DYNA 3.0 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Success United Pte Ltd/GBF2632H/17/01/2023 18:06
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER ASSY <i>replaced</i>	0.00	0.00	*280.00 F
2	1		*FRT HEADLAMP ASSY RH <i>unltd</i>	0.00	0.00	*350.00 F
Sub Total (S\$)						630.00
+ Margin on L,N Items 10.00% (S\$)						63.00
Total Parts (S\$)						693.00

F=Franchise part.

Success United Pte Ltd/GBF2632H/17/01/2023 18:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

- 1 To remove, repair and replaced damaged bodyparts, realigned bodyworks & where consistent to the accident, and to putty and respray painting on frt bumper, corner panel and door RH.

New

450.00

400

Gross Labour Cost (S\$)

450.00

Success United Pte Ltd/GBF2632H/17/01/2023 18:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Adrian

1/s 19/01/23.

03 Days

total: 1083

1/s: 850 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: