

Section A - Accident Details

Registration Number	SHF362D
Case Reference Number	TAX/01/23/2044
Registration Date	14/Dec/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	POH SWEE KHENG
Type of Accident	Head to Rear
Accident Date and Time	18/Jan/2023 4:50 PM
Accident Reported Date and Time	19/Jan/2023 9:17 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24117475
Special Instruction to ARC, if any	TP/ FRONT AND REAR PORTION
Prepared Date and Time	19/Jan/2023 10:06 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates
Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$3,718.00	\$1,200.00
Total Spray Cost	\$3,924.00	\$1,400.00
Total Spare Part Cost	\$53,733.94	\$18,665.92
Total Other Cost	\$896.00	(\$4,065.92)
TOTAL COST	\$62,271.94	\$17,200.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	16.0	9.0
Prepared / Adjusted By	Boon Chew Tay	Taufikh (LKK) / INCOME
ARC / Surveyor Sign Off Date	02/02/2023 4:50 PM	02/02/2023 1:16 PM
Signature		
Remarks	REQ NBV / AFTER PAINT PHOTOS ,FOR CHECK ITEM and REPLACE ITEM.PLEASE CALL SURVEYOR TAUFIKH , HP 9749 5749/ EMAIL: taufikh@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2303-0060	Invoice Number	
Quotation Date	09.03.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$2,028.00	\$700.00
TO REPAIR REAR PORTION	\$1,690.00	\$500.00
Total Labour	\$3,718.00	\$1,200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$100.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$3,924.00	\$1,400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$4,275.92)
TOWING CHARGE	\$56.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$50.00
TO TOP UP A/C GAS	\$120.00	\$100.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CONDUCT RADIATOR PRESSURE CHECK	\$120.00	\$0.00
Total Other Costs	\$896.00	(\$4,065.92)

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 11/03/2023

User ID : PohSuan

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		5211947962	COVER, FR BUMPER	1.00	\$560.30	25.00	\$420.23	Replace	Replace	✓
		5211547050	SUPPORT, FR BUMPER RH	1.00	\$86.20	25.00	\$64.65	Replace	Replace	✓
		5211647050	SUPPORT, FR BUMPER LH	1.00	\$86.20	25.00	\$64.65	Replace	Replace	✓
		5212747907	COVER, FR BUMPER RH	1.00	\$31.80	100.00	\$0.00	Replace	Repair	R
		5212847906	COVER, FR BUMPER LH	1.00	\$31.80	100.00	\$0.00	Replace	Repair	R
		5211447190	BRACKET, FR BUMPER	1.00	\$111.80	25.00	\$83.85	Replace	Replace	✓
			NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace	✓
			NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace	✓
		5202147110	REINFORCEMENT FRONT UPPER	0.00	\$773.90	0.00	\$0.00	Replace	Check	X
		5261147140	ABSORBER, FR BUMPER	1.00	\$85.90	25.00	\$64.43	Replace	Replace	✓
		5210347010	EXTENSION SUB-ASSY, LH	0.00	\$129.90	0.00	\$0.00	Replace	Check	X
		5210247020	EXTENSION SUB-ASSY, RH	0.00	\$129.90	0.00	\$0.00	Replace	Check	X
		5213247010	REINFORCEMENT FRONT LOWER	0.00	\$265.90	0.00	\$0.00	Replace	Check	X
		5261847090	ABSORBER, FR BUMPER LOWER	0.00	\$143.60	0.00	\$0.00	Replace	Check	X
		5339547040	SEAL, HOOD TO FR END	0.00	\$55.80	0.00	\$0.00	Replace	Check	X
		7531047060	EMBLEM ASSY FRONT	1.00	\$98.70	25.00	\$74.03	Replace	Replace	✓
		5311247240	GRILLE, RADIATOR	0.00	\$183.90	0.00	\$0.00	Replace	Check	X
		5310147080	GRILLE SUB-ASSY	1.00	\$374.40	25.00	\$280.80	Replace	Replace	✓
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace	✓
		5253550060	RETAINER, FR BUMPER, LH & RH	1.00	\$9.50	25.00	\$7.13	Replace	Replace	✓
		5142047030	COVER ASSY, ENGINE	0.00	\$201.00	0.00	\$0.00	Replace	Check	X
		5141047020	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$511.20	0.00	\$0.00	Replace	Check	X
		5144347020	COVER, ENGINE UNDER SIDE RH	0.00	\$86.20	0.00	\$0.00	Replace	Check	X
		5144447010	COVER, ENGINE UNDER SIDE LH	0.00	\$86.20	0.00	\$0.00	Replace	Check	X
		8121047020	LAMP ASSY, FOG, RH	0.00	\$1,029.90	0.00	\$0.00	Replace	Check	X
		8122047020	LAMP ASSY, FOG, LH	0.00	\$1,029.90	0.00	\$0.00	Replace	Check	X
		8118547691	UNIT, HEADLAMP, LH	1.00	\$2,852.40	10.00	\$2,567.16	Replace	Replace	✓
		8114547691	UNIT, HEADLAMP, RH	1.00	\$2,852.40	10.00	\$2,567.16	Replace	Replace	✓
		8105647690	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	0.00	\$1,039.90	0.00	\$0.00	Replace	Check	X
		8101647690	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$1,039.90	0.00	\$0.00	Replace	Check	X
		5330147110	HOOD SUB-ASSY	1.00	\$1,066.30	25.00	\$799.73	Replace	Replace	✓
		5334147040	INSULATOR, HOOD	1.00	\$444.40	25.00	\$333.30	Replace	Replace	✓
		5328947072	COVER, RADIATOR	0.00	\$254.70	0.00	\$0.00	Replace	Check	X
		9046709050	INSULATOR, HOOD CLIP	6.00	\$3.10	25.00	\$13.95	Replace	Replace	✓
		5341047130	HINGE ASSY, HOOD, RH	1.00	\$63.70	25.00	\$47.78	Replace	Replace	✓
		5342047130	HINGE ASSY, HOOD, LH	1.00	\$63.70	25.00	\$47.78	Replace	Replace	✓
		5363047090	CABLE ASSY, HOOD	0.00	\$59.50	0.00	\$0.00	Replace	Check	X
		5344047060	SUPPORT ASSY, HOOD	0.00	\$47.80	0.00	\$0.00	Replace	Not Given	X
		5345247050	HOLDER, HOOD STAY	0.00	\$18.60	0.00	\$0.00	Replace	Not Given	X
		5360152010C1	LEVER SUB-ASSY, HOOD	0.00	\$80.60	0.00	\$0.00	Replace	Not Given	X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 11/03/2023

User ID : PohSuan

		5357733010	BOLT, HOOD LOCK	0.00	\$11.20	0.00	\$0.00	Replace	Not Given	X
		5351047140	LOCK ASSY, HOOD	1.00	\$146.10	25.00	\$109.58	Replace	Replace	✓
		5321747030	BRACE, HOOD LOCK SUPPORT	1.00	\$84.40	25.00	\$63.30	Replace	Replace	✓
		5110747020	FRONT REINFORCEMENT SIDE RH	0.00	\$144.30	0.00	\$0.00	Replace	Check	X
		5110847020	FRONT REINFORCEMENT SIDE LH	0.00	\$144.30	0.00	\$0.00	Replace	Check	X
		5122847010	FRONT PLATE, FR SUSPENSION	0.00	\$10.50	0.00	\$0.00	Replace	Check	X
		5320547900	SUPPORT S/A UPPER,	1.00	\$408.50	25.00	\$306.38	Replace	Replace	✓
		5320247901	SUPPORT S/A RH	1.00	\$265.10	25.00	\$198.83	Replace	Replace	✓
		5320347901	SUPPORT S/A LH	1.00	\$265.10	25.00	\$198.83	Replace	Replace	✓
		5302847010	SUPPORT SUB-ASSY LOWER	0.00	\$443.50	0.00	\$0.00	Replace	Check	X
		5321347050	SUPPORT, RADIATOR UPPER RH	1.00	\$85.20	25.00	\$63.90	Replace	Replace	✓
		5321447050	SUPPORT, RADIATOR UPPER LH	1.00	\$85.20	25.00	\$63.90	Replace	Replace	✓
		8531947170	WIPER WASHER INLET	0.00	\$72.30	0.00	\$0.00	Replace	Check	X
		8531547160	WIPER WASHER JAR	0.00	\$236.90	0.00	\$0.00	Replace	Check	X
		8533058010	MOTOR AND PUMP ASSY, WINDSHIELD WASHER	0.00	\$316.40	0.00	\$0.00	Replace	Not Given	X
		1659237020	GUIDE, RADIATOR AIR,	1.00	\$122.10	25.00	\$91.58	Replace	Replace	✓
		5315547010	SEAL, RADIATOR GRILLE	0.00	\$45.50	0.00	\$0.00	Replace	Check	X
		5570847230	WIPER GARNISH LOUVER SUB-ASSY	0.00	\$742.70	0.00	\$0.00	Replace	Check	X
		5575347090	WIPER GARNISH SHIELD, COWL WATER , RH	0.00	\$21.30	0.00	\$0.00	Replace	Check	X
		5575447070	WIPER GARNISH SHIELD, COWL WATER , LH	0.00	\$21.30	0.00	\$0.00	Replace	Check	X
		1656237010	SEAL, RADIATOR TO RH	0.00	\$32.10	0.00	\$0.00	Replace	Check	X
		1656337010	SEAL, RADIATOR TO LH	0.00	\$32.10	0.00	\$0.00	Replace	Check	X
		1659337040	GUIDE, RADIATOR AIR , RH	0.00	\$70.70	0.00	\$0.00	Replace	Check	X
		1659537050	GUIDE, RADIATOR AIR , LH	0.00	\$75.90	0.00	\$0.00	Replace	Check	X
		9048040021	GROMMET (FOR RADIATOR LOWER SUPPORT)	0.00	\$16.60	0.00	\$0.00	Replace	Check	X
		1652337010	CUSHION, (FOR RADIATOR UPPER SUPPORT)	0.00	\$12.80	0.00	\$0.00	Replace	Check	X
		1659437010	GUIDE, RADIATOR AIR , UPPER	0.00	\$57.90	0.00	\$0.00	Replace	Check	X
		1640037310	RADIATOR ASSY	0.00	\$2,397.40	0.00	\$0.00	Replace	Check	X
		1636137070	FAN RADIATOR , RH	0.00	\$304.10	0.00	\$0.00	Replace	Check	X
		1636137060	FAN RADIATOR , LH	0.00	\$236.90	0.00	\$0.00	Replace	Check	X
		1671137160	FAN SHROUD RADIATOR	0.00	\$286.80	0.00	\$0.00	Replace	Check	X
		1636336160	MOTOR, COOLING FAN , RH	0.00	\$579.90	0.00	\$0.00	Replace	Check	X
		1636337060	MOTOR, COOLING FAN , LH	0.00	\$708.40	0.00	\$0.00	Replace	Check	X
			COOLANT	0.00	\$12.32	0.00	\$0.00	Replace	Check	X
		8837047092	AIR CON COMPRESSOR ASSY	0.00	\$5,160.70	0.00	\$0.00	Replace	Not Given	X
		8871047160	TUBE & ACCESSORY	0.00	\$751.00	0.00	\$0.00	Replace	Check	X
		8846010320	AIR CON CONDENSER ASSY	0.00	\$1,928.00	0.00	\$0.00	Replace	Check	X
		8870347080	HOSE SUB-ASSY, DISCHARGE	0.00	\$436.20	0.00	\$0.00	Replace	Check	X
		8870447100	HOSE SUB-ASSY, SUCTION	0.00	\$699.80	0.00	\$0.00	Replace	Check	X
		8870747090	PIPE SUB-ASSY, SUCTION	0.00	\$504.10	0.00	\$0.00	Replace	Check	X
		8868847710	BRACKET, COOLER REFRIGERANT HOSE, NO.1	0.00	\$17.20	0.00	\$0.00	Replace	Check	X
		8868847700	BRACKET, COOLER REFRIGERANT HOSE, NO.2	0.00	\$24.50	0.00	\$0.00	Replace	Check	X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 11/03/2023

User ID : PohSuan

		1775337010	INLET, AIR CLEANER, NO 3	1.00	\$45.60	25.00	\$34.20	Replace	Replace	√
		1775237121	INLET, AIR CLEANER, NO 2	1.00	\$122.10	25.00	\$91.58	Replace	Replace	√
		1775137110	INLET, AIR CLEANER, NO 1	1.00	\$168.40	25.00	\$126.30	Replace	Replace	√
		9611110650	CLAMP (FOR AIR CLEANER INLET , NO.1)	0.00	\$9.30	0.00	\$0.00	Replace	Check	X
		1788137330	HOSE, AIR CLEANER , NO.1	0.00	\$80.30	0.00	\$0.00	Replace	Check	X
		9611110650	CLAMP (FOR AIR CLEANER INLET , NO.1)	0.00	\$9.30	0.00	\$0.00	Replace	Check	X
		9611110750	CLAMP (FOR AIR CLEANER HOSE , NO.2)	0.00	\$11.70	0.00	\$0.00	Replace	Check	X
		9090406008	TUBE, UNION (FOR AIR CLEANER HOSE)	0.00	\$25.30	0.00	\$0.00	Replace	Check	X
		1789337130	RESONATOR, INTAKE AIR	0.00	\$16.70	0.00	\$0.00	Replace	Check	X
		9611110430	CLAMP (FOR RESONATOR INTAKE AIR)	0.00	\$9.30	0.00	\$0.00	Replace	Check	X
		1777137020	BRACKET, AIR CLEANER	0.00	\$34.80	0.00	\$0.00	Replace	Check	X
		1770037330	AIR CLEANER ASSY	1.00	\$1,242.00	25.00	\$931.50	Replace	Replace	√
		2880037130	BATTERY	0.00	\$1,584.90	0.00	\$0.00	Replace	Not Given	X
		8211147J21	WIRE, ENGINE ROOM MAIN	0.00	\$7,942.90	0.00	\$0.00	Replace	Not Given	X
		8212347060	WIRE, ENGINE, NO.3	0.00	\$335.10	0.00	\$0.00	Replace	Not Given	X
		821H247010	WIRE, AIR CONDITIONER	0.00	\$576.30	0.00	\$0.00	Replace	Not Given	X
		5380147080	FENDER SUB-ASSY, FR , RH	1.00	\$1,060.70	25.00	\$795.53	Replace	Replace	√
		7537447140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$59.10	25.00	\$44.33	Replace	Replace	√
		5387547070	LINER, FR FENDER, RH	0.00	\$223.50	0.00	\$0.00	Replace	Check	X
		5385147061	PAD, FR WHEEL RH	0.00	\$65.00	0.00	\$0.00	Replace	Check	X
		5380247100	FENDER SUB-ASSY, FR , LH	1.00	\$1,060.70	25.00	\$795.53	Replace	Replace	√
		7537447140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$59.10	25.00	\$44.33	Replace	Replace	√
		5387647110	LINER, FR FENDER, LH	0.00	\$219.10	0.00	\$0.00	Replace	Check	X
		5385247041	PAD, FR WHEEL LH	0.00	\$65.00	0.00	\$0.00	Replace	Check	X
		6700247162	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,407.80	100.00	\$0.00	Replace	Repair	R
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	√
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.18	Replace	Replace	√
		5202347030	REAR BUMPER REINFORCEMENT	1.00	\$360.10	25.00	\$270.08	Replace	Replace	√
		5246247030	PAD, RR BUMPER, RH & LH , 1	2.00	\$4.30	25.00	\$6.45	Replace	Replace	√
		5246247020	PAD, RR BUMPER, RH & LH , 2	2.00	\$4.30	25.00	\$6.45	Replace	Replace	√
		5246247010	PAD, RR BUMPER, RH & LH , 3	2.00	\$4.30	25.00	\$6.45	Replace	Replace	√
		5246147010	PAD, RR BUMPER, CTR	1.00	\$2.50	25.00	\$1.88	Replace	Replace	√
		5219147030	SEAL, RR BUMPER ARM, RH & LH	1.00	\$12.30	25.00	\$9.23	Replace	Replace	√
		5259968030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.80	0.00	\$0.00	Replace	Check	X
		5257547040	RETAINER, RR BUMPER, RH	0.00	\$127.40	0.00	\$0.00	Replace	Check	X
		5257647040	RETAINER, RR BUMPER, LH	1.00	\$127.40	25.00	\$95.55	Replace	Replace	√
		5259247040	SEAL, RR BUMPER , LH	0.00	\$95.50	0.00	\$0.00	Replace	Check	X
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace	√
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$623.50	25.00	\$467.63	Replace	Replace	√
		5256647900	FILLER, RR BUMPER , LH	1.00	\$168.60	25.00	\$126.45	Replace	Replace	√
		5216947020	COVER, GUARD RR BUMPER LOWER	1.00	\$16.70	25.00	\$12.53	Replace	Replace	√
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	√

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 11/03/2023

User ID : PohSuan

		8999730100	ANTENNA, ELECTRICAL KEY	0.00	\$78.00	0.00	\$0.00	Replace	Check	X
		9018906029	REAR BUMPER GROMMET SCREW	0.00	\$2.20	0.00	\$0.00	Replace	Check	X
		8156147151	LENS & BODY, REAR COMBINATION LAMP , LH	0.00	\$489.00	0.00	\$0.00	Replace	Check	X
		8159147010	LENS & BODY ASSY , RR BUMPER , LH	0.00	\$544.40	0.00	\$0.00	Replace	Check	X
		5839947030	COVER, REAR FLOOR UNDER , LH	0.00	\$261.60	0.00	\$0.00	Replace	Check	X
		5839847050	COVER, REAR FLOOR UNDER , RH	0.00	\$189.20	0.00	\$0.00	Replace	Check	X
		6625947010	COVER, REAR FLOOR UNDER CENTER	0.00	\$249.10	0.00	\$0.00	Replace	Check	X
		6160247160	PANEL SUB-ASSY, FENDER REAR LH	0.00	\$943.10	0.00	\$0.00	Replace	Not Given	X
		6563847060	LINER, REAR FENDER , LH	0.00	\$151.10	0.00	\$0.00	Replace	Check	X
		6700547440	TAIL GATE PANEL SUB-ASSY, BACK DOOR	0.00	\$1,238.40	0.00	\$0.00	Replace	Not Given	X
		6788147050	TAIL GATE WEATHERSTRIP, BACK DOOR	1.00	\$402.50	25.00	\$301.88	Replace	Replace	✓
		7680147110A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$992.30	100.00	\$0.00	Replace	Repair	R
		7544147090	NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT	1.00	\$59.10	25.00	\$44.33	Replace	Replace	✓
		7544247130	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	1.00	\$59.10	25.00	\$44.33	Replace	Replace	✓
			STRIDES LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	✓
		5830747090	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$707.10	0.00	\$0.00	Replace	Check	X
		5831147130	SPARE TYRE PANEL , PAN, REAR FLOOR	0.00	\$630.30	0.00	\$0.00	Replace	Not Given	X
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Check	X
			STICKER PETROL ONLY	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
Total					\$59,853.12		\$13,550.05			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		8846010320	AIR CON CONDENSER ASSY	1.00	\$1,928.00	25.00	\$1,446.00	Replace	Replace
		1640037310	RADIATOR ASSY	1.00	\$2,397.40	25.00	\$1,798.05	Replace	Replace
		8101647690	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	1.00	\$1,039.90	10.00	\$935.91	Replace	Replace
		8105647690	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1.00	\$1,039.90	10.00	\$935.91	Replace	Replace
Total					6,405.20		5,115.87		

	18,665.92	
+	1200.00	
+	1610.00	L/S \$17,200/-
	21,475.92	
	-20%	
	17,180.74	