

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI23000684/DVY3Q2**Date:** 30/01/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000206	
Claimant Vehicle No :	SHD438E	Insured Vehicle No :	SLP134X	
Date of Loss:	22/10/2022	Nature of Claim:	TP	Claim No: M2206338

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD438E	Engine No:	M9R8839C003338
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Chassis No:	VF1ABL15AUC283409
Reg. Date:	27/04/2017 (Man. Year: 2016)	Odometer:	707105 km
Colour:	Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,421.93	3,305.72	10,116.21	75.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,360.00	1,660.00	2,700.00	61.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,781.93	4,965.72	12,816.21	72.07
Approved Total (Overridden) (\$\$)		3,900.00		
(\$\$)	17,781.93	3,900.00	13,881.93	78.07
+ GST 8.00/8.00% (\$\$)	1,422.55	312.00	1,110.55	78.07
Nett Amount (\$\$)	19,204.48	4,212.00	14,992.48	78.07

INSPECTION

Date of Assignment:	20/01/2023		
Date Inspected:	26/10/2022	Inspected At:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	4.0 days		

Adjuster: BRYAN TANI**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Jan 2023)
Parts:	143	RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD438E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL FRT LH	Repair	2,844.66 FL	*- FL
2	1		*DOOR MOULDING FRT LH	Not Necessary	100.50 FL	*- FL
3	1		*DOOR HANDLE OUTER FRT LH	Not Necessary	169.50 FL	*- FL
4	1		*DOOR HANDLE MODULE FRT LH	Not Necessary	133.40 FL	*- FL
5	1		*DOOR REGULATOR FRT LH	Not Necessary	501.40 FL	*- FL
6	1		*DOOR REGULATOR MOTOR FRT LH	Not Necessary	758.10 FL	*- FL
7	1		*DOOR HINGE UPPER FRT LH	Not Necessary	274.50 FL	*- FL
8	1		*DOOR HINGE LOWER FRT LH	Not Necessary	300.55 FL	*- FL
9	1		*DOOR PANEL REAR LH	Dented	2,844.66 FL	*2,844.66 FL
10	1		*DOOR HANDLE OUTER REAR RH	Not Necessary	42.10 FL	*- FL
11	1		*DOOR HANDLE MODULE REAR RH	Not Necessary	133.40 FL	*- FL
12	1		*DOOR REGULATOR REAR LH	Not Necessary	450.60 FL	*- FL
13	1		*DOOR REGULATOR MOTOR REAR LH	Not Necessary	758.10 FL	*- FL
14	1		*DOOR HINGE UPPER REAR LH	Not Necessary	241.60 FL	*- FL
15	1		*DOOR HINGE LOWER REAR LH	Not Necessary	169.90 FL	*- FL
16	1		*BUMPER COVER REAR	Cut	561.70 FL	*561.70 FL
17	1		*BUMPER BRACKET SIDE LH REAR	Not Necessary	80.80 FL	*- FL
18	1		*BUMPER RETAINER LH REAR	Not Necessary	54.20 FL	*- FL
19	1		*ROCKER PANEL OUTER LH	Repair	1,184.99 FL	*- FL
20	1		*FENDER PANEL REAR LH	Repair	1,933.20 FL	*- FL
21	1		*WHEELARCH REAR LH	Not Necessary	275.40 FL	*- FL
22	1		*DOOR TRIM CLIP	Not Necessary	70.00 FS	*- FS
23	1		*DOOR MOULDING CLIP	Not Necessary	70.00 FS	*- FS
24	1		*DOOR STICKER TRANSCAB	Necessary	100.00 FS	*80.00 FS
25	1		*DOOR STICKER 65553333	Necessary	100.00 FS	*80.00 FS
26	1		*DOOR STICKER CLASSIC	Necessary	100.00 FS	*50.00 FS
27	1		*RIM	Serviceable	350.00 FS	*- FS
28	1		*REAR BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
29	1		*FENDER CLIP	Not Necessary	70.00 FS	*- FS
30	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,803.26	3,646.36
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,381.33	340.64
Total Parts (\$\$)	13,421.93	3,305.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	230.00	40.00
2	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	800.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,000.00	700.00
5	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
6	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
Gross Labour Cost (S\$)			4,360.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >