

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD438E

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer:

Date of Registration:

Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AAD2210-**SHD438E**

VF1ABL15AUC283409

200303878K

RENAULT

LATITUDE

20/10/2022

SLP134X/ Tokio

27/04/2017

PART**LIST**

1	DOOR PANEL FRT LH	\$	2,844.66	X
1	DOOR MOULDING FRT LH	\$	100.50	X
1	DOOR HANDLE OUTER FRT LH	\$	169.50	X
1	DOOR HANDLE MODULE FRT LH	\$	133.40	X
1	DOOR REGULATOR FRT LH	\$	501.40	X
1	DOOR REGULATOR MOTOR FRT LH	\$	758.10	X
1	DOOR HINGE UPPER FRT LH	\$	274.50	X
1	DOOR HINGE LOWER FRT LH	\$	300.55	X
1	DOOR PANEL REAR LH	\$	2,844.66	✓
1	DOOR HANDLE OUTER REAR RH	\$	42.10	X
1	DOOR HANDLE MODULE REAR RH	\$	133.40	X
1	DOOR REGULATOR REAR LH	\$	450.60	X
1	DOOR REGULATOR MOTOR REAR LH	\$	758.10	X
1	DOOR HINGE UPPER REAR LH	\$	241.60	X
1	DOOR HINGE LOWER REAR LH	\$	169.90	X
1	BUMPER COVER REAR	\$	561.70	✓
1	BUMPER BRACKET SIDE LH REAR	\$	80.80	X
1	BUMPER RETAINER LH REAR	\$	54.20	X
1	ROCKER PANEL OUTER LH	\$	1,184.99	X
1	FENDER PANEL REAR LH	\$	1,933.20	X
1	WHEELARCH REAR LH	\$	275.40	X
TOTAL		\$	13,813.26	
10%		\$	1,381.33	
		\$	12,431.93	

Special Nett

Trans-cab Auto Services Pte Ltd**AAD2210-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD438E

1 DOOR TRIM CLIP HH	\$	70.00	X
1 DOOR MOULDING CLIP HH	\$	70.00	X
1 DOOR STICKER TRANSCAB HCU	\$	100.00	✓ 80/-
1 DOOR STICKER 65553333 HCU	\$	100.00	✓ 80/-
1 DOOR STICKER CLASSIC HCU	\$	100.00	✓ 50/-
1 RIM SW	\$	350.00	X
1 REAR BUMPER CLIP HCU	\$	65.00	✓ 30/-
1 FENDER CLIP HH	\$	70.00	X
1 FENDER LINER CLIP HH	\$	65.00	X
TOTAL	\$	990.00	

TOTAL PARTS \$ 13,421.93**LABOUR**

To rust-proofing and apply undercoat of the affected areas.	\$	230.00	40/-
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	60/-
Putty and spray painting of the affected portion.	\$	1,400.00	800/-
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,000.00	700/-
To transfer of tire, rim and on wheel balancing.	\$	170.00	60/- HH
To Check Electrical Lighting Concerned.	\$	170.00	HH

To check steering geometry and computer wheel alignment	\$	220.00	60/-
TOTAL	\$	4,360.00	

Over All Total \$ 17,781.93**(LUMPSUM) Repair Days****20 Days**

26/10/2022 @ 1015hr

NA Andu

1/5hr

4 days.

2Kk Andu