



PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857

TEL : 6474 3323 FAX : 6264 6786

EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : 24 BENOI SECTOR
CONTACT NO : 6474 3323
FAX NO : 6264 6786
REFERENCE : PAC/OD/0008/2023/GW
DATE : 18-Jan-23
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

ALLIANZ INSURANCE SINGAPORE PTE LTD

79 Robinson Road

#09-01

Singapore 068897

ATTN: MOTOR CLAIMS DEPT

Tel: 6297 2529 Fax: 6297 1956

OWNER'S NAME : MR CHRISTOPHER COLDWELL RAINS
ADDRESS : 32 A CAIRNHILL ROAD
URBAN RESORT
SINGAPORE 229720
TELEPHONE : HP +65 91822672
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : SP20002751854
VEHICLE NO : **S 1980 CD**
MODEL CODE : A4 SEDAN 1.4 TFSI
MODEL YEAR : 21/12/2016
ENGINE NO : CVN028161
CHASSIS NO : WAUZZZF45HA091037
MILEAGE : -
DATE IN :
ESTIMATED BY : ALLAN WU
ACCIDENT DATE : 17-Jan-23
PLACE OF ACCIDENT : CARPARK OF FORT CANNING



PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857

TEL : 6474 3323 FAX : 6264 6786

EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE S 1980 CD

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N	\$ 150.00	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N	\$ 100.00	
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N	\$ 700.00	
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.		\$ 1,200.00	
5	TO RESPRAY FRONT BUMPER, BONNET AND LHS FRONT FENDER.		\$ 800.00	
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N	\$ 180.00	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 150.00	
TOTAL LABOUR CHARGES		:	\$ 3,280.00	

PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857

TEL : 6474 3323 FAX : 6264 6786

EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. S 1980 CD

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT	
				COST + 10 %
1 FRONT BUMPER	1	\$	2,512.00	
2 FRONT BUMPER FIXING PARTS	1	\$	416.00	
3 FRONT BUMPER SECURING STRIP	1	\$	42.00	
4 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$	269.00	
5 FRONT BUMPER AIR GUIDE - LH	1	\$	75.00	
6 FRONT AIR GUIDE GRILLE - LH	1	\$	159.00	
7 FRONT BUMPER GUIDE SECTION - LH	1	\$	43.00	
8 FRONT BUMPER COVER	1	\$	151.00	
9 SIGN ' CAUTION ' STICKER	1	\$	17.00	
10 AIR CONDITIONER STICKER	1	\$	9.00	
11 FRONT LOCK CARRIER BRACKET	1	\$	163.00	
12 FRONT LOCK CARRIER SUPPORT - LH / RH	2	\$	68.00	
13 POP RIVET	4	\$	4.00	
14 HORN - LH	1	\$	142.00	
15 HORN BRACKET - LH	1	\$	35.00	
16 FRONT FENDER - LH	1	\$	912.00	
17 FRONT FENDER ATTACHMENT PARTS - LH	1	\$	238.00	
18 FRONT FENDER CLOSING ELEMENT	1	\$	86.00	
19 FRONT FENDER BRACKET - LH	1	\$	44.00	
20 FRONT FENDER BRACE - LH	1	\$	140.00	
SUB - TOTAL PARTS CHARGES	:	\$	5,525.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857

TEL : 6474 3323 FAX : 6264 6786

EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. S 1980 CD

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT	
				COST + 10 %
21 FRONT FENDER DEFORMATION - LH	1	\$	59.00	
22 FRONT FENDER BRACKET - LH CENTRE	1	\$	50.00	
23 FRONT WHEEL HOUSING LINER - LH	1	\$	281.00	
24 FRONT FENDER PANEL COVER - LH	1	\$	31.00	
25 FRONT WHEEL SPOILER - LH	1	\$	87.00	
26 FRONT END PLATE- LH	1	\$	42.00	
27 FRONT STONE CHIP GUARD	1	\$	60.00	
28 FRONT FENDER LEDGE COVER - LH	1	\$	37.00	
29 FRONT FENDER LEDGE COVER - LH INNER	1	\$	27.00	
30 LED HEADLIGHT - LH	1	\$	8,787.00	
31 HEADLIGHT POWER MODULE	1	\$	916.00	
32 HEADLIGHT CONTROL UNIT	1	\$	866.00	
33 HEADLIGHT HOSE	1	\$	43.00	
34 LIFT CYLINER FOR HEADLIGHT WASHER SYSTEM	1	\$	24.00	
35 BRACKET FOR LIFT CYLINDER	1	\$	8.00	
36 CORRUGATED PIPE FOR HEADLGHT WASHER SYSTEM	1	\$	111.00	
37 FRONT LOCK CARRIER	1	\$	1,569.00	
38 RADIATOR COOLANT	6	\$	326.00	
39 RADIATOR AIR GUIDE - LH	1	\$	38.00	
40 RADIATOR AIR GUIDE - RH	1	\$	25.00	
SUB - TOTAL PARTS CHARGES	:	\$	13,387.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857

TEL : 6474 3323 FAX : 6264 6786

EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. S 1980 CD

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
21 RADIATOR AIR GUIDE - UPPER	1	\$	25.00	
22 FORNT WHEEL RIM - LH	1	\$	1,080.00	
23 RUBBER VALVE	1	\$	4.00	
24 SUNDRIES	1	\$	500.00	
TOTAL PARTS CHARGES	:	\$	20,521.00	
TOTAL LABOUR CHARGES	:	\$	3,280.00	
GRAND TOTAL	:	\$	23,801.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



24 BENOI SECTOR, SINGAPORE 629857

TEL : 6474 3323 FAX : 6264 6786

EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6474 3323 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOCARE CENTRE

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT