

Borneo Motors**TOYOTA**

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no.: 6631 1188

26/1

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Ms Koh Chern Chern 27 West Coast Rise #03-10 Singapore 127470 Mobile: 90409529
	Document No. 0	
	Document Date 20/01/2023	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2014	ZGE20R	HPXNP S4	16/01/2015	SKR0805U	0	19767	65DS/SKR0805U
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDGG20W40J002063	2ZR1493010	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS. : CHINA TAIPING INS. T/P VEH. : YQ7556G ACC DATE : 19.01.23 BY : <i>UKK</i>				50 100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00
3	L	BP-LPO SUPPLY REGN PLATE (PO#)				80.00
4	B	BP-LAB2 RESET AND REPROGRAMME ECU.				198.00
5	B	BP-LAB2 CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.				198.00
6	B	BP-LAB2 DRILL HOLE TO INSTALL REVERSE SENSOR.				198.00
7	B	BP-LAB2 REMOVE TAIL-GATE COMPONENTS TO TRANSFER ONTO NEW DOOR.				396.00
8	B	BP-LAB2 CLEAN UP BOOT INTERIOR BROKEN GLASSES.				198.00
9	B	BP-LAB2 REPLACE REAR W/SCREEN GLASS.				495.00
10	S	BP-SUBLET SUPPLY AND INSTALL REAR W/SCREEN SOLAR FILM.				350.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Ms Koh Chern Chern 27 West Coast Rise #03-10 Singapore 127470 Mobile: 90409529
	Document No. 0	
	Document Date 20/01/2023	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2014	ZGE20R	HPXNP S4	16/01/2015	SKR0805U	0	19767	65DS/SKR0805U

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDGG20W40J002063	2ZR1493010	60	Francis Cher T S	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN REAR BUMPER, TAIL-GATE, TAIL-LAMP PANEL AND AFFECTED PORTION OF CAR. <i>@ 792X4</i>				<i>3168</i> 4782.00
12	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR. <i>656X4</i>				<i>2624</i> 3936.00
13	1	T52159-68907 PLATE, RR BUMPER <i>de</i>	1.00	710.20		710.20
14	2	T52155-68030 SUPPORT, RR BUMPER <i>? xan</i>	1.00	117.20		117.20
15	3	T52156-68030 SUPPORT, RR BUMPER <i>? xan</i>	1.00	117.20		117.20
16	4	T52575-68020 RETAINER, RR BUMPER <i>? xan</i>	1.00	55.30		55.30
17	5	T52576-68020 RETAINER, RR BUMPER <i>? xan</i>	1.00	55.30		55.30
18	6	S52161-0K040 PIECE, RR BUMPER <i>an</i>	4.00	4.90		19.60
19	7	T58307-68031 PANEL SUB-ASSY, BODY <i>bt-phoh?</i>	1.00	644.90		644.90
20	8	T52181-68010 ARM, RR BUMPER <i>? xan</i>	2.00	64.60		129.20
21	9	T67935-68020 BO PLATE, BACK DOOR <i>? xan</i>	1.00	358.30		358.30
22	0	T67005-68041 PANEL SUB-ASSY, BACK <i>bt</i>	1.00	1775.90		1775.90
23	1	T68105-68071 GLASS SUB-ASSY, BACK <i>bs</i>	1.00	1279.30		1279.30
24	2	T21000-20 SIKI 182010 SIKI TACK GO! (BLA <i>ne</i>	2.00	108.00		216.00
25	3	T21000-22 SIKI 207. G+P ADHESIVE PRIMER <i>ne</i>	1.00	200.00		200.00
26	4	T76811-68130 GARNISH, BACK DOOR, <i>ca</i>	1.00	348.60		348.60

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due
<i>[Signature]</i>			

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
THIRD PARTY CLAIM				S1000020 / TPCLAIM		Ms Koh Chern Chern 27 West Coast Rise #03-10 Singapore 127470 Mobile: 90409529			
				Document No.					
				0					
				Document Date					
				20/01/2023					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2014	ZGE20R	HPXNP S4	16/01/2015	SKR0805U	0	19767	65DS/SKR0805U		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTDGG20W40J002063		2ZR1493010	60	Francis Cher T S	--/--/----		0.00	--/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
27	5	T81581-68020 LENS & BODY, RR <i>ca</i>			1.00	353.40		353.40	
28	6	T81591-68020 LENS & BODY, RR <i>ca</i>			1.00	353.40		353.40	
29	7	T81551-68062 LENS & BODY, RR <i>2 x an</i>			1.00	425.90		425.90	
30	8	T81561-68062 LENS & BODY, RR <i>? x an</i>			1.00	425.90		425.90	
31	9	T90975-02086 EMBLEM, SYMBOL <i>an</i>			1.00	72.20		72.20	
32	0	T75444-68010 PLATE, LUGGAGE COMPT <i>an</i>			1.00	49.40		49.40	
33	1	SPZ061-12010 27 4T8 SENSOR <i>an X an</i>			1.00	151.60		151.60	
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____ <i>Same</i> <i>4p 90000068</i> <i>9 days</i> <i>26/01/23 @ 1420</i> <i>Resy before print</i>									
For & on behalf of				Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd								18,859.80	
				Please acknowledge receipt of vehicle		Parts		7,858.80	
						Labour		10,571.00	
						Sublet		430.00	
						Lubrication/Fluid		0.00	
						Others		0.00	
						Total		18,859.80	
						GST 8.00%		1,508.78	
						Less		0.00	
						Amount Due		20,368.58	

Customer Copy



: 196700086Z
: MR-8500000-9
DAN CRESCENT
JRE 128462, Tel no.: 6631 1188

TAX INVOICE

Account Details		Account No.	Customer Details	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Ms Koh Chern Chern	
		Document No. 38069642	27 West Coast Rise #03-10 Singapore 127470	
		Document Date 21/02/2023	Mobile: 90409529	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2014	ZGE20R	HPXNP S4	16/01/2015	SKR0805U	106001	19767	65DS/SKR0805U

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDGG20W40J002063	2ZR1493010	60	Francis Cher T S	30/01/2023 14.51	21/02/2023 16.35

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN REAR BUMPER, TAIL-GATE, TAIL-LAMP PANEL AND AFFECTED PORTION OF CAR.				3168.00
11	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				2624.00
12	1	T52159-68907 PLATE,RR BUMPER	1.00	710.20		710.20
13	2	S52161-0K040 PIECE, RR BUMPER	4.00	4.90		19.60
14	3	T58307-68031 PANEL SUB-ASSY, BODY	1.00	644.90		644.90
15	4	T67005-68041 PANEL SUB-ASSY, BACK	1.00	1775.90		1775.90
16	5	T68105-68071 GLASS SUB-ASSY, BACK	1.00	1279.30		1279.30
17	6	T21000-20 SIKI 182010 SIKI TACK GO! (BLA	2.00	108.00		216.00
18	7	T21000-22 SIKI 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00
19	8	T76811-68130 GARNISH, BACK DOOR,	1.00	348.60		348.60
20	9	T81581-68020 LENS & BODY, RR	1.00	353.40		353.40
21	0	T81591-68020 LENS & BODY, RR	1.00	353.40		353.40
22	1	T90975-02086 EMBLEM, SYMBOL	1.00	72.20		72.20
23	2	T75444-68010 PLATE, LUGGAGE COMPT	1.00	49.40		49.40
24	3	SPC507-47006 4W4 BACK SENSOR DARK SHERRY MM ca } suppl	1.00	251.40		251.40
25	4	T89997-30070 ANTENNA, ELECTRICAL ca	1.00	231.00		231.00

For & on behalf of		Customer's Signature	Charge Summary	Total
orneo Motors (Singapore) Pte Ltd				14,480.30
		Please acknowledge receipt of vehicle	Parts 6,505.30	GST 8.00% 1,158.42
			Labour 7,625.00	
			Sublet 350.00	
			Lubrication/Fluid 0.00	Less 0.00
			Others 0.00	Amount Due 15,638.72