

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
 Kaki Bukit Autohub. Singapore 417921
 Tel No. : 67461515 / 67471787 Fax No. : 67485015
 Website : www.successunited.com.sg
 Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
 AIG Building
 78 Shenton Way, #07-16
 Singapore 079120
 Attention : Motor Claim Department
 Contact : 64191053 Fax No. : 68357416

Xiao Tang

Estimate : TP23-009

Date : 14/01/2023
 Vehicle Num. : SMJ23C
 Make/Model : BMW 220i-2015
 Chassis/Eng# : WBA1L72050V491067/B2941176N20B20
 Accident Date : 02/01/2023
 Claim No. :
 Reference :
 Policy No. : (23/03/2023)

S/N	Quantity	Particular	Unit Price	Amount SS
LIST ITEMS :				
1.	1 pc	Frt Bumper Assy <i>Repair</i>		1,530.60 <i>+</i>
2.	10 pcs	Frt Bumper Clips <i>new</i>	5.00	50.00 <i>30</i>
3.	1 pc	Frt No. Plate Garnish Base <i>Delend</i>		108.95 <i>+</i>
4.	2 pcs	Frt PDC Sensor <i>He n</i>	398.35	796.70 <i>+</i>
5.	1 pc	Frt Bumper Lower Air Grille <i>new</i>		253.10 <i>+</i>
6.	1 pc	Frt Grille Assy RH <i>new</i>		152.55 <i>+</i>
7.	1 pc	Aircon Temperature Sensor <i>new</i>		121.95 <i>+</i>
List TotalSS :				3,013.85
5.00% Discount SS :				150.69
				2,863.16
SPECIAL NETT ITEMS :				
1.	1 set	Frt No. Plate w/frame <i>Revised</i>	45	45.00 <i>✓</i>
Special Nett Total SS :				45.00
LABOUR :				
To remove, rearrange electrical wirings, check lighting				80.00 <i>30</i>
To check aircon sensor & temperature sensor. *Owner complaint aircon not cold.			480	250.00 <i>+</i>
To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident				500.00 <i>200</i>
To putty and respray painting on frt bumper.				450.00 <i>250</i>
Labour Total SS :				1,280.00

Total SS : 4,188.16
 =====

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SUCCESS UNITED PTE LTD

total 28735
(P/P) P/P 14/01/23.
Adrian Lj
02 days