

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 10.01.2023

TO : CHINA TAIPING MOTOR CLAIMS I
VEHICLE NO : EQ3223E
MODEL : MERCEDES C180
DATE OF ACCIDENT : 09.01.2023
TIME OF ACCIDENT : 07:45 HOURS

Xiao Tony
WDD2050402 R212958

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Delnd</i>	1	\$ 2,191.00	\$ 2,191.00 <i>1890.</i>
2	REAR BUMPER CENTRE FRAME <i>Delnd</i>	1	\$ 232.00	\$ 232.00
3	REAR BUMPER TOWING COVER <i>new</i>	1	\$ 88.00	\$ 88.00
4	REAR BUMPER EXHAUST COVER GARNISH <i>new</i>	1	\$ 138.00	\$ 138.00
5	REAR BUMPER REVERSE SENSOR <i>2 pieces</i>	4	\$ 265.00	\$ 1,060.00 <i>530.</i>
6	REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	6	\$ 67.00	\$ 402.00 <i>150.</i>
7	REAR BUMPER REVERSE SENSOR WIRE HARNESS <i>lit</i>	1	\$ 798.00	\$ 798.00 <i>435</i>
8	REAR BUMPER CENTER UPPER BRACKET <i>lit</i>	2	\$ 78.00	\$ 156.00
9	REAR BUMPER BOTTOM CENTER GARNISH <i>Delnd</i>	1	\$ 185.00	\$ 185.00
10	REAR BUMPER LOWER GARNISH <i>Delnd</i>	1	\$ 285.00	\$ 285.00
11	REAR BUMPER LOWER GARNISH CHROME <i>lit</i>	1	\$ 346.00	\$ 346.00
12	REAR BUMPER UPPER CORNER BRACKET <i>new</i>	2	\$ 179.00	\$ 358.00
13	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 74.00	\$ 148.00
14	REAR BUMPER LOWER BRACKET (CENTER) <i>new</i>	2	\$ 65.00	\$ 130.00
15	REAR BUMPER SMART SENSOR CONTROL UNIT <i>new</i>	1	\$ 374.00	\$ 374.00
16	REAR BUMPER SMART SENSOR <i>new</i>	1	\$ 169.00	\$ 169.00
17	REAR BUMPER SMART SENSOR C/W CABLE <i>new</i>	1	\$ 279.00	\$ 279.00
18	REAR BUMPER SMART SENSOR WIRE HARNESS <i>new</i>	1	\$ 485.20	\$ 485.20
19	REAR BUMPER REINFORCEMENT <i>Delnd</i>	1	\$ 658.00	\$ 658.00
20	REAR FENDER COWLING <i>2 pc</i>	2	\$ 198.00	\$ 396.00
21	REAR FENDER INNER TRIM <i>new</i>	2	\$ 425.00	\$ 850.00
22	REAR FLOOR WELL PANEL	1	\$ 663.00	\$ 663.00

TO : CHINA TAIPING MOTOR CLAIMS I
 VEHICLE NO : EQ3223E
 MODEL : MERCEDES C180
 DATE OF ACCIDENT : 09.01.2023
 TIME OF ACCIDENT : 07:45 HOURS

23	TAILLAMP <i>new</i>	2	\$ 762.00	\$ 1,524.00	+
24	BOOTLID WEATHER STRIP <i>new</i>	1	\$ 189.00	\$ 189.00	+
25	REAR END PANEL <i>Repair</i>	1	\$ 1,460.00	\$ 1,460.00	+
26	REAR END PANEL INNER GARNISH <i>new</i>	1	\$ 285.00	\$ 285.00	+

TOTAL PRICE \$ 13,849.20
 LESS 10% \$ 1,384.92
SUB TOTAL PRICE \$ 12,464.28

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	30
2	REAR BUMPER BOTTOM CENTER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	20
3	REAR BUMPER LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	20
4	REAR BUMPER EXHAUST COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
5	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
6	REAR FENDER DRAIN GARNISH CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
7	REAR FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
8	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
9	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00	+
10	REAR END PANEL INNER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
11	REAR FLOOR UNDER SIDE GARNISH CLIP RH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+

TOTAL \$ 760.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	400
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	300
3	TUFF COAT	\$ 350.00	40
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 380.00	x

TO : CHINA TAIPING MOTOR CLAIMS I
VEHICLE NO : EQ3223E
MODEL : MERCEDES C180
DATE OF ACCIDENT : 09.01.2023
TIME OF ACCIDENT : 07:45 HOURS

7	CONDUCT WATER LEAKAGE TEST	\$ 100.00	x
9	REMOVE AND REFIX AND RECODING SMART SENSOR	\$ 1,200.00	280.
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 650.00	x

TOTAL \$ 5,460.00

TOTAL PARTS COST : \$ 13,224.28
TOTAL LABOUR COST : \$ 5,460.00
TOTAL REPAIR COST : \$ 18,684.28

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
L/S 11/01/23.

03 Days.

total: 6240.10

L/S: SK

SK