



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SDG19M

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

WIP No
Reg No/Reg Date
Date In/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Vehicle & Document Information

62486
SDG19M / 29/06/2022
SDG19M
W1K2130612B048480
25693030488686
MB/ 53 4MATIC+ SEDAN
021 197 Obsidian Bl/ 048 898 Titanium Gr

Account No	Terms	Date/Time Printed	CSE	Operator
CO00668	Credit	19/01/2023/ 15:25	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
THIS IS NOT AN OFFICIAL TAX INVOICE <i>Resur</i> <i>Hp 90000018</i> <i>3 days</i> <i>10/02/23 101620</i> <i>Resur before print</i>				
REQUEST Customer Request BRNSUN POLICY NO/ACC DATE : 7220071855 // 17-1-2023 DRIVE IN/TP VEH NUMBER : 18-1-2023 // SJT6950U - CHINA TAIPING DATE IN/DATE SURVEY: DIRECT SETTLEMENT BY: BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH. BPIRES RESPRAY FRONT BUMPER BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT BPILAB TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NETT LH/HEADLAMP UNIT <i>cut</i> LH/FRONT BUMPER TRIM STRIP <i>cut</i> RIVET <i>cut</i> LH/SIDE FRONT BUMPER COVER <i>cut</i> FRONT AMG BUMPER <i>cut</i>				960 1440.00 ✓ 800 960.00 ✓ 0.10 380.00 ✓ 120.00 ✓ 1.00 3677.73 00.00 3677.73 ✓ 1.00 140.01 00.00 140.01 ✓ 12.00 5.34 00.00 64.08 ✓ 1.00 139.86 00.00 139.86 ✓ 1.00 2091.76 00.00 2091.76 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirmed & accepted by

Acknowledged by Repairer
Signature:
Date:

Nett 9,013.44
8% GST on 9013.44 721.08

Total Payable 9,734.52

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of removing the rubber seal or other repairs requiring removal of the windscreen.

Pandan Lagoon Service Center
118 Pandan Lagoon
Singapore 128376
Tel: 6778 8349
Fax: 6778 8320



Mercedes-Benz

SUPPLEMENTARY

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SDG19M

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

WIP No
Reg No/Reg Date
Date In/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Vehicle & Document Information
62486
SDG19M / 29/06/2022
20/03/2023/ 6140
W1K2130612B0484801
25693030488686
MB/ 53 4MATIC+ SEDAN
021 197 Obsidian B1/ 048 898 Titanium Gr

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WC000668	Credit	26/03/2023/ 09:41	CH	371 / Go Chee Han				

M. BPNSUN
POLICY NO/ACC DATE : 7220071855 // 17-1-2023
DRIVE IN/TP VEH NUMBER : 18-1-2023 // SJT6950U - CHINA TAIPING
DATE IN/DATE SURVEY: 10-2-2023 // RASUL - LKK
DIRECT SETTLEMENT BY: 1-2-2023 // IRENE TAY - CHINA TAIPING
X BLACK BLIND RIVET *nu*

10.00 2.36 00.00 23.60

Confirmed & accepted by

8% GST on Nett 23.60 1.89

Total Payable 25.49

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG