



Mercedes-Benz

Finalization

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SDG19M

CHINA TAIPING INSURANCE (S) PTE  
LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

## Vehicle &amp; Document Information

WIP No 62486  
Reg No/Reg Date SDG19M / 29/06/2022  
Date In/Mileage 20/03/2023/ 6140  
Chassis No W1K2130612B0484801  
Engine No 25693030488686  
Make/Model MB/ 53 4MATIC+ SEDAN  
Colour/Trim 021 197 Obsidian Bl/ 048 898 Titanium Gr

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	26/03/2023/ 09:41	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST				
Customer Request				
M BPNSUN				
POLICY NO/ACC DATE : 7220071855 // 17-1-2023				
DRIVE IN/TP VEH NUMBER : 18-1-2023 // SJT6950U - CHINA TAIPING				
DATE IN/DATE SURVEY: 10-2-2023 // RASUL - LKK				
DIRECT SETTLEMENT BY: 1-2-2023 // IRENE TAY - CHINA TAIPING				
A BPILAB				960.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				
A BPIRES			0.05	800.00
RESPRAY FRONT BUMPER				
A BPILAB			0.10	380.00
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				
A BPILAB				120.00
TO REMOVE, REPLACE HEADLAMP WITH FOCUS , NETT				
X LH/HEADLAMP UNIT	1.00	3677.73	00.00	3677.73
X LH/FRONT BUMPER TRIM STRIP	1.00	140.01	00.00	140.01
X RIVET	12.00	5.34	00.00	64.08
X LH/SIDE FRONT BUMPER COVER	1.00	139.86	00.00	139.86
X FRONT AMG BUMPER	1.00	2091.76	00.00	2091.76
X BLACK BLIND RIVET	10.00	2.36	00.00	23.60

Confirmed &amp; accepted by

8% GST on **Nett** 8,397.04  
8397.04 671.76

**Total Payable** 9,068.80

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6298 1818  
Fax: 6779 5383  
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

**SUPPLEMENTARY**

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

**ESTIMATE FOR SDG19M**

CHINA TAIPING INSURANCE (S) PTE  
LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

Vehicle & Document Information

WIP No **62486**  
Reg No/Reg Date **SDG19M / 29/06/2022**  
Date In/Mileage **20/03/2023/ 6140**  
Chassis No **W1K2130612B0484801**  
Engine No **25693030488686**  
Make/Model **MB/ 53 4MATIC+ SEDAN**  
Colour/Trim **021 197 Obsidian Bl/ 048 898 Titanium Gr**

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WC000668	Credit	26/03/2023/ 09:41	CH	371 / Go Chee Han					
<p>M BPNSUN POLICY NO/ACC DATE : 7220071855 // 17-1-2023 DRIVE IN/TP VEH NUMBER : 18-1-2023 // SJT6950U - CHINA TAIPING DATE IN/DATE SURVEY: 10-2-2023 // RASUL - LKK DIRECT SETTLEMENT BY: 1-2-2023 // IRENE TAY - CHINA TAIPING X BLACK BLIND RIVET</p>									
						10.00	2.36	00.00	23.60

Confirmed & accepted by

8% GST on **Nett 23.60**  
**1.89**  
**Total Payable 25.49**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6298 1818  
Fax: 6779 5383  
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG