



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2304256

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 05/07/2023
Reference CC6/CTI23000715/Aya3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SKU 3741J
Insured Veh. SJK 5316E
Claim No. SNM23D200027/C02
Policy No. DMPCSNW00237692202
Accident Date 31/12/2022
Inspection Date 03/01/2023

Description	Total
Survey Inspection	280.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	280.00
GST (8%)	22.40
Grand Total	302.40

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI23000715/Aya3q2 Date: 05/07/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJK 5316E	Veh. Inspected	SKU 3741J	
Policy No.	DMPCSNW00237692202	Coverage (\$)	0.00	
Claim No.	SNM23D200027/C02	Excess (\$)	0.00	
Assign From		Assign Date	03/01/2023	
2. Vehicle Particulars & Condition				
Make & Model	mitsubishi LANCER EX	c.c	1590	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JMYSRCY1AFU004952	Colour	SILVER	
Odometer	105434 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/12/2022	Inspection Date	03/01/2023	
Survey held at	XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			14 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 3741J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOT LID	DISTORTED	698.50	698.50
2	BOOT LID LAMP @\$405.60	CUT	811.20	624.00
2	BOOT LID LAMP INNER SEALER @\$38.00	NOT NECESSARY	76.00	-
1	BOOT LID THIRD BRAK LAMP	CRACKED	165.90	165.90
1	BOOT LID KEYLESS DETECTOR SENSOR	DAMAGED	369.00	145.00
1	BOOT LID KEYLESS BUZZER	DAMAGED	194.00	194.00
1	BOOT LID LOGO	NECESSARY	85.60	85.60
1	BOOT LID EMBLEM 'LANCER'	NECESSARY	83.20	83.20
1	BOOT LID EMBLEM 'MIVEC'	NECESSARY	78.90	78.90
1	BOOT LID INSULATOR	NOT NECESSARY	315.90	-
2	BOOT LID HINGE @\$95.60	NOT NECESSARY	191.20	-
1	BOOT LID TOP LOCK	DAMAGED	145.30	145.30
1	BOOT LID OUTER LOCK SWITCH BUTTON	NOT NECESSARY	165.80	-
1	BOOT LID LOWER LOCK	NOT NECESSARY	35.80	-
1	BOOT LID WEATHERSTRIP	CUT	175.80	175.80
1	BOOT LID DETECTOR SENSOR	NOT NECESSARY	185.90	-
2	TAILAMP @\$425.70	CRACKED	851.40	760.00
2	TAILAMP PANEL @\$198.50	TO REPAIR SEE LABOUR	397.00	-
1	REAR BUMPER	DISTORTED	845.20	845.20
1	REAR BUMPER TOWING COVER	DAMAGED	39.70	39.70
2	REAR BUMPER REFLECTOR @\$45.80	CRACKED	91.60	91.60
1	REAR BUMPER REINFORCEMENT	BENT	345.20	345.20
2	REAR BUMPER SIDE RETAINER @\$65.30	DAMAGED	130.60	130.60
2	REAR NUMBER PLATE LAMP @\$60.80	DAMAGED	121.60	121.60
2	REAR NUMBER PLATE LAMP BRACKET @\$45.30	DAMAGED	90.60	90.60
1	REAR NUMBER PLATE LAMP WIRE HARNESS	NOT NECESSARY	285.30	-
2	REAR FENDER @\$785.90	NOT NECESSARY	1,571.80	-
1	REAR FENDER AIR VENT	NOT NECESSARY	69.80	-
2	REAR FENDER INNER COWLING @\$65.30	NOT NECESSARY	130.60	-
2	REAR FENDER INNER TRIM @\$328.70	TORN	657.40	580.00

Report Ref No. CC6/CTI23000715/Aya3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL	DISTORTED	598.70	598.70
1	REAR END PANEL TOP GARNISH	DEFORMED	152.90	152.90
1	REAR END PANEL BRACKET	BENT	198.70	198.70
1	REAR FLOOR PANEL	BUCKLED	852.30	852.30
1	REAR FLOOR PANEL TOP BOARD	TORN	185.90	185.90
1	REAR EXHAUST PIPE	BENT	859.60	859.60
1	REAR EXHAUST PIPE GARNISH	NOT NECESSARY	98.50	-
2	REAR EXHAUST MOUNTING @\$45.20	NOT NECESSARY	90.40	-
1	REAR EXHAUST INSULATOR	NOT NECESSARY	89.00	-
1	REAR EXHAUST GASKET	NOT NECESSARY	60.00	-
1	FRONT BUMPER	DEFORMED	898.00	898.00
1	FRONT BUMPER GRILLE LOGO	NECESSARY	85.30	85.30
1	FRONT BUMPER UPPER GRILLE	CRACKED	369.00	369.00
1	FRONT BUMPER LOWER GRILLE	DEFORMED	168.00	168.00
2	FRONT BUMPER FOG LAMP COVER @\$68.90	NOT NECESSARY	137.80	-
1	FRONT BUMPER TOP RUBBER	NOT NECESSARY	75.80	-
1	FRONT BUMPER TOWING COVER	NOT NECESSARY	38.20	-
2	FRONT NUMBER SIDE RETAINER @\$58.90	DAMAGED	117.80	117.80
1	FRONT BUMPER REINFORCEMENT	BENT	469.00	326.00
2	FRONT BUMPER BRACKET @\$38.90	NOT NECESSARY	77.80	-
1	FRONT BUMPER TOP BEAM	BENT	135.00	135.00
1	FRONT BUMPER UNDER COVER GARNISH	TORN	198.00	198.00
2	FRONT ENGINE SIDE UNDER COVER GARNISH @\$78.00	NOT NECESSARY	156.00	-
2	FRONT FENDER @\$698.00	NOT NECESSARY	1,396.00	-
2	FRONT FENDER COWLING @\$136.20	NOT NECESSARY	272.40	-
1	BONNET	TO REPAIR SEE LABOUR	899.00	-
2	BONNET STOPPER @\$34.00	NOT NECESSARY	68.00	-
2	BONNET WEATHERSTRIP (INNER) @\$39.00	NOT NECESSARY	78.00	-
1	BONNET LOCK	NOT NECESSARY	158.20	-
2	BONNET HINGE @\$65.30	NOT NECESSARY	130.60	-
2	HEADLAMP @\$897.60	CRACKED	1,795.20	1,795.20
2	HEADLAMP PANEL @\$179.00	TO REPAIR SEE LABOUR	358.00	-

Report Ref No. CC6/CTI23000715/Aya3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	HEAD LAMP LOWER CLIPS @\$41.00	NOT NECESSARY	82.00	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	489.50	-
1	FRONT SUPPORT PANEL TOP COVER GARNISH	DEFORMED	149.20	149.20
2	HORN @\$86.30	NOT NECESSARY	172.60	-
1	WIPER WASHER TANK	NOT NECESSARY	110.00	-
1	RADIATOR	NOT NECESSARY	1,116.00	-
1	RADIATOR TOP BRACKET @\$25.90	NOT NECESSARY	51.80	-
2	RADIATOR MOUNTING @\$28.90	NOT NECESSARY	57.80	-
1	RADIATOR FAN COWLING	NOT NECESSARY	395.00	-
1	RADIATOR UPPER HOSE	NOT NECESSARY	68.00	-
1	RADIATOR LOWER HOSE	NOT NECESSARY	79.00	-
1	AIRCON CONDENSER	WARPED	1,023.00	1,023.00
1	AIR CON HOSE (PRESSURE)	NOT NECESSARY	397.00	-
1	AIR CON HOSE (SUCTION)	NOT NECESSARY	359.00	-
	LESS 10% DISCOUNT		-2,522.28	-1,351.33
			22,700.52	12,161.97
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	MISSING	50.00	50.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	30.00
2	SET TAIL LAMP CLIP @\$30.00 (SN)	NECESSARY	60.00	20.00
1	BOOT LID SEALANT (SN)	NOT NECESSARY	80.00	-
1	SET BOOT LID INSULATOR CLIP (SN)	NOT NECESSARY	50.00	-
1	BOOT LID EMBLEM 'C&C' (SPECIAL TYPE) (SN)	NECESSARY	120.00	50.00
1	REAR EXHAUST CHROME GARNISH (SPECIAL TYPE) (SN)	NOT NECESSARY	280.00	-
2	SET REAR FENDER INNER COWLING CLIP @\$30.00 (SN)	NOT NECESSARY	60.00	-
2	SET REAR FENDER INNER TRIM CLIPS @\$30.00 (SN)	NECESSARY	60.00	60.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	30.00	20.00
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	150.00	60.00
1	FLOOR PANEL INSULATION PADS (SN)	NECESSARY	180.00	180.00
1	REVERSE CAMERA (SN)	DAMAGED	450.00	380.00
1	REVERSE SENSOR (SN)	DAMAGED	250.00	200.00

Report Ref No. CC6/CTI23000715/Aya3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE (SN)	BENT	50.00	50.00
1	FRONT NUMBER PLATE HOLDER (SN)	DEFORMED	85.00	85.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	30.00	30.00
1	SET FRONT BUMPER UNDER COVER GARNISH CLIP (SN)	NECESSARY	30.00	30.00
1	SET FRONT ENGINE SIDE UNDER COVER GARNISH RH CLIP (SN)	NOT NECESSARY	30.00	-
1	SET FRONT FENDER CORNER COVER GARNISH CLIP (SN)	NOT NECESSARY	40.00	-
2	SET FRONT FENDER COWLING CLIP @\$30.00 (SN)	NOT NECESSARY	60.00	-
1	FRONT WINDSCREEN SOLAR TINTED FILM (SN)	NOT NECESSARY	480.00	-
1	FRONT SUPPORT PANEL SEALANT (SN)	NOT NECESSARY	150.00	-
1	SET FRONT SUPPORT PANEL TOP COVER GARNISH CLIP (SN)	NECESSARY	40.00	20.00
			2,865.00	1,265.00
	LABOUR			
	TO PANEL BEAT ,WELD ,CUT ,GRAZE ,ADJUST AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF TAILAMP PANEL .		2,200.00	1,200.00
	TO PUTTY ,SPRAY PAINT POLISH ,WAX.		2,000.00	1,000.00
	TO SPRAY TUFF COAT.		250.00	80.00
	WIRING ,BULB CHECKING .		120.00	30.00
	REMOVE AND REFIX UPHOLSTERY TO FACILITATE REPAIR .		350.00	60.00
	CONDUCT WATER LEAKAGE TEST .	NOT NECESSARY	80.00	-
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		100.00	50.00
	TO REPAIR AND STRAIGHTEN REAR CHASSIS MEMBER .	NOT NECESSARY	350.00	-
	REMOVE AND REFIX REVERSE CAMERA.		150.00	50.00
	TRANSFER BOOTLID MECHANISM .		120.00	60.00
	REMOVE AND REFIX REAR EXHAUST PIPE .		120.00	50.00
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
	TO PANEL BEAT ,WELD ,CUT ADJUST PARTS.INCLUSIVE OF THE REPAIR OF BONNET,HEADLAMP PANEL AND FRONT SUPPORT PANEL .		1,600.00	500.00
	TO PUTTY, APPLY SEALANT AND SPRAY PAINTING.		1,600.00	600.00

Report Ref No. CC6/CTI23000715/Aya3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING BULB CHECKING.		120.00	30.00
	HEADLAMP FOCUSING.	NOT NECESSARY	120.00	-
	REMOVE /INSTALL CONDENSER AND TOP UP GAS.		100.00	60.00
	REMOVE/INSTALL RADIATOR AND CONDUCT PRESSURE TEST .		120.00	60.00
	FRONT CHASSIS ALIGNMENT.	NOT NECESSARY	250.00	-
			9,930.00	3,830.00
GRAND TOTAL			35,495.52	17,256.97
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,800.00

Report Ref No. CC6/CTI23000715/Aya3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKU 3741J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKU 3741J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

