

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKA3359K**
 MODEL : **VOLKSWAGEN GOLF**
 DATE OF ACCIDENT : 03.01.2023
 TIME OF ACCIDENT : 16:50 HOURS

29	REAR FENDER LH	Buckled	1	\$ 2,183.44	\$ 2,183.44	✓
30	REAR FENDER INNER TRIM	Deformed	2	\$ 535.60	\$ 1,071.20	✓
31	REAR FENDER AIR VENT LH	Not new	1	\$ 102.71	\$ 102.71	+
32	REAR END PANEL	Dented	1	\$ 1,599.60	\$ 1,599.60	1037 ✓
33	REAR END PANEL TOP GARNISH	Deformed	1	\$ 346.87	\$ 346.87	✓
34	REAR FLOOR PANEL	Repair	1	\$ 2,439.60	\$ 2,439.60	+
35	REAR FLOOR MAT	Not new	1	\$ 398.69	\$ 398.69	+
36	REAR FLOOR PANEL TOP BOARD	Deformed	1	\$ 698.75	\$ 698.75	✓
37	REAR TOOLS SPONGE	cracked	1	\$ 189.98	\$ 189.98	✓
38	REAR SPARE TYRE BOLT	Not new	1	\$ 90.97	\$ 90.97	+
39	REAR EXHAUST PIPE	3 Not	1	\$ 1,588.18	\$ 1,588.18	+
40	REAR EXHAUST MOUNTING	Not new	2	\$ 90.97	\$ 181.94	+
41	REAR EXHAUST INSULATOR	Not new	1	\$ 299.96	\$ 299.96	+

19060.84

TOTAL PRICE \$ 28,594.19

17154.75

LESS 10% \$ 2,859.42

SUB TOTAL PRICE \$ 25,734.77

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT		
1	REAR NUMBER PLATE	Dented	1	\$ 50.00	\$ 50.00	✓
2	REAR BUMPER CLIP (SET)	Not new	1	\$ 80.00	\$ 80.00	30
3	REAR FENDER SEALANT	Not new	1	\$ 80.00	\$ 80.00	60
4	REAR FENDER INNER TRIM CLIPS (SET)	Not new	1	\$ 80.00	\$ 80.00	30
5	REAR FENDER COWLING CLIP	Not new	1	\$ 40.00	\$ 40.00	+
6	TAILGATE SEALANT	Not new	1	\$ 150.00	\$ 150.00	+
7	TAIL GATE INNER TRIM CLIP (SET)	Not new	1	\$ 80.00	\$ 80.00	30
8	TAILGATE WINDSCREEN SEALANT	Not new	1	\$ 80.00	\$ 80.00	40
9	TAILGATE WINDSCREEN INNER SEAL	Not new	1	\$ 60.00	\$ 60.00	30
10	TAILGATE WINDSCREEN SOLAR FILM	Not new	1	\$ 150.00	\$ 150.00	✓
11	TAILLAMP CLIP (SET)	Not new	1	\$ 50.00	\$ 50.00	30
12	REAR END PANEL TOP GARNISH CLIPS (SET)	Not new	1	\$ 30.00	\$ 30.00	20
13	REAR END PANEL INSULATION SEAL	Not new	1	\$ 150.00	\$ 150.00	60
14	REAR BRAKE DOWN SIGN BOARD	Deformed	1	\$ 180.00	\$ 180.00	120
15	VIDEO RECORDER	Missing	1	\$ 800.00	\$ -800.00	580

1330

TOTAL \$ 2,060.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 2,200.00	1400
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	1200

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKA3359K**
 MODEL : **VOLKSWAGEN GOLF**
 DATE OF ACCIDENT : 03.01.2023
 TIME OF ACCIDENT : 16:50 HOURS

3	TUFF COAT	\$ 250.00	120
4	WIRING AND BULB CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	100
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	TRANFER TAILGATE MECHANISM	\$ 80.00	✓
8	(To vacuum glass) Fragments	\$ 80.00	✓
9	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	x
10	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 380.00	150.

12 Replace rear Video Recorder
TOTAL \$ ~~5,500.00~~ ¹⁰⁰ 5,500.00

Adrian Ly
 H/S 09/01/23.
 10 Days.

3380

ESTIMATE REPORT

TOTAL PARTS COST : \$ 27,794.77
 TOTAL LABOUR COST : \$ 5,500.00
 TOTAL REPAIR COST : \$ 33,294.77

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP:8297 9787

total: 21864.15
 L/S: 17.5K.

17.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: