

YSK AUTO

1 KAKI BUKIT AVENUE 6
#01-71 AUTOBAY SINGAPORE 417883

VEHICLE DETAILS

VEHICLE NO : SMV2354X
VEHICLE MODEL : TOYOTA RAIZE
CHASSIS NO : A200A0016033

TP China.
Xiao Tony

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL	
1	REAR NUMBER PLATE LAMP <i>Not New</i>	2	\$ 65.00	\$ 130.00	x.
2	REAR BUMPER <i>Rehnd.</i>	1	\$ 1,245.00	\$ 1,245.00	✓
3	REAR BUMPER SIDE HOLDER <i>Not New</i>	2	\$ 84.00	\$ 168.00	+
4	REAR BUMPER REFLECTOR <i>Not New</i>	2	\$ 95.00	\$ 190.00	+
5	REAR BUMPER LOWER SPOILER <i>at.</i>	1	\$ 652.00	\$ 652.00	✓
6	REAR BUMPER SIDE GRILLE <i>Rit cut.</i>	2	\$ 131.00	\$ 262.00	131
7	REAR END PANEL <i>Dented.</i>	1	\$ 721.00	\$ 721.00	✓
8	REAR END PANEL TOP GARNISH <i>Not New</i>	1	\$ 235.00	\$ 235.00	+
9	REAR END PANEL ANTENNA SENSOR <i>Not New</i>	1	\$ 198.00	\$ 198.00	+
10	REAR END PANEL AIR VENT <i>Not New</i>	2	\$ 42.00	\$ 84.00	+
11	TAILLAMP <i>Lt crushed.</i>	2	\$ 475.00	\$ 950.00	475
12	TAILGATE <i>Crushed.</i>	1	\$ 1,580.00	\$ 1,580.00	✓
13	TAILGATE LOCK <i>Dented.</i>	1	\$ 393.00	\$ 393.00	✓
14	TAILGATE WEATHERSTRIPE <i>Not New</i>	1	\$ 355.00	\$ 355.00	+
15	TAILGATE GLASS MOULDING <i>New</i>	1	\$ 121.00	\$ 121.00	✓
16	SPARE TYRE PANEL TOP BOARD <i>Not New</i>	1	\$ 525.00	\$ 525.00	+

5318
3988.50

TOTAL PRICE: \$ 7,809.00
LESS 25% \$ 1,952.25
SUB TOTAL PRICE: \$ 5856.75

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL	
1	REAR NUMBER PLATE <i>at</i>	1	\$ 30.00	\$ 30.00	✓
2	REAR NUMBER PLATE HOLDER <i>Rehnd</i>	1	\$ 30.00	\$ 30.00	✓
3	REAR BUMPER CLIPS <i>New</i>	1 SET	\$ 30.00	\$ 30.00	✓
4	REVERSE SENSOR <i>Dented</i>	1 SET	\$ 280.00	\$ 280.00	280.
5	REAR END PANEL TOP GARNISH CLIPS <i>Not New</i>	1 SET	\$ 20.00	\$ 20.00	+
6	REAR END PANEL SEALANT <i>New</i>	1 SET	\$ 60.00	\$ 60.00	✓
7	TAILGATE GLASS SEALANT <i>New</i>	1 SET	\$ 60.00	\$ 60.00	✓

410

TOTAL : \$ 510.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	800	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	800	
3	WIRING CHECK	\$ 100.00	30	
4	TO APPLY TUFF COAT	\$ 150.00	80	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	50	

6	TO REMOVE REAR CAMERA	\$ 100.00	52	
7	TO REMOVE VIDEO RECORDER	\$ 100.00	52	
8	TO REMOVE UPHOLSTERY	\$ 150.00	80.	
9	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	60.	
10	TO REMOVE TAILGATE GLASS	\$ 180.00	120.	

TOTAL: \$ 3,430.00

2120

ESTIMATE REPORT

TOTAL PARTS COST:

\$ 6366.75

TOTAL LABOUR COST:

\$ 3,430.00

TOTAL REPAIR COST:

\$ 9796.75

total: 6518.50

APPROVED DETAILS

SURVEYOR:

H/s: S-2K ✓

CONTACT:

FAX:

06 Days

PART BY PART / LUMP SUM:

NO. OF DAYS:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: