

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS23000750/SWP3M4**Date:** 09/03/2023**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

Claimant Vehicle No : SBS6073B**Insured Vehicle No :** XD6752T

Date of Loss: 17/01/2023

Nature of Claim: TP Claim No: XD6752T

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SBS6073B**

Make & Model: MERCEDES-BENZ CITARO O530, 6.4 D (A)

Engine No: 90292609016040

Reg. Date: 22/08/2011 (Man. Year: 2011)

Chassis No: WEB62808323122063

Colour: White/Purple

Odometer: 893971 km

Engine Capacity: 6374 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22

Rear Tyre Size: 275/70 R22

Front Left Side: Michelin 8 mm

Rear Left Side: Michelin 8 mm

Front Right Side: Michelin 8 mm

Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,099.80	1,099.80	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	244.40	150.00	94.40	38.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,344.20	1,249.80	94.40	7.02
+ GST 8.00/8.00% (S\$)	107.54	99.98	7.56	7.03
Nett Amount (S\$)	1,451.74	1,349.78	101.96	7.02
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 25/01/2023

Date Inspected: 27/01/2023

Inspected At:

SBS TRANSIT LTD (Branch)

28 SOON LEE ROAD

SINGAPORE 628083

Estimated Period of Repair: 0.5 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqubal**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 09 Mar 2023)	
Parts:	N/A	MERCEDES-BENZ CITARO O530 6.4 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS6073B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*30600077=OUTSIDE REARVIEW MIRROR;O/S	Cracked	1,099.80 F	*1,099.80 F
F=Franchise part.						
Total Parts (S\$)					1,099.80	1,099.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	244.40	150.00
Gross Labour Cost (\$\$)			244.40	150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >