

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 21 Mar 2023

**Preliminary Advice**

Insured Vehicle No	: SJN2961X	Accident Date	: 20/01/2023
TP Vehicle No	: SH7794D	Assignment Date	: 07/03/2023
Make	: AUDI A1	Est. Duration of Repair	: 14 DAYS
Date of Inspection	: 30/01/2023		
Inspection At	: BIFROST AUTO PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	84,133.42
Revised Amount	:S\$	51,746.73
Check Items (Estimated)	:S\$	0.00
Total	:S\$	51,746.73

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Pending Book Value Document from Workshop.  
The above survey was conducted on a 'Without Prejudice' basis.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.