

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0071/2023/GW
DATE : 19-Jan-22
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/01/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Taufikh

5 days - ok - Johnny Boo

29-May-23

OWNER'S NAME : MR BASMA HASSAN ASSAD
ADDRESS : 5 RHU CROSS #03-18
COSTA RHU LIVONIA BLOCK
SINGAPORE 437434
TELEPHONE : HP +65 97782291
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700085629-05
VEHICLE NO : **SLU 5639 Y**
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI
MODEL YEAR : 6/12/2017
ENGINE NO : DAX009672
CHASSIS NO : WAUZZZF0J2040581
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Jan-23
PLACE OF ACCIDENT : 5 RHU CROSS S437434, CAR PARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 5639 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	\$ 1,000.00
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER , BONNET AND BOTH WHEEL ARC TRIMS.	\$	4,100.00	\$ 1,300.00
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 7,852.00	\$ 2,972.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 5639 Y

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER - LH	1	\$ 1,536.00	\$	1,228.80
2	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 133.00		
3	FRONT BUMPER SECURING STRIP - LH	1	\$ 45.00	\$	35.44
4	FRONT BUMPER GUIDE SECTION - LH	1	\$ 46.00	\$	36.32
5	FRONT FENDER - LH	1	\$ 1,607.00	\$	1,285.60
6	FRONT FENDER BRACE - LH	1	\$ 266.00		
7	FRONT FENDER BRACKET - LH	1	\$ 21.00		
8	FRONT FENDER BRACKET CENTRE - LH	1	\$ 21.00		
9	FRONT FENDER CLOSURE PANEL - LH	1	\$ 37.00	\$	29.20
10	FRONT FENDER CLOSURE PANEL COVER - LH	1	\$ 47.00	\$	37.44
11	FRONT WHEEL HOUSING LINER - LH	1	\$ 326.00		
12	FRONT WHEEL SPOILER - LH	1	\$ 191.00		
13	FRONT WHEEL COVER - LH / RH	2	\$ 1,504.00	\$	601.20
14	INSCRIPTION 'S - LINE'	1	\$ 141.00	\$	112.40
15	HEADLIGHT MOUNTING - LH	1	\$ 140.00		
16	LED HEADLIGHT - LH	1	\$ 9,226.00		
17	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM	1	\$ 162.00		
18	HOSE FOR HEADLIGHT WASHER SYSTEM	1	\$ 150.00		
19	FRONT WHEEL RIM - LH	1	\$ 2,153.00		
20	RUBBER VALVE	1	\$ 4.00		
21	SUNDRIES	1	\$ 400.00		
TOTAL SPARE PARTS			\$ 18,156.00	\$	3,366.40
TOTAL LABOUR CHARGES			\$ 7,852.00	\$	2,972.00
GRAND TOTAL			\$ 26,008.00	\$	6,338.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-07/04/23



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT