

REC BY: Toujan

REF:

CS/ ALG 23000761/Tvc

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 1700085629

Claims No. 4536637534SG

Sum Insured: _____ Excess: 0 464

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 9137K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: George Vehicle: IN / OUT

Veh No: SLU56394 Yr Regn: 2017, Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi Q5 C.C. 1984

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 60234 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU ZZZ FY OJ = 2040581

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55R19

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI / TOYO / YOKO, or

Front R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 9/11/23 D.O.I. 20/1/23

Survey held at Premium Alexander

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
5/6/23	Final fig \$17,569.68 confirmed by email (Red 16,648.32, 48%)

Date/Time, File Pass to? : Preli. Report : Final Report

1) _____
Date/Time, File Return to?
2) 5/7/23-typist

Report Format: Merimen
Lump Sum / L.B.K. (\$ \$17,569.68)

Days Of Repair: 3
Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Insp (\$)
 : Weekend (\$)

Survey Fee:	_____
Transportation:	_____
_____ S + RS _____ \$	_____
Photos	_____
Others	_____



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0070/2023/GW
DATE : 19-Jan-22
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/01/2023

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR BASMA HASSAN ASSAD
ADDRESS : 5 RHU CROSS #03-18
COSTA RHU LIVONIA BLOCK
SINGAPORE 437434
TELEPHONE : HP +65 97782291
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700085629-05
VEHICLE NO : **SLU 5639 Y**
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI
MODEL YEAR : 6/12/2017
ENGINE NO : DAX009672
CHASSIS NO : WAUZZZFY0J2040581
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 9-Jan-23
PLACE OF ACCIDENT : LITTLE FARM CARPARK (EAST COAST RD)



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 5639 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. S/N \$	480.00	<i>X Refer to 1st accident 4/1/23.</i>
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE. S/N \$	400.00	<i>✓</i>
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. \$	1,200.00	<i>X Refer to 1st accident 4/1/23</i>
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS. ^{1st} ^{-?} <i>X RM photos - \$200</i> \$	4,500.00	<i>200</i>
5	TO CARRY OUT DIAGNOSTIC CHECK. S/N \$	192.00	<i>Refer to 1st accident 4/1/23</i>
TOTAL LABOUR CHARGES		\$ 6,772.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 5639 Y

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER - RH	1	\$ 1,536.00	de ✓
2	FRONT BUMPER CONNECTING PIECE - CENTER	1	\$ 242.00	?
3	FRONT BUMPER SECURING STRIP -RH	1	\$ 45.00	?
4	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 133.00	?
5	FRONT BUMPER GRILLE - CENTER	1	\$ 170.00	X
6	FRONT BUMPER SPOILER	1	\$ 900.00	?
7	FRONT BUMPER UNDERRUN BAR	1	\$ 614.00	cut ✓
8	FRONT BUMPER CLOSING ELEMENT	1	\$ 260.00	?
9	RADIATOR GRILLE	1	\$ 4,155.00	eng ✓
10	INSCRIPTION ' QUATTRO '	1	\$ 118.00	new ✓
11	RADIATOR GRILLE STRIKER PLATE	1	\$ 288.00	?
12	FRONT AIR GUIDE GRILLE - RH	1	\$ 691.00	alt ✓
13	FRONT AIR GUIDE GRILLE END CAP - RH	1	\$ 109.00	?
14	LOCKING CLIP	2	\$ 10.00	new ✓
15	FOAM FILLER PIECE	1	\$ 210.00	?
16	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 1,104.00	?
17	FRONT BUMPER GUIDE SECTION - RH	1	\$ 46.00	?
18	FRONT BUMPER COVER	1	\$ 152.00	X
19	STICKER ' CAUTION '	1	\$ 17.00	X
20	STICKER ' AIR CONDITIONER '	1	\$ 24.00	X
SUB TOTAL SPARE PARTS		:	\$ 10,824.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 5639 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT SENSOR - RH INNER / OUTER	2	\$ 544.00	?
22	SENSOR SEAL RING	4	\$ 11.00	ok
23	HORN - RH	1	\$ 220.00	?
24	HEADLIGHT MOUNTING - RH	1	\$ 140.00	?
25	LED HEADLIGHT - RH	1	\$ 9,226.00	ok
26	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM - RH	1	\$ 162.00	?
27	LED HEADLIGHT HOSE	1	\$ 150.00	?
28	FRONT BUMPER WIRING	1	\$ 457.00	?
29	FRONT WHEEL HOUSING LINER - RH	1	\$ 326.00	X
30	FRONT WHEEL SPOILER - RH	1	\$ 182.00	X
31	FRONT WHEEL COVER - LH / RH	2	\$ 1,504.00	photo,
32	TEMP SENSOR BRACKET	1	\$ 20.00	?
33	RADIATOR AIR GUIDE - UPPER	1	\$ 61.00	?
34	RADIATOR AIR GUIDE - CENTER	1	\$ 61.00	?
35	RADIATOR AIR GUIDE - LOWER	1	\$ 61.00	?
36	RADIATOR AIR GUIDE - RH	1	\$ 70.00	?
37	RADIATOR LOUVRE	1	\$ 623.00	?
38	FRONT NO. PLATE	S/N	\$ 60.00	X
39	SUNDRIES		\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 25,202.00	
TOTAL LABOUR CHARGES		:	\$ 6,772.00	
GRAND TOTAL		:	\$ 31,974.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Tanfhu 97495749
 SURVEYED DATE :
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS :
 or Not Authorise 20/1/23 @ 220pm
 Ex: fb
 Resurvey before paint 03 days.
 tanfhu@lkkauto.com

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT