



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0070/2023/GW
DATE : 19-Jan-22
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/01/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Taufikh
3 days - ok - Johnny Boo
29-May-23

OWNER'S NAME : MR BASMA HASSAN ASSAD
ADDRESS : 5 RHU CROSS #03-18
COSTA RHU LIVONIA BLOCK
SINGAPORE 437434
TELEPHONE : HP +65 97782291
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700085629-05
VEHICLE NO : **SLU 5639 Y**
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI
MODEL YEAR : 6/12/2017
ENGINE NO : DAX009672
CHASSIS NO : WAUZZZFY0J2040581
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 9-Jan-23
PLACE OF ACCIDENT : LITTLE FARM CARPARK (EAST COAST RD)

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 5639 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS	
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00		
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$	400.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00		
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS.	\$	4,500.00	\$	750.00
5	ADD LABOUR	\$	1,280.00	\$	730.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00		
TOTAL LABOUR CHARGES		:	\$ 8,052.00	\$	1,880.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 5639 Y

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT		REMARKS
1	FRONT BUMPER - RH	1	\$	1,536.00	\$ 1,228.80
2	FRONT BUMPER CONNECTING PIECE - CENTER	1	\$	242.00	
3	FRONT BUMPER SECURING STRIP -RH	1	\$	45.00	
4	FRONT BUMPER CLOSING ELEMENT - RH	1	\$	133.00	\$ 106.40
5	FRONT BUMPER GRILLE - CENTER	1	\$	170.00	
6	FRONT BUMPER SPOILER	1	\$	900.00	
7	FRONT BUMPER UNDERRUN BAR	1	\$	614.00	\$ 491.20
8	FRONT BUMPER CLOSING ELEMENT	1	\$	260.00	\$ 207.60
9	RADIATOR GRILLE	1	\$	4,155.00	\$ 3,324.00
10	INSCRIPTION ' QUATTRO '	1	\$	118.00	\$ 94.00
11	RADIATOR GRILLE STRIKER PLATE	1	\$	288.00	\$ 230.40
12	FRONT AIR GUIDE GRILLE - RH	1	\$	691.00	\$ 552.80
13	FRONT AIR GUIDE GRILLE END CAP - RH	1	\$	109.00	
14	LOCKING CLIP	2	\$	10.00	
15	FOAM FILLER PIECE	1	\$	210.00	\$ 168.00
16	FRONT BUMPER REINFORCEMENT BEAM	1	\$	1,104.00	
17	FRONT BUMPER GUIDE SECTION - RH	1	\$	46.00	
18	FRONT BUMPER COVER	1	\$	152.00	\$ 121.60
19	STICKER ' CAUTION '	1	\$	17.00	\$ 13.28
20	STICKER ' AIR CONDITIONER '	1	\$	24.00	\$ 18.56
SUB TOTAL SPARE PARTS			:	\$ 10,824.00	\$ 6,556.64

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 5639 Y

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
		<i>c/f</i>		\$	6,556.64
21	FRONT SENSOR - RH INNER / OUTER	2	\$	544.00	
22	SENSOR SEAL RING	4	\$	11.00	
23	HORN - RH	1	\$	220.00	
24	HEADLIGHT MOUNTING - RH	1	\$	140.00	\$ 111.60
25	LED HEADLIGHT - RH	1	\$	9,226.00	\$ 7,380.80
26	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM - RH	1	\$	162.00	
27	LED HEADLIGHT HOSE	1	\$	150.00	
28	FRONT BUMPER WIRING	1	\$	457.00	
29	FRONT WHEEL HOUSING LINER - RH	1	\$	326.00	
30	FRONT WHEEL SPOILER - RH	1	\$	182.00	\$ 145.60
31	FRONT WHEEL COVER - LH / RH	2	\$	1,504.00	\$ 601.20
32	TEMP SENSOR BRACKET	1	\$	20.00	
33	RADIATOR AIR GUIDE - UPPER	1	\$	61.00	
34	RADIATOR AIR GUIDE - CENTER	1	\$	61.00	
35	RADIATOR AIR GUIDE - LOWER	1	\$	61.00	
36	RADIATOR AIR GUIDE - RH	1	\$	70.00	\$ 55.28
37	RADIATOR LOUVRE	1	\$	623.00	
38	FRONT NO. PLATE (<i>Radiator grille replaced</i>)	S/N	\$	60.00	\$ 60.00
39	ADD PART		\$	964.00	\$ 771.20
40	SUNDRIES		\$	500.00	\$ 7.36
TOTAL SPARE PARTS			:	\$ 26,166.00	\$ 15,689.68
TOTAL LABOUR CHARGES			:	\$ 8,052.00	\$ 1,880.00
GRAND TOTAL			:	\$ 34,218.00	\$ 17,569.68

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-05/04/23



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0070/2023/GW 16-Feb-23 CHANG 1 of 1 SLU 5639 Y AUDI Q5 2.0 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND RENEW CHARGE AIR COOLER. S/N	\$ 480.00	\$ 480.00
2	TO REPAIR RHS FRONT FENDER.	\$ 800.00	\$ 250.00
	PARTS	\$ 1,280.00	\$ 730.00
Parts			
1	CHARGE AIR COOLER	\$ 964.00	\$ 771.20
	LABOUR		
GRAND TOTAL		\$ 2,244.00	\$ 1,501.20

For Premium Automobiles Pte Ltd

 Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT