

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Noor Amran, Noor Yussyuhaila

Date: 26 Jan 2023

### **Preliminary Advice**

Vehicle No	: SLU5639Y	Accident Date	: 09/01/2023
Make	: AUDI Q5 SPORT	Policy No.	: 1700085629
Assignment Date	: 25/01/2023	Excess	: S\$0.00
Date of Inspection	: 20/01/2023	Est. Duration of Repair	: 3
Inspection At	: 281 ALEXANDRA ROAD SINGAPORE 159938 REPAIRER: PREMIUM AUTOMOBILES PTE LTD		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	31,974.00
Revised Amount	:S\$	16,961.00
Check Items (Estimated)	:S\$	7,910.00
Total	:S\$	24,871.00
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	137,000.00
COE / PARF Rebate	:S\$	66,507.00
Salvage Value	:S\$	
Margin for Repair	:S\$	70,493.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.