



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC23000766/Tqce2 Date: 01/06/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 6101Y	Veh. Inspected	SG 5507K	
Policy No.		Coverage (\$)	0.00	
Claim No.	23/23/23/VC05/026804	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	25/01/2023	
2. Vehicle Particulars & Condition				
Make & Model	VOLVO B9TL	c.c	9364	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	YV3S4P924HA182982	Colour	GREEN	
Odometer	330204 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/70 R22.5	BRIDGESTONE	8 mm	
L/H Front Tyre	295/70 R22.5	BRIDGESTONE	8 mm	
R/H Rear Tyre	295/70 R22.5 (D)	BRIDGESTONE	8/8 mm	
L/H Rear Tyre	295/70 R22.5 (D)	BRIDGESTONE	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/01/2023	Inspection Date	26/01/2023	
Survey held at	3 YIO CHU KANG CRESCENT ROAD, SINGAPORE 786010			
Repairer	SBS TRANSIT LTD (Branch)			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	