

ASS. REC. BY:

REF: *SMR / 23000768 / Knp3**Kenneth*

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s *Car times*

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *04* days Res.: Yes or NoLum Sum: *1.67* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SMQ 38721* Yr Regn: *11, 19*Type: *M. Car* / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Honda Vezel* c.c. *1496*Colour: *M. Grey* A/C: Insured / Std / NI / NASp. Reading: *22737* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *RUI 1320386*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt or

Modi: NII / S/Rim / STD A/Rim or

Tyre Size: F: *215/60R16*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO orFront *7* Rear *7*R/Bal. *7* mm R/Bal. *7* mmL/Bal. *7* mm L/Bal. *7* mmD.O.A. *23/1/23* D.O.I. *26/1/2023*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 *GIA & ESI not ready**14/7/19* *834506* (Red. \$5946, 63%)

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

Days Of Repair: *4*

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Not Authorized
 Harvey Astipain
 4 days
 1/Rep \$3450p

VEHICLE NO: SMQ3872L

MODEL: HONDA VEZEL

CHASSIS NO: RU1

DESCRIPTION	REPAIRER'S ESTIMATE(S\$)
<u>PARTS (LIST ITEMS)</u>	
TAILGATE	B \$ 980.00 ✓
TAILGATE INNER TRIM	Sn \$ 200.00 X
TAILGATE LOCK ASSY	n \$ 120.00 X
REAR WINDSCREEN MOULDING	nn \$ 80.00 ✓
TAILGATE LAMP RHS	Sn \$ 460.00 X
TAIL LAMP RHS	Sn \$ 660.00 X
HONDA EMBLEM	nn \$ 40.00 X
VEZEL EMBLEM	nn \$ 50.00 ✓
HYBRID EMBLEM	nn \$ 50.00 X
REAR BUMPER	Bn \$ 510.00 ✓
REAR BUMPER RETAINER RHS	n \$ 30.00 ✓
END PANEL	\$ n 420.00 X
END PANEL TOP GARNISH	\$ Sn 70.00 X
REAR BUMPER REFLECTOR RHS	CM \$ 160.00 ✓
REAR CORNER PANEL RHS	\$ n 150.00 X
REAR WHEEL ARCH MOULDING RHS	nn \$ 180.00 ✓
EXHAUST	\$ B 540.00 ✓
EXHAUST MID PIPE 1015	B \$ 1,200.00 ✓
SMART BUZZER	Sn \$ 110.00 X
KEY ANTENNA	Sn \$ 60.00 X
	\$ 6,070.00
20%	\$ 1,214.00
	\$ 4,856.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SPECIAL NETT ITEMS

REAR SENSORS

CARPLATE W/HOLDER

WINDSCREEN SEALEANT

BUMPER CLIPS 1 SET

ph \$ 200.00
\$ *sn* 40.00
\$ *12* 40.00
\$ *12* 60.00

✓
✓
✓

Total \$ 340.00

TOTAL PARTS \$ 5,196.00

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,800.00	500/
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,800.00	400/
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00	20/
4	To provide anti-rust treatment on affected areas	\$ 100.00	30/
5	Transfer tailgate parts	\$ 150.00	60/
6	Remove and refit rear windscreen	\$ 150.00	120/
7	Remove & refit rear sensors	\$ 100.00	50/
	Labour Total :	\$ 4,200.00	
	TOTAL (PARTS & LABOUR):	\$ 9,396.00	