

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ganesh Sinathambi

Date: 16 Feb 2023

Preliminary Advice

Vehicle No	: FBH9676A	Accident Date	: 17/01/2023
Make	: SYM GTS 200	Policy No.	: 1001742541
Assignment Date	: 20/01/2023	Excess	: S\$300.00
Date of Inspection	: 27/01/2023	Est. Duration of Repair	: 0
Inspection At	: GLEN ENTERPRISE PTE LTD (HQ) 1100 / 1102 SERANGOON ROAD SINGAPORE 328196		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,490.50
Revised Amount	:S\$	1,989.20
Check Items (Estimated)	:S\$	226.80
Total	:S\$	2,216.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	3,000.00
COE / PARF Rebate	:S\$	140.00
Salvage Value	:S\$	
Margin for Repair	:S\$	2,860.00

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.