

Estimate Repair For Vehicle ~~FBH 970 A~~ (SYM GTS 200) FBH 9676A

QTY	DESCRIPTION OF PARTS	PRICE
2 pcs	Rear side body cover L/R @ \$175.00	\$ 350.00 ✓ <sup>L/BN</sup> <sub>R/?</sub>
2 pcs	Rear side body cover garnish L/R @ \$60.00	\$ 120.00 ✓ <sup>L/BN</sup> <sub>R/?</sub>
1 set	Rear side cowling "GTS 200" emblem L/R	\$ 28.00 ✓ NGL
1 unit	Rear tail lamp assy	\$ 260.00 ✓ BN
1 pc	Rear signal lamp	\$ 120.00 ✓ BN
1 pc	Rear license lamp	\$ 45.00 ✓ BN
1 pc	Rear tail cowling panel	\$ 115.00 ✓ BN
1 pc	Rear rim arch cover	\$ 65.00 ✓ BN
1 pc	Rear fender assy	\$ 85.00 ✓ BN
1 pc	Rear mudguard	\$ 165.00 ✓ BN
1 pc	Seat lock cable	\$ 19.00 ?
1 pc	Rear carrier assy	\$ 120.00 ✓ BN
1 pc	Luggage box assy	\$ 220.00 ✓ BN
1 pc	Cushion seat main cover	\$ 15.00 ✓ BN
1 set	Wire harness	\$ 180.00 ✓ BN
1 unit	Battery	\$ 60.00 X SVC
1 pc	Battery cable	\$ 45.00 X SVC
1 unit	Rectifier	\$ 149.00 ?
1 pc	Ignition coil assy	\$ 34.00 ?
2 pcs	Rear seat duct L/R @ \$25.00	\$ 50.00 ?
		\$ 2,245.00
	Less 10%	\$ 224.50
		\$ 2,020.50
<b>Labour charge</b>		
1]	Towing service charge.	\$ 40.00 show receipt
2]	To repair & respray body frame.	\$ 80.00 50
3]	Replace, realign & adjust above damaged parts.	
	check wiring, re-connection & lighting system.	\$ 350.00 200
	<b>Sub Total :</b>	\$ 470.00

**Total Parts and Labour \$ 2,490.50**

NAZ LXX

15/12/2023 1730

LIS

3 DAYS

CHECK ITEM PHOTOS

AFTER REPAIR PHOTOS

\* Repairer informed that repair limit is \$2,000.00 and agreed.

**LIK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before & after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_