



PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857

TEL : 6474 3323 FAX : 6264 6786

EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : 24 BENOI SECTOR
CONTACT NO : 6474 3323
FAX NO : 6264 6786
REFERENCE : PAC/OD/0010/2023/GW
DATE : 19-Jan-23
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

ALLIANZ INSURANCE SINGAPORE PTE LTD

79 Robinson Road

#09-01

Singapore 068897

ATTN: MOTOR CLAIMS DEPT

Tel: 6297 2529 Fax: 6297 1956

OWNER'S NAME : MR. CHENG JINSHEN CALVIN
ADDRESS : 12 MT ELIZABETH #20-01
SINGAPORE 228511
TELEPHONE : HP +65 98194986
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : PER/AIS/2022/0002416
VEHICLE NO : **SKJ 6297 M**
MODEL CODE : VW JETTA 1.4 TSI
MODEL YEAR : 5/5/2010
ENGINE NO : CAV150581
CHASSIS NO : WVVZZZ1KZAN095088
MILEAGE : -
DATE IN :
ESTIMATED BY : ALLAN WU
ACCIDENT DATE : 6-Jan-23
PLACE OF ACCIDENT : ALONG CAIRNHILL RD



24 BENOI SECTOR, SINGAPORE 629857
TEL : 6474 3323 FAX : 6264 6786
EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKJ 6297 M

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N	\$ 150.00	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N	\$ 100.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.		\$ 800.00	
4	TO RESPRAY FRONT BUMPER, BONNET AND LHS FRONT FENDER.		\$ 800.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 150.00	
TOTAL LABOUR CHARGES		:	\$ 2,000.00	

PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857

TEL : 6474 3323 FAX : 6264 6786

EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKJ 6297 M

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT	
				COST + 10 %
1 FRONT BUMPER	1	\$	1,650.00	
2 FRONT BUMPER SPOILER	1	\$	543.00	
3 FRONT BUMPER REINFORCEMENT BEAM	1	\$	829.00	
4 FRONT BUMPER GUIDE PROFILE - LH	1	\$	72.00	
5 FOAM FILLER PIECE	1	\$	151.00	
6 LICENCE PLATE HOLDER	1	\$	95.00	
7 FRONT BUMPER TRIM STRIPS	1	\$	178.00	
8 FORNT BUMPER GUIDE PROFILE - LH	1	\$	67.00	
9 FRONT BUMPER VENT GRILLE - LH	1	\$	255.00	
10 FRONT BUMPER VENT GRILLE - CENTER	1	\$	834.00	
11 FRONT BUMPER DECORATIVE FRAME - UPPER	1	\$	1,200.00	
12 FRONT BUMPER DECORATIVE FRAME - LOWER CENTRE	1	\$	867.00	
13 FRONT BUMPER STRIP - LH LOWER	1	\$	108.00	
14 RADIATOR GRILLE REPAIR SET	1	\$	991.00	
15 HORN - LH	1	\$	157.00	
16 HORN RETAINER - LH	1	\$	59.00	
17 FRONT FENDER - LH	1	\$	697.00	
18 PERMANENT UNDERBODY PROTECTION	1	\$	95.00	
19 ANTI CORROSION WAX	1	\$	53.00	
20 1K ADHESIVE SEALANT	1	\$	50.00	
SUB - TOTAL PARTS CHARGES	:	\$	8,951.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857

TEL : 6474 3323 FAX : 6264 6786

EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKJ 6297 M

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
				COST + 10 %
21 FRONT FENDER BRACE - LH	1	\$	173.00	
22 FRONT WHEEL HOUSING LINER - LH UPPER	1	\$	280.00	
23 FRONT WHEEL HOUSING LINER - LH LOWER	1	\$	157.00	
24 BONNET	1	\$	2,065.00	
25 ANTI CORROSION WAX	1	\$	53.00	
26 GASKET FLAP - LH	1	\$	49.00	
27 VW EBLEM	1	\$	268.00	
28 HEADLIGHT - LH	1	\$	978.00	
29 FOG LAMP - LH	1	\$	312.00	
30 FRONT NO. PLATE	S/N	\$	80.00	
31 SUNDRIES		\$	400.00	
TOTAL PARTS CHARGES	:	\$	10,989.00	
TOTAL LABOUR CHARGES	:	\$	2,000.00	
GRAND TOTAL	:	\$	12,989.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.



24 BENOI SECTOR, SINGAPORE 629857
TEL : 6474 3323 FAX : 6264 6786
EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6474 3323 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOCARE CENTRE

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT