



Case Details

Case Reference Number :

TAX/01/23/2045

Type of Repair : Accident Repair**Vehicle Registration Number :**

SHB5246U

Company Type : Strides Taxi Pte Ltd**Estimation ID :** EST-20341-ID**Assigned By :** Taxi Claims Manager Team**Insurance Company Name :** NTUC Income Insurance Co-operative Ltd**Accident Date and Time :** 19/01/2023 03:20 AM**Vehicle Age(In Months) :-**

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			COVER, RR BUMPER ASSY	1	478.90	478.90	25.00	359.17	Replace	1	0	Repair	RY
Standard	Main			REAR BUMPER REINFORCEMENT	1	360.10	360.10	25.00	270.08	Replace	0	0	Not Give	Xun
Standard	Main			PAD, RR BUMPER, RH & LH, 1	2	4.30	8.60	25.00	6.45	Replace	0	0	Not Give	Xun
Standard	Main			PAD, RR BUMPER, RH & LH, 2	2	4.30	8.60	25.00	6.45	Replace	0	0	Not Give	Xun
Standard	Main			PAD, RR BUMPER, RH & LH, 3	2	4.30	8.60	25.00	6.45	Replace	0	0	Not Give	Xun
Standard	Main			PAD, RR BUMPER, CTR	1	2.50	2.50	25.00	1.88	Replace	0	0	Not Give	Xun
Standard	Main			SEAL, RR BUMPER ARM, RH & LH	1	12.30	12.30	25.00	9.23	Replace	0	0	Not Give	Xun
Standard	Main			STOPPER, RR BUMPER, RH & LH	1	4.80	4.80	25.00	3.60	Replace	0	0	Not Give	Xun
Standard	Main			RETAINER, RR BUMPER, LH	1	127.40	127.40	25.00	95.55	Replace	0	0	Check	Xun.
Standard	Main			SEAL, RR BUMPER, LH	1	95.50	95.50	25.00	71.63	Replace	0	0	Not Give	Xun
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.80	48.00	25.00	36.00	Replace	10	36.00	Replace	u
Standard	Main			GUARD, RR BUMPER, LOWER	1	623.50	623.50	25.00	467.63	Replace	0	0	Not Give	Xun
Total Spare Part Cost									3,862.43	Surveyor Total			525.96	
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)			020	
Final Spare Part Cost									2,999.29	Final Sur Total			420.77	

Surveyor Approval

SMRT Recommendation														GOLD	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Givr	Xun	
Standard	Main			COVER, GUARD RR BUMPER LOWER	1	16.70	16.70	25.00	12.52	Replace	0	0	Not Givr	Xun	
Standard	Main			ANTENNA, ELECTRICAL KEY	1	78.00	78.00	25.00	58.50	Replace	0	0	Not Givr	Xun	
Standard	Main			REAR BUMPER GROMMET SCREW	1	2.20	2.20	25.00	1.65	Replace	0	0	Not Givr	Xun	
Standard	Main			LENS & BODY, REAR COMBINATION LAMP , LH	1	489.00	489.00	10.00	440.10	Replace	0	0	Not Givr	Xun	
Standard	Main			LENS & BODY ASSY , RR BUMPER , LH	1	544.40	544.40	10.00	489.96	Replace	1	489.96	Replace	ant	
Standard	Main			COVER, REAR FLOOR UNDER , LH	1	261.60	261.60	25.00	196.20	Replace	0	0	Not Givr	Xun	
Standard	Main			COVER, REAR FLOOR UNDER CENTER	1	249.10	249.10	25.00	186.83	Replace	0	0	Not Givr	Xun	
Standard	Main			COVER, REAR FLOOR UNDER, RH	1	189.20	189.20	25.00	141.90	Replace	0	0	Not Givr	Xun	
Standard	Main			PANEL SUB-ASSY, FENDER REAR LH	1	943.10	943.10	25.00	707.33	Replace	0	0	Not Givr	Xun	
Standard	Main			LINER, REAR FENDER , LH	1	151.10	151.10	25.00	113.32	Replace	0	0	Not Givr	Xun	
Total Spare Part Cost									3,862.43	Surveyor Total		525.96			
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)					
Final Spare Part Cost									2,999.29	Final Sur Total		420.77			

48
25/-36
544.40
10/-489.96

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION LH	676.00	200	
Total:			676.00	200.00	✓

check wiring 930 me

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	Xun
Total:			936.00	200.00	✓

4:19 PM

<https://vacsweb.smrt.com.sg/Estimation.aspx>

Signature

Estimator Assessment(\$)

Surveyor Assessment(\$)



T

Save Clear

Survey Date

20/01/2023

36
489.96
200
200
30
955.96
20% 764.77
L/S \$750
2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfah 97495745
wp' 20/1/23 24pm
cls Rising after repair
2 days
Tanfah consultants