



Section A - Accident Details

Registration Number	SHB5246U
Case Reference Number	TAX/01/23/2045
Registration Date	19/Dec/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TAN SOON CHOO
Type of Accident	Head to Rear
Accident Date and Time	19/Jan/2023 11:20 AM
Accident Reported Date and Time	20/Jan/2023 10:07 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24117481
Special Instruction to ARC, if any	TP/ REAR LEFT PORTION / TP
Prepared Date and Time	20/Jan/2023 12:39 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$936.00	\$200.00
Total Spare Part Cost	\$3,862.43	\$525.96
Total Other Cost	\$500.00	(\$175.96)
TOTAL COST	\$5,974.43	\$750.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	Boon Chew Tay	Taufikh (LKK) / INCOME
ARC / Surveyor Sign Off Date	21/01/2023 10:48 AM	20/01/2023 4:16 PM
Signature		
Remarks	lump sum repair / all check items to revert before proceed / After Paint photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR HP 9749 5749 taufikh@lkkauto.com NTUC	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2302-0148	Invoice Number	
Quotation Date	15.02.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION LH	\$676.00	\$200.00
Total Labour	\$676.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$936.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$205.96)
TO WASH AND VACUUM	\$60.00	\$0.00 Xnn
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$30.00 nec✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00 Xnn
TO CHECK & RESET SYSTEM FUNCTION	\$120.00	\$0.00 Xnn
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00 Xnn
Total Other Costs	\$500.00	(\$175.96)

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	100.00	\$0.00	Replace	Repair
		5202347030	REAR BUMPER REINFORCEMENT	0.00	\$360.10	0.00	\$0.00	Replace	Not Given
		5246247030	PAD, RR BUMPER, RH & LH , 1	0.00	\$4.30	0.00	\$0.00	Replace	Not Given
		5246247020	PAD, RR BUMPER, RH & LH , 2	0.00	\$4.30	0.00	\$0.00	Replace	Not Given
		5246247010	PAD, RR BUMPER, RH & LH , 3	0.00	\$4.30	0.00	\$0.00	Replace	Not Given
		5246147010	PAD, RR BUMPER, CTR	0.00	\$2.50	0.00	\$0.00	Replace	Not Given
		5219147030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$12.30	0.00	\$0.00	Replace	Not Given
		5259968030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.80	0.00	\$0.00	Replace	Not Given
		5257647040	RETAINER, RR BUMPER, LH	0.00	\$127.40	0.00	\$0.00	Replace	Check
		5259247040	SEAL, RR BUMPER , LH	0.00	\$95.50	0.00	\$0.00	Replace	Not Given
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace
		5245347010	GUARD, RR BUMPER, LOWER	0.00	\$623.50	0.00	\$0.00	Replace	Not Given

R
X
X
X
X
X
X
X
X
X
X
✓
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 26/02/2023

User ID : PohSuan

			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
		52169470 20	COVER, GUARD RR BUMPER LOWER	0.00	\$16.70	0.00	\$0.00	Replace	Not Given	X
		89997301 00	ANTENNA, ELECTRICAL KEY	0.00	\$78.00	0.00	\$0.00	Replace	Not Given	X
		90189060 29	REAR BUMPER GROMMET SCREW	0.00	\$2.20	0.00	\$0.00	Replace	Not Given	X
		81561471 51	LENS & BODY, REAR COMBINATION LAMP , LH	0.00	\$489.00	0.00	\$0.00	Replace	Not Given	X
		81591470 10	LENS & BODY ASSY , RR BUMPER , LH	1.00	\$544.40	10.00	\$489.96	Replace	Replace	√
		58399470 30	COVER, REAR FLOOR UNDER , LH	0.00	\$261.60	0.00	\$0.00	Replace	Not Given	X
		66259470 10	COVER, REAR FLOOR UNDER CENTER	0.00	\$249.10	0.00	\$0.00	Replace	Not Given	X
		58398470 50	COVER, REAR FLOOR UNDER , RH	0.00	\$189.20	0.00	\$0.00	Replace	Not Given	X
		61602471 60	PANEL SUB-ASSY, FENDER REAR LH	0.00	\$943.10	0.00	\$0.00	Replace	Not Given	X
		65638470 60	LINER, REAR FENDER , LH	0.00	\$151.10	0.00	\$0.00	Replace	Not Given	X
Total					\$4,827.10		\$525.96			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	525.96	
+	200.00	
+	230.00	L/S \$750/-
	955.96	
	-20%	
	764.77	