

ASS. REC. BY: Person

REF: CS/CT123 000712/RVP3

4654

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SK2 33184
 at Workshop m/s CYCLE & CARRIAGE
 of 188, POMPONA LANE
 Insured: SJJ 2573D CT1
 Policy No. DMPCSNW00183512204
 Claims No. SNM23D200598/C02/TOHHS
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 61K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SK2 33184 Yr Regn: 2016 JAN
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: MERCEDES BENZ B180 STYLE C.C. 1595
 Colour: GREY A/C: Insured / Std / NI / NA
 Sp. Reading: 14116 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WDD 246242ZJ377342
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 205/55R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 28/01/23 D.O.I. 16/02/23
 Survey held at CYCLE & CARRIAGE (PL)
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>REPAIR LIMIT - 30K</u>
<u>11/5/23</u>	<u>Rasul confirmed final fig \$21,352.17 (red 6248.90, 22%)</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 13
 Resurvey No. of Trip: 1

1) _____
Date/Time, File Return to?

2) 11/5/23-typist
 Report Format: Merimen
 Lump Sum / L.B.I. (\$): \$21,352.17

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:	
Transportation:	
\$ + RS. \$1	
Photos	
Others	
TOTAL	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 25/01/2023 15:54 (SGT)
Reported by Both
Date of Accident 25/01/2023 11:45 (SGT)
Exact Location of Accident Singapore
Additional Location Information BUONA VISTA
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKZ3318Y

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner HENG WAN SIA PATRICIA
NRIC No SXXXX465G
Email Address HENGPATRICIA@GMAIL.COM
Mobile Phone No (Phone) +65-94300990
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Mercedes
Model B180
Variant -
Exact purpose for which vehicle was being used at time of accident -
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1595

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number SKZ3318Y

DRIVER

Name of Driver HENG WAN SIA PATRICIA
NRIC No SXXXX465G
Date Of Birth 27/05/1955
Occupation Indoor

Date Of Driving Pass	15/12/1979
Driving experience	43 YEARS AND 1 MONTH
Gender	Female
Mobile Number	(Phone) +65-94300990
Alt. Phone Number	-
Email Address	HENGPATRICIA@GMAIL.COM
Address	246 PASIR PANJANG ROAD
Address complement	-
Postcode	118605
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	5
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	UNKNOWN
Gender	Male

PASSENGER 2

Name	UNKNOWN
Gender	Male

PASSENGER 3

Name	UNKNOWN
Gender	Male

PASSENGER 4

Name	UNKNOWN
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

MY VEHICLE SKZ3318Y WAS TRAVELLING ALONG BUONA VISTA ROAD NEAR BUS STOP (THE GALEN) AND VEHICLE SJJ2573D WAS IN THE OPPOSITE SIDE OF THE ROAD. SJJ2573D SKIDDED AND HIS VEHICLE RIGHT FRONT HITTED INTO MY VEHICLE SKZ3318Y.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJJ2573D
Vehicle Manufacturer Hyundai
Vehicle Model Verna
Vehicle Variant -
Vehicle Colour Black
Vehicle Category Private car
Name of Driver FARHAN BIN HAMZAH
NRIC No SXXXX632D
Contact Number -
Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Henry
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

25/01/2024




Describe Circumstances of the Accident

My vehicle SKZ 331FY was travelling along Buons Visis Rd near Bus stop (The Glen) and vehicle SJJ 2573D was in the opposite R. side of the Rd.

SJJ 2573D slipped and his vehicle Right Front hit into my vehicle SKZ 331FY

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

26/01/2023
14:00pm

Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKZ3318Y

CHINA TAIPING INSURANCE (S) PTE LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 62566
Reg No/Reg Date SKZ3318Y / 25/01/2016
Date In/Mileage / 0
Chassis No WDD2462422J377342
Engine No 27091030851555
Make/Model MB/B 180 SEDAN (W246) "STYLE
Colour/Trim 027 787 Mountain Gr/ 041 111 Black

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WC000668	Credit	10/02/2023/ 10:01	VS	356 / Vincent Seah				
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : 2100448124-07// 25.01.2023								
DRIVE IN/EXCESS : 25.01.2023 // TP CAR .: SJJ2573D=CHINA TAIPING								
DATE IN/DATE SURVEY: 13.02.2022 //								
DIRECT SETTLEMENT: ALFRED TOH- China Taiping					0.10			380.00
A BPILAB								
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT					0.19			400.00
A BPILAB								
REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR. NETT								
RHR DR								160 1920.00
A BPILAB								
REMOVE CARRIAGE ASSY FROM FRAME, IMPACT, REPLACE AND ASSEMBLE WHEEL BASE & ADJUST TO VEHICLE.								540.00
A BPILAB								
TO INSPECT & CONDUCT OPTICAL WHEEL ALIGNMENT. NETT								1920 2880.00
A BPILAB								
REMOVE & INSTALL INTERIOR SEATS, CARPET, GARNISH UNHOLSTRY ETC FOR NECESSARY REPAIR.								60.00
S BPNSUB								
TRANSFER RIM AND BALANCING TYRE-NETT								
RHR								5280 5760.00
A BPILAB								
PANEL BEAT TO REPAIR AFFECTED AREAS , REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.								3200 4800.00
A BPIRES								
RESPRAY ON RHF DR, RHR DR, RHR FENDER , REAR BUMPER , RIGHT RUNNIGN BOARD AND ACCIDENT AFFECTED AREA					1.00	1872.27	00.00	1872.27
M RHF DOOR <i>Repair</i>					1.00	2085.70	00.00	2085.70
M RIGHT REAR DOOR <i>Repair</i>					1.00	74.42	00.00	74.42
M ABSORBING -RHR DOOR <i>Repair</i>								

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKZ3318Y

CHINA TAIPING INSURANCE (S) PTE LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No **62566**
Reg No/Reg Date **SKZ3318Y / 25/01/2016**
Date In/Mileage **1 / 0**
Chassis No **WDD2462422J377342**
Engine No **27091030851555**
Make/Model **MB/B 180 SEDAN (W246) "STYLE**
Colour/Trim **027 787 Mountain Gr/ 041 111 Black**

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	10/02/2023/ 10:01	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RHR DOOR WEATHERSTRIP	1.00	317.72	00.00	317.72
M BLIND RIVET WITH PAN HEAD	9.00	2.70	00.00	24.30
M RH/R DOOR WINDOW RUN <i>2.00 X nn</i>	1.00	137.50	00.00	137.50
M REAR BUMPER <i>cut</i>	1.00	1607.14	00.00	1607.14
M RHS RUNNING BOARD <i>cut</i>	1.00	394.69	00.00	394.69
M REAR RIGHT FENDER <i>cut</i>	1.00	2839.83	00.00	2839.83
M RH/REAR FENDER AIR FLAP <i>2.00 X nn</i>	1.00	81.43	00.00	81.43
M RHR FENDER LINEAR <i>2.00 X nn</i>	1.00	157.70	00.00	157.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Repair
HP 90010068
13 days
10/02/23 P1200
Rey before paint

Confirmed & accepted by	Nett	26,332.70
	8% GST on	26332.70
		2106.62
	Total Payable	28,439.32

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKZ3318Y

CHINA TAIPING INSURANCE (S) PTE LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information
WIP No 62566
Reg No/Reg Date SKZ3318Y / 25/01/2016
Date In/Mileage 10/02/2023/ 141916
Chassis No WDD2462422J377342
Engine No 27091030851555
Make/Model MB/B 180 SEDAN (W246) "STYLE
Colour/Trim 027 787 Mountain Gr/ 041 111 Black

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	31/03/2023/ 16:41	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : 2100448124-07// 25.01.2023 DRIVE IN/EXCESS :25.01.2023 // TP CAR .: SJJ2573D=CHINA TAIPING DATE IN/DATE SURVEY:10.02.2022 //10.02.2022 Rasul-LKK 11:40AM DIRECT SETTLEMENT: ALFRED TOH- China Taiping				
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR,NETT RHR DR			0.19	400.00
A BPILAB REMOVE CARRIAGE ASSY FROM FRAME, IMPACT, REPLACE AND ASSEMBLE WHEEL BASE & ADJUST TO VEHICLE				960.00
A BPILAB TO INSPECT & CONDUCT OPTICAL WHEEL ALIGNMENT.NETT				540.00
A BPILAB REMOVE & INSTALL INTERIOR SEATS, CARPET, GARNISH UNHOLSTRY ETC FOR NECESSARY REPAIR.				1920.00
S BPNSUB TRANSFER RIM AND BALANCING TYRE-NETT RHR				60.00
A BPILAB PANEL BEAT TO REPAIR AFFECTED AREAS , REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.				5280.00
A BPIRES RESPRAY ON RHF DR, RHR DR, RHR FENDER ,REAR BUMPER ,RIGHT RUNNIGN BOARD AND ACCIDENT AFFECTED AREA			0.01	3200.00
X RIGHT REAR DOOR	1.00	2085.70	00.00	2085.70
X ABSORBING -RHR DOOR	1.00	74.42	00.00	74.42
X RHR DOOR WEATHERSTRIP	1.00	317.72	00.00	317.72

Confirmed & accepted by

Authorized signatory and company stamp

Finalization

13 days

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKZ3318Y

Vehicle & Document Information

CHINA TAIPING INSURANCE (S) PTE LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

WIP No 62566
Reg No/Reg Date SKZ3318Y / 25/01/2016
Date In/Mileage 10/02/2023/ 141916
Chassis No WDD2462422J377342
Engine No 27091030851555
Make/Model MB/B 180 SEDAN (W246) "STYLE
Colour/Trim 027 787 Mountain Gr/ 041 111 Black

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	31/03/2023/ 16:41	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X BLIND RIVET WITH PAN HEAD	9.00	2.70	00.00	24.30
X REAR BUMPER	1.00	1607.14	00.00	1607.14
X RHS RUNNING BOARD	1.00	394.69	00.00	394.69
X REAR RIGHT FENDER	1.00	2839.83	00.00	2839.83
S BPNSUB				100.00
SUPPLY & INSTALL HUPER OPTIK WINDOW FILM ON RHS QUARTER GLASS PANEL.				
X RH/R FENDER 3/4 GLASS	1.00	239.65	00.00	239.65
X MOUNTING CLIP	1.00	11.94	00.00	11.94
X MOUNTING CLIP	2.00	5.62	00.00	11.24
X RIVET	8.00	6.09	00.00	48.72
X RIVET	5.00	3.02	00.00	15.10
X CLIP	1.00	5.03	00.00	5.03
X TWO-COMPONENT ADHESIVE	1.00	118.43	00.00	118.43
X SEAM SEAL	1.00	116.42	00.00	116.42
X RHR DISK WHEEL	1.00	601.84	00.00	601.84

THIS IS NOT AN OFFICIAL TAX INVOICE
ESTIMATE

Finalization

Confirmed & accepted by

8% GST on	21352.17	1708.17
Total Payable		23,060.34

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKZ3318Y

Vehicle & Document Information

CHINA TAIPING INSURANCE (S) PTE LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

WIP No 62566
Reg No/Reg Date SKZ3318Y / 25/01/2016
Date In/Mileage 10/02/2023/ 141916
Chassis No WDD2462422J377342
Engine No 27091030851555
Make/Model MB/B 180 SEDAN (W246) "STYLE
Colour/Trim 027 787 Mountain Gr/ 041 111 Black

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	31/03/2023/ 16:44	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : 2100448124-07// 25.01.2023 DRIVE IN/EXCESS :25.01.2023 // TP CAR .: SJJ2573D=CHINA TAIPING DATE IN/DATE SURVEY:10.02.2022 //10.02.2022 Rasul-LKK 11:40AM DIRECT SETTLEMENT: ALFRED TOH- China Taiping				100.00 ✓
S BPNSUB SUPPLY & INSTALL HUPER OPTIK WINDOW FILM ON RHS QUARTER GLASS PANEL.				
X RH/R FENDER 3/4 GLASS <i>na</i>	1.00	239.65	00.00	239.65
X MOUNTING CLIP <i>na</i>	1.00	11.94	00.00	11.94
X MOUNTING CLIP <i>na</i>	2.00	5.62	00.00	11.24
X RIVET <i>na</i>	8.00	6.09	00.00	48.72
X RIVET <i>na</i>	5.00	3.02	00.00	15.10
X CLIP <i>na</i>	1.00	5.03	00.00	5.03
X TWO-COMPONENT ADHESIVE <i>na</i>	1.00	118.43	00.00	118.43
X SEAM SEAL <i>na</i>	1.00	116.42	00.00	116.42
X RHR DISK WHEEL <i>na</i>	1.00	601.84	00.00	601.84

THIS IS NOT AN OFFICIAL TAX INVOICE
ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

Nett	1,268.37
8% GST on 1268.37	101.47
Total Payable	1,369.84

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg