



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKZ3318Y

CHINA TAIPING INSURANCE (S) PTE LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No **62566**
Reg No/Reg Date **SKZ3318Y / 25/01/2016**
Date In/Mileage **10/02/2023/ 141916**
Chassis No **WDD2462422J377342**
Engine No **27091030851555**
Make/Model **MB/B 180 SEDAN (w246) "STYLE**
Colour/Trim **027 787 Mountain Gr/ 041 111 Black**

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	31/03/2023/ 16:44	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

Z REQUEST

Customer Request

M BPNSUN

POLICY NO/ACC DATE : 2100448124-07// 25.01.2023
DRIVE IN/EXCESS :25.01.2023 // TP CAR .: SJJ2573D=CHINA TAIPING
DATE IN/DATE SURVEY:10.02.2022 //10.02.2022 Rasul-LKK 11:40AM
DIRECT SETTLEMENT: ALFRED TOH- China Taiping

S BPNSUB

SUPPLY & INSTALL HUPER OPTIK WINDOW FILM
ON RHS QUARTER GLASS PANEL.

X RH/R FENDER 3/4 GLASS	1.00	239.65	00.00	239.65
X MOUNTING CLIP	1.00	11.94	00.00	11.94
X MOUNTING CLIP	2.00	5.62	00.00	11.24
X RIVET	8.00	6.09	00.00	48.72
X RIVET	5.00	3.02	00.00	15.10
X CLIP	1.00	5.03	00.00	5.03
X TWO-COMPONENT ADHESIVE	1.00	118.43	00.00	118.43
X SEAM SEAL	1.00	116.42	00.00	116.42
X RHR DISK WHEEL	1.00	601.84	00.00	601.84

SUPPLEMENTARY

Confirmed & accepted by

	Nett	1,268.37
8% GST on	1268.37	101.47
	Total Payable	1,369.84

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKZ3318Y

CHINA TAIPING INSURANCE (S) PTE LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No	62566
Reg No/Reg Date	SKZ3318Y / 25/01/2016
Date In/Mileage	10/02/2023/ 141916
Chassis No	WDD2462422J377342
Engine No	27091030851555
Make/Model	MB/B 180 SEDAN (W246) "STYLE
Colour/Trim	027 787 Mountain Gr/ 041 111 Black

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	31/03/2023/ 16:41	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : 2100448124-07// 25.01.2023 DRIVE IN/EXCESS :25.01.2023 // TP CAR .: SJJ2573D=CHINA TAIPING DATE IN/DATE SURVEY:10.02.2022 //10.02.2022 Rasul-LKK 11:40AM DIRECT SETTLEMENT: ALFRED TOH- China Taiping				
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR.NETT RHR DR			0.19	400.00
A BPILAB REMOVE CARRIAGE ASSY FROM FRAME, IMPACT REPLACE AND ASSEMBLE WHEEL BASE & ADJUST TO VEHICLE.				960.00
A BPILAB TO INSPECT & CONDUCT OPTICAL WHEEL ALIGNMENT.NETT				540.00
A BPILAB REMOVE & INSTALL INTERIOR SEATS, CARPET, GARNISH UNHOLSTRY ETC FOR NECESSARY REPAIR.				1920.00
S BPNSUB TRANSFER RIM AND BALANCING TYRE-NETT RHR				60.00
A BPILAB PANEL BEAT TO REPAIR AFFECTED AREAS , REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.				5280.00
A BPIRES RESPRAY ON RHF DR, RHR DR, RHR FENDER ,REAR BUMPER ,RIGHT RUNNIGN BOARD AND ACCIDENT AFFECTED AREA			0.01	3200.00
X RIGHT REAR DOOR	1.00	2085.70	00.00	2085.70
X ABSORBING -RHR DOOR	1.00	74.42	00.00	74.42
X RHR DOOR WEATHERSTRIP	1.00	317.72	00.00	317.72

Confirmed & accepted by

Authorized signatory and company stamp

Finalization

13 days

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKZ3318Y

CHINA TAIPING INSURANCE (S) PTE LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No **62566**
Reg No/Reg Date **SKZ3318Y / 25/01/2016**
Date In/Mileage **10/02/2023/ 141916**
Chassis No **WDD2462422J377342**
Engine No **27091030851555**
Make/Model **MB/B 180 SEDAN (W246) "STYLE**
Colour/Trim **027 787 Mountain Gr/ 041 111 Black**

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	31/03/2023/ 16:41	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X BLIND RIVET WITH PAN HEAD	9.00	2.70	00.00	24.30
X REAR BUMPER	1.00	1607.14	00.00	1607.14
X RHS RUNNING BOARD	1.00	394.69	00.00	394.69
X REAR RIGHT FENDER	1.00	2839.83	00.00	2839.83
S BPNSUB				100.00
SUPPLY & INSTALL HUPER OPTIK WINDOW FILM ON RHS QUARTER GLASS PANEL.				
X RH/R FENDER 3/4 GLASS	1.00	239.65	00.00	239.65
X MOUNTING CLIP	1.00	11.94	00.00	11.94
X MOUNTING CLIP	2.00	5.62	00.00	11.24
X RIVET	8.00	6.09	00.00	48.72
X RIVET	5.00	3.02	00.00	15.10
X CLIP	1.00	5.03	00.00	5.03
X TWO-COMPONENT ADHESIVE	1.00	118.43	00.00	118.43
X SEAM SEAL	1.00	116.42	00.00	116.42
X RHR DISK WHEEL	1.00	601.84	00.00	601.84

ESTIMATE

Finalization

Confirmed & accepted by

Nett **21,352.17**
8% GST on **21352.17** **1708.17**

Authorized signatory and company stamp

Total Payable 23,060.34

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg