

ASS. REC. BY: P. Ryan

REF: CS/CT123 000792/RVP3

4654

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SK2 33184

at Workshop m/s CYCLE & CARRIAGE

of 188, POMEROY LANE

Insured: CTI

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 61K

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SK2 33184 Yr Regn: 2016 JAN

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES BENZ B180 STYLE c.c 1595

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 141916 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2462422J377342

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 25/01/23 D.O.I. 16/02/23

Survey held at CYCLE & CARRIAGE (PL)

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>REPAIR LIMIT - 30K</u>

Date/Time, File Pass to? : Prel. Report
 : Final Report

1) Date/Time, File Return to?
2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

Survey Fee:

Transportation: _____

S + RS: \$ _____

Printed: _____

Others: _____

Report Form No: _____

Lum Sum / 1/2/1/1/1/1



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-6500111-X

ESTIMATE FOR SKZ3318Y

CHINA TAIPING INSURANCE (S) PTE LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No **62566**
Reg No/Reg Date **SKZ3318Y / 25/01/2016**
Date In/Mileage **SKZ3318Y / 0**
Chassis No **WDD2462422J377342**
Engine No **27091030851555**
Make/Model **MB/B 180 SEDAN (W246) "STYLE**
Colour/Trim **027 787 Mountain Gr/ 041 111 Black**

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	10/02/2023/ 10:01	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : 2100448124-07// 25.01.2023 DRIVE IN/EXCESS :25.01.2023 // TP CAR .: SJJ2573D=CHINA TAIPING DATE IN/DATE SURVEY:13.02.2022 // DIRECT SETTLEMENT: ALFRED TOH- China Taiping				
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR. NETT. RHR DR			0.19	400.00
A BPILAB REMOVE CARRIAGE ASSY FROM FRAME, IMPACT REPLAGE AND ASSEMBLE WHEEL BASE & ADJUST TO VEHICLE.			160	1920.00
A BPILAB TO INSPECT & CONDUCT OPTICAL WHEEL ALIGNMENT. NETT				540.00
A BPILAB REMOVE & INSTALL INTERIOR SEATS, CARPET, GARNISH UNHOLSTRY ETC FOR NECESSARY REPAIR.			1920	2880.00
S BPNSUB TRANSFER RIM AND BALANCING TYRE-NETT RHR				60.00
A BPILAB PANEL BEAT TO REPAIR AFFECTED AREAS , REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.			5280	5280.00
A BPIRES RESPRAY ON RHF DR, RHR DR, RHR FENDER ,REAR BUMPER ,RIGHT RUNNIGN BOARD AND ACCIDENT AFFECTED AREA			3700	4800.00
M RHF DOOR <i>repair</i>	1.00	1872.27	00.00	1872.27
M RIGHT REAR DOOR <i>base</i>	1.00	2085.70	00.00	2085.70
M ABSORBING -RHR DOOR <i>base</i>	1.00	74.42	00.00	74.42

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of removing the rubber seal or other repair procedure.

Pandan Limb Service Centre
188 Pandan Limb
Singapore 128375
Tel: 6771 8500



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKZ3318Y

CHINA TAIPING INSURANCE (S) PTE LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No **62566**
Reg No/Reg Date **SKZ3318Y / 25/01/2016**
Date In/Mileage **SKZ3318Y**
Chassis No **WDD2462422J377342**
Engine No **27091030851555**
Make/Model **MB/B 180 SEDAN (W246) "STYLE**
Colour/Trim **027 787 Mountain Gr/ 041 111 Black**

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	10/02/2023/ 10:01	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RHR DOOR WEATHERSTRIP	1.00	317.72	00.00	317.72
M BLIND RIVET WITH PAN HEAD	9.00	2.70	00.00	24.30
M RH/R DOOR WINDOW RUN	1.00	137.50	00.00	137.50
M REAR BUMPER	1.00	1607.14	00.00	1607.14
M RHS RUNNING BOARD	1.00	394.69	00.00	394.69
M REAR RIGHT FENDER	1.00	2839.83	00.00	2839.83
M RH/REAR FENDER AIR FLAP	1.00	81.43	00.00	81.43
M RHR FENDER LINEAR	1.00	157.70	00.00	157.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Handwritten:
Rahul
Hp 90010068
13 days
10/02/23 P12W
Reg before paint

Confirmed & accepted by

Nett **26,332.70**
8% GST on **26332.70** **2106.62**

Authorized signatory and company stamp

Total Payable **28,439.32**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of resurveying the rubber seal or other repair requiring the removal of the windscreen.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 465G

Vehicle Details

Vehicle No.: SKZ3318Y

Vehicle to be Exported: No

Intended Deregistration Date: 12 Feb 2023

Vehicle Make: MERCEDES BENZ

Vehicle Model: B180 STYLE (R16 LED)

Primary Colour: Grey

Manufacturing Year: 2015

Engine No.: 27091030851555

Chassis No.: WDD2462422J377342

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$26,108.00

Original Registration Date: 25 Jan 2016

First Registration Date: 25 Jan 2016

Transfer Count: 0

Actual ARF Paid: \$23,552.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 24 Jan 2026

PARF Rebate Amount: \$14,131.00

Intended COE Rebate Details

COE Expiry Date: 24 Jan 2026

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$56,989.00

COE Rebate Amount: \$16,805.00

Total Rebate Amount: \$30,936.00

Mercedes-Benz B-Class B180 Style

Overview

Financial

Accessories

Similar

Research

Photos

Map



GEN CAPITAL

Price **\$61,000** (2.98% loan with \$500 cash back.) [Get Pre-approved Loan.](#)

Depreciation [?](#) \$16,810 /yr
[View models with similar depre](#)

Reg Date 18-Jan-2016
(2yrs 11mths 5days COE left)

Mileage 72,000 km (10.2k /yr)

Manufactured [?](#) 2015

Road Tax [?](#) \$740 /yr

Transmission Auto

Dereg Value [?](#) \$30,477 as of today (change)

OMV [?](#) \$26,023

COE [?](#) \$56,001

ARF [?](#) \$23,433

Engine Cap 1,595 cc

Power 90.0 kW (120 bhp)

Curb Weight [?](#) 1,425 kg

No. of Owners [?](#) 2