



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI23000799/Uvp3m4 Date: 03/02/2023	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMR 6335X	Veh. Inspected	SKH 5030H	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10020101/JL	Excess (\$)	0.00	
Assign From	FRAULEINE KHOO	Assign Date	26/01/2023	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU IMPREZA (A)	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JF1GE3KS59G005891	Colour	SILVER	
Odometer	172116 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	GOODYEAR	6 mm	
L/H Front Tyre	225/45 R17	GOODYEAR	6 mm	
R/H Rear Tyre	225/45 R17	GOODYEAR	6 mm	
L/H Rear Tyre	225/45 R17	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/01/2023	Inspection Date	27/01/2023	
Survey held at	1 KAKI BUKIT AVE 6 #01-73 SINGAPORE 417883			
Repairer	SPEEDWERKZ PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	