

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0073/2023/EQ  
**DATE** : 25-Jan-23  
**WIP** : 59612

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 26/1/2023**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**Hi Adrian**

**3 days - ok - Johnny Boo**

**14-Mar-23**

**OWNER'S NAME** : MR HO WEI RUI, GILBERT  
**ADDRESS** : 501 DUNMAN ROAD  
#11-03  
SINGAPORE 439193  
**TELEPHONE** : HP +65 96698629  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 1900244032-01  
**VEHICLE NO** : **SKH 6911 J**  
**MODEL CODE** : AUDI A3 SPORTSBACK 1.0 TF  
**MODEL YEAR** : 15/11/2019  
**ENGINE NO** : CHZ C33218  
**CHASSIS NO** : WAUZZZ8VXKA121470  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 17-Jan-23  
**PLACE OF ACCIDENT** : CROSS JUNCTION OF DUNMAN ROAD AND TANJONG KATONG ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKH 6911 J**

| S/N                         | NATURE OF JOBS                                                                                                                |        | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|-------------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY. | S/N \$ | 360.00               |                               |
| 2                           | TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                         | S/N \$ | 350.00               |                               |
| 3                           | TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MNAAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.  | \$     | 1,050.00             | \$ 500.00                     |
| 4                           | TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.                                                                                 | \$     | 2,000.00             | \$ 550.00                     |
| 5                           | TO CARRY OUT DIAGNOSTIC CHECK                                                                                                 | S/N \$ | 192.00               | \$ 192.00                     |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                               | : \$   | <b>3,952.00</b>      | <b>\$ 1,242.00</b>            |

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6911 J**

|                             |                                             |     | DAMAGED PARTS & PRICES |         |          |
|-----------------------------|---------------------------------------------|-----|------------------------|---------|----------|
| S/N                         | PARTS DESCRIPTION                           | QTY | S/NETT                 | REMARKS |          |
| 1                           | FRONT BUMPER                                | 1   | \$ 2,273.00            | \$      | 1,818.40 |
| 2                           | FRONT BUMPER FIXING PARTS                   | 1   | \$ 207.00              |         |          |
| 3                           | FRONT BUMPER GUIDE SECTION - RH             | 1   | \$ 46.00               | \$      | 36.32    |
| 4                           | FRONT BUMPER GRILLE - CENTER                | 1   | \$ 190.00              |         |          |
| 5                           | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE | 1   | \$ 352.00              |         |          |
| 6                           | FRONT BUMPER CLOSING ELEMENT - RH           | 1   | \$ 337.00              |         |          |
| 7                           | RADIATOR GRILLE                             | 1   | \$ 1,679.00            |         |          |
| 8                           | RADIATOR GRILLE CLOSING ELEMENT             | 1   | \$ 223.00              |         |          |
| 9                           | FRONT BUMPER AIR GUIDE GRILLE - RH          | 1   | \$ 222.00              |         |          |
| 10                          | AIR CONDITIONER STICKER                     | 1   | \$ 9.00                |         |          |
| 11                          | CAUTION SIGN STICKER                        | 1   | \$ 17.00               |         |          |
| 12                          | FRONT WHEEL HOUSING LINER - RH              | 1   | \$ 198.00              | \$      | 158.00   |
| 13                          | HEADLIGHT                                   | 1   | TBC                    |         |          |
| 14                          | HEADLIGHT LIFT CYLINDER - RH                | 1   | \$ 165.00              |         |          |
| 15                          | LIFT CYLINDER HOSE                          | 1   | \$ 81.00               |         |          |
| 16                          | HORN LOW TONE - RH                          | 1   | \$ 225.00              |         |          |
| 17                          | FRONT NO PLATE                              | S/N | \$ 60.00               |         |          |
| 18                          | SUNDRIES                                    |     | \$ 400.00              |         |          |
| <b>TOTAL SPARE PARTS</b>    |                                             | :   | \$ 6,684.00            | \$      | 2,012.72 |
| <b>TOTAL LABOUR CHARGES</b> |                                             | :   | \$ 3,952.00            | \$      | 1,242.00 |
| <b>GRAND TOTAL</b>          |                                             | :   | \$ 10,636.00           | \$      | 3,254.72 |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED  
 SPARE PARTS ARE SPECIAL NETT.  
 BL-22/02/23



**PREMIUM AUTOMOBILES**



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT