

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|---|--|--------------------------------------|-----------------|-----------------------|--|
| | TOKIO MARINE IN | SURANCE SINGAPORE LTD | Ref | : CS/TMI23000806/Anp3 | |
| | 20 MCCALLUM ST TOKIO MARINE CI | REET #09-01 ENTRESINGAPORE 069046 | Dat | e: 27/01/2023 | |
| | | | Cod | de: TMI | |
| 1. | 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SLG 2263R | Veh. Inspected | SH 7012C | |
| | Policy No. | MN000276 | Coverage (\$) | 0.00 | |
| | Claim No. | M2300517 | Excess (\$) | 0.00 | |
| | Assign From | TAN WAN CONG | Assign Date | 26/01/2023 | |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | | c.c | 0 | |
| | Engine No. | HIDDEN | Year of Reg. | | |
| | Chassis No. | | Colour | | |
| | Odometer - | | Steering | | |
| | Brakes | | Modification | | |
| | General | | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | | | mm | |
| | L/H Front Tyre | | | mm | |
| | R/H Rear Tyre | | | mm | |
| | L/H Rear Tyre | | | mm | |
| 4. | Description of Damages | | | | |
| | | | | | |
| 5. | General Information | | | | |
| | Accident Date | 20/01/2023 | Inspection Date | 27/01/2023 | |
| | Survey held at | COMFORTDELGRO ENGINEER | RING PTE LTD | | |
| | | 59 LOYANG DRIVE SINGAPORE 508969 | | | |
| | | emarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |