

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0074/2023/EQ
DATE : 26-Jan-23
WIP : 59579

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/1/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR DHARMARAJ RAMESH
ADDRESS : 70 PHOENIX ROAD
#20-16
SINGAPORE 667973
TELEPHONE : HP +65 92360827
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : -
VEHICLE NO : **SGX 1911 E**
MODEL CODE : AUDI A7 SB 2.0 TFSI QU S
MODEL YEAR : 30/10/2020
ENGINE NO : DLH 066891
CHASSIS NO : WAUZZZF22LN013749
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Jan-23
PLACE OF ACCIDENT : 70, PHOENIX ROAD, HILLSTA CARPARK
SINGAPORE 667973

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGX 1911 E**

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	\$	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING AND LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	\$	600.00
3	TO RESPRAY REAR BUMPER, REAR END PANELLING AND LHS REAR FENDER.	\$	3,000.00	\$	1,200.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		: \$	5,952.00	\$	2,352.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGX 1911 E

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER	1	\$ 3,677.00	\$	2,941.60
2	REAR BUMPER FIXING PARTS	2	\$ 259.00		
3	REAR BUMPER SECURING STRIP - LH / RH	2	\$ 102.00		
4	REAR BUMPER SPOILER	1	\$ 565.00	\$	451.60
5	REAR BUMPER CHROME TRIM - CENTER	1	\$ 261.00	\$	208.80
6	REAR BUMPER CHROME TRIM - LH	1	\$ 265.00	\$	211.60
7	REAR BUMPER CHROME TRIM	1	\$ 688.00	\$	550.40
8	REAR BUMPER SECURING STRIP	1	\$ 204.00	\$	162.80
9	REAR BOOT LID OPENING CONTROL UNIT	1	\$ 491.00		
10	REAR TAILGATE OPENING SENSOR LINE	2	\$ 460.00		
11	REAR TELEPHONE AERIAL	1	\$ 94.00		
12	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,140.00		
13	REAR BUMPER IMPACT BAR GASKET - LH / RH	2	\$ 34.00		
14	REAR BUMPER GUIDE SECTION - LH UPPER	1	\$ 54.00		
15	REAR BUMPER GUIDE SECTION - LH LOWER	1	\$ 75.00		
16	REAR BUMPER HOLDING STRAP - CENTER	1	\$ 140.00		
17	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 598.00		
18	REAR PARKING AID SEAL RING	4	\$ 11.00		
19	REAR BUMPER WIRING SET	1	\$ 648.00		
20	REAR OUTER TAIL LIGHT - LH	1	\$ 1,626.00	\$	1,300.80
SUB TOTAL SPARE PARTS		:	\$ 11,392.00	\$	5,827.60

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGX 1911 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 5,827.60
21	REAR TAIL LIGHT TRIM - LH	2	\$ 104.00	\$ 41.04
22	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 11,896.00	\$ 5,868.64
TOTAL LABOUR CHARGES		:	\$ 5,952.00	\$ 2,352.00
GRAND TOTAL		:	\$ 17,848.00	\$ 8,220.64

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-15/03/23



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT