



Mercedes-Benz

Finalization

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNE7040X

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information

WIP No 62593
Reg No/Reg Date SNE7040X / 01/04/2022
Date In/Mileage 27/01/2023/ 8954
Chassis No W1K2130532B0410369
Engine No 27492032012792
Make/Model MB/E 300 e SEDAN
Colour/Trim 028 859 Mojave Silv/ 042 201 AMG Line Le

Account No	Terms	Date/Time Printed	CSE	Operator			
WA000001	Credit	21/03/2023/ 15:04	YK	395 / Yik Chan Hoe			
Description of Goods / Services				Qty	Unit Price	Dis %	Amount

Z REQUEST

Customer Request

M BPNSUN

POLICY NO/ACC DATE : SP2003915046 // 05/01/2023
DRIVE IN/EXCESS : 26/01/2023 // \$700.00
DATE IN/DATE SURVEY: 27/01/2023 // TAUFIK LKK
BY/AUTHORIZED ON : 31/01/2023 // VERON LKK

A BPILAB

PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW
BODY PANELS WITH REFINISH

A BPIRES

RESpray REAR BUMPER AND LEFT REAR FENDER.

A BPILAB

USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO
STANDARD SETTINGS. NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE. NET

X BPNEXC

INSURANCE EXCESS

X LEFT OUTER REAR LAMP COMBINATION

X LEFT INNER REAR LAMP COMBINATION

X LEFT REAR GASKET FOR LIGHT HOUSING

Attn: Taufik

05

Working Days

960.00

0.05

1600.00

0.10

380.00

120.00

-700.00

1.00

793.61

00.00

793.61

1.00

564.36

00.00

564.36

1.00

44.02

00.00

44.02

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd

Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272

Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett

3,761.99

8% GST on

3761.99

300.96

Total Payable

4,062.95

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG