



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS3/LPC22011741/Svy3m4-1 Date: 13/02/2023 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	XD 9789T	Veh. Inspected	SMY 8539A
	Policy No.		Coverage (\$)	0.00
	Claim No.	22/22/22/VC00/026608	Excess (\$)	0.00
	Assign From	KENNY LIM	Assign Date	25/01/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA NOAH	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	ZWR800438887	Colour	SILVER
	Odometer	157949 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	DAVANTI	6 mm
	L/H Front Tyre	195/65 R15	DAVANTI	6 mm
	R/H Rear Tyre	195/65 R15	DAVANTI	5 mm
	L/H Rear Tyre	195/65 R15	DAVANTI	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	19/11/2022	Inspection Date	22/11/2022
	Survey held at	APEX MOTORING 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGAPORE 417800.		
<b>5a. Remarks</b>				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	