



Borneo Motors

INCORPORATED

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462. Tel no 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
THIRD PARTY CLAIM		S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd				
		Document No. 0	3 Media Close #01-03/06 Singapore 138498				
		Document Date 17/01/2023	Work: 65703925				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	17/04/2017	SLM8839J	0	19697	66OD/SLM8839J/170123
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FU203555349		2ZRS034992	60	Shashitharan	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.: SKW4787K ACC DATE:16/01/23 DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				150	100.00
2	B	BP-LAB2 CHECK WIRING AND CONDUCT LEAK TEST				1188	198.00
3	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL				1212	2376.00
4	B	BP-RES2 RESRPAY ACC AFF AREA				1212	1968.00
5	1	U52116-47050 SUPPORT, FR BUMPER	1.00	95.70		1212	95.70
6	2	U53802-47100 FENDER SUB-ASSY. FR	1.00	1177.80		1212	1177.80
7	3	U53876-47110 LINER, FR FENDER, LH	1.00	243.20		1212	243.20
8	4	U75374-47150 EMBLEM, SIDE PANEL	1.00	65.60		1212	65.60
9	5	U81185-47691 UNIT, HEADLAMP	1.00	3167.20		1212	3167.20
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged parts: during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company							
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Date:			9,391.50		
Please acknowledge receipt of vehicle		Parts		GST 8.00%		751.32	
23/1/23 @ 250pm - 4 days		Labour					
Resurvey before part		Sublet		Less		0.00	
fongfkh@lkkauto.com		Lubrication/Fluid		Amount Due		10,142.82	
		Others					

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS	M/S Grab Rentals Pte Ltd				
		Document No. 0	3 Media Close #01-03/06 Singapore 138498				
		Document Date 01/02/2023	Work: 65703925				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	17/04/2017	SLM8839J	0	19697	66OD/SLM8839J/170123
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In	Collected On	
JTDKB3FU203555349		2ZRS034992	6Q	Shashitharan	28/01/2023	8.00	01/02/2023 18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.: SKW4787K ACC DATE:16/01/23 DRIVE IN:25/01/23 EXCESS: DATE-IN:27/01/23 DATE SURVEY:27/01/23 NO OF REPAIR DAYS:4 BY:taufikh AUTHORISED ON:270/1/23	*			50.00	
2	B	BP-LAB2 CHECK WIRING AND CONDUCT LEAK TEST	*			198.00	
3	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL	*			1188.00	
4	B	BP-RES2 RESRPAY ACC AFF AREA				1312.00	
5	1	U52116-47050 SUPPORT, FR BUMPER	1.00	95.70		95.70	
6	2	U53802-47100 FENDER SUB-ASSY, FR	1.00	1177.80		1177.80	
7	3	U53876-47110 LINER, FR FENDER, LH	1.00	243.20		243.20	
8	4	U52119-47962 COVER, FR BUMPER	1.00	622.20		622.20	
9	5	U75374-47150 EMBLEM, SIDE PANEL	1.00	65.60		65.60	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle			4,952.50		
					GST 8.00%		
					396.20		
					Less		
					0.00		
				Amount Due		5,348.70	

Customer Copy